## **COMFORT TRANSPORTATION PTE LTD**

## REPAIR ESTIMATE

Vehicle No.: SH8944G

Make : Toyota

Model : Prius (G4A) Date: 18/06/2021

Insurance: AIG

MVA: MS. LOKE YY

ADEAD SUMMER		Amount
1 REAR BUMPER		\$499.90
10 REAR BUMPER CLIPS		\$22.00
1 REAR BUMPER LOWER COVER		\$552.60
1 REAR BUMPER REINFORCEMENT		\$318.80
1 REAR BUMPER TOWING COVER		\$82.70
SUB TOTAL		\$1,476.00
LESS 25%		\$369.00
DISCOUNTED TOTAL		\$1,107.00
1 REAR REVERSE SENSOR		0405 70
1 REAR BUMPER MAT		\$135.70
		\$45.00 <b>\$180.70</b>
	l	\$100.70
Labour Charge		
PANEL BEATING		\$400.00
SPRAY PAINTING CHARGE		\$300.00
REMOVE/REFIX REVERSE SENSOR		\$60.00
TOTAL LABOUR		\$760.00
ESTIMATE TOTAL		\$2,047.70

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Touthi 9749 Try9

18/6/18/7

18/6/18/7

LKK Auto Consultants hence noting the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey before are subject to confirmation

• Third party survey is on a "Without Prejure"

• No illegal modification(s) is allowed

LKK Auto Consultants hence notify

- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701 Markine + 65 6383 6280 Facsimile + 65 6290 9755 Workshops 205 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717

Date/Time: 18.06.2021 14:18 Page : 1

Team: ARC Repair TP(CLSO)1	OB CARD	Sales Order: 4090370	JC NO.: 305474138
STOMER		REGN NO.: SH 8944G	MILEAGE
MS COMFORT TRANSPORTATION PTE : 7010045	LTD	MAKE: TOYOTA	FUEL
ORESS 383 SIN MING DRIVE Singapore SINGAPORE 575717		MODEL PRIUS HYBRID(G4	DATE/TIME IN 17.06.2021 16:55
(R) 65508755 (O)		YR OF MANU. 02.05.2019	TARGET DATE
COUNT CARD NO.		CHASSIS CODE JTDKB3FU4030801	COMPLETION DATE/TIME: 25
Accident Date: 17.06.2021 NATURE: 3P 17.06.2021	IOB DESCRIPTION		
S/NO LABOR CODE	DESC	RIPTION	HOHT SIDE
ECKED & PASSED OUT BY:			
SERVICE ADVISOR		CUSTOMER'S S	IGNATURE
wledgement Slip	Exit Pass		
: b.: e No.: SH 8944G YY	Vehicle No.:	SH 8944G	
of Service Advisor Signature/Date	Name of Service Adv	isor Date	
returned to Service Reception upon collection	To be kept by Securit	y Guard	