## AFORTDELGRO ENGINEERING PTE LTD

AIR ESTIMATE\*

HICLE NO SHD3719A

DATE: 16.

16. June 2021

AKE HYUNDAI				127.00-02.00.00	
DDEL IONIQ		DOA:	16. Jun. 2021	<u>NTUC</u>	7
Qty Parts Description/ Labour		Туре	Unit Price	Amount	10_
1 REAR BUMPER ASSY				\$459.34	A .
1 REAR BUMPER BEAM				\$394.80	
1 REAR BUMPER BEAM BRACKET LH				\$138.10	1
10 REAR BUMPER MOULDING CENTRE				\$22.00	
1 REAR BUMPER MOULDING CENTRE				\$451.25	
1 REAR FOG LAMP 1 ANTENNA ASSY – SMARTKEY				\$201.50 \$40.50	
1 REAR BUMPER TOW COVER				\$98.80	30
				\$30.00	(** )-
	2332		1426.19		
	SUB TOTAL			\$1,806.29	l
	LESS 20%		1140.95	\$361.25	
	DISCOUNTED TOTAL			\$1,445.04	
			•		
REAR BUMPER MAT	,		logs Le		
REVERSE SENSOR	LKK Auto Consultarit	s hence no		755.55	
ADVERTISEMENT LOGO	the Repairer of the fo	flowing:	11/0.	\$180.00	
	To resurvey before/after     To display damaged part		207	\$50.00	Nett
	Parts prices are subject	to confirmation		6200.00	
	Third party survey is on a     No illegal modification(s)	a "Without Preji	udice basis	\$280.00	
Labour Charge	<ul> <li>Supplementary item(s) n</li> </ul>	nust be resurve	yed <u>and</u>		
PANEL BEATING	is subject to final approve	al from Insuran	ce Company 35	S (400.00	
SPRAY PAINT	Acknowledged by Repare	r I			
CHECK WIRING	Signature: Date:		9	\$500.00	
REMOVE/REFIX REVERSE S	SENSOR	_		\$50.00	
Taylor 12495	) Y 3		`>	O \$80.00	
wp 12/5/	71 e 4pm		٠	9(0.	
1 1 Many	you repair				
+2 dens	TOTAL LABOUR		0207.95	<u> </u>	
Tayth 1749745  WP 176/7/e 4pm  Who non after report  Total LABOUR  Lafter Philandson ESTIMATE TOTAL			2 10 1 ()	\$1,030.00	
faith o Man	ESTIMATE TOTAL		4/59/850		
1 1			ordens It	\$2,755.04	
			2307.95 6/59/850 02days H		
			U		
This					
This is an initial estimate based be prepared after the vehicle is	on a visual inspection of the	above b	J. 71 . 5		
be prepared after the vehicle is	surveyed by a motor Surveyo	r appoint	cie. The final repair qu	antum will	
		- appointed	u by the insurance co	mpany.	