

ASS. REC. BY:

Steve

CS/ 111 2190 6833/ERF3

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

cd

Insured:

Policy No. D19MFL0005549 01

Claims No. MFL2021D0002629


Sum Insured: Excess: 1500

(Client's Record)

Make of Veh:

(Policy Condition)

Remarks: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report Consistent? : Yes or No

SIA / PR Sent Consistent? : Yes or No

Est. Repair: 10 days Res.: Yes or No

Cum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

GRT 80666

Yr Regn:

2018/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace

c.c

2982

Colour:

White

A/C: Insured / Std / Nil / N

Sp. Reading

52690

T/Radio: Insured / Std / Nil / N

Eng/No:

C/No:

JTF11702 PX 90249286

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185 R15C

R:

11

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

15/6/21

D.O.A.

21/6/21

Survey held at

Efficient Mot

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV-71K

22/06/21 @ 2.44pm revert to Gabriel Wee via Merimen.

28/06/21 @ 11.15am Zuhaidah informed C/A &amp; ex: \$1500 via Merimen

28/06/21 @ 2.18pm Informed wksp C/A &amp; ex: \$1500 by email.

13/07/21 @ 9.48am confirmed with wksp L.S. \$6500. 10 days (Red \$8425.40, 56%)

Date/Time, File, Pass to?



: Prel. Report

13/07 Typist



: Final Report

Date/Time, File Return to?

Days Of Repair: 10

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Photos

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Wash and (\$

Approved:

MER-OD

Date/Time, File Return to?

6500

# EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

VEHICLE NO : GBJ8066G

MAKE & MODEL : TOYOTA / HIACE VAN TURBO 5DR MT

CHASSIS NO : JTFHT02PX00249286

DATE : 18 JUN 2021

CLAIM TYPE : OD CLAIM

D.O.A : 15 JUN 2021

TO : INDIA INTERNATIONAL INSURANCE PTE LTD

## ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

| S/No. | QTY | DESCRIPTION                                 | CONDITION /<br>REMARKS | COST PRICE | TOTAL PRICE |
|-------|-----|---------------------------------------------|------------------------|------------|-------------|
| 1     | 1   | FRONT BUMPER / BR                           |                        | \$ 170.00  | \$ 170.00   |
| 2     | 1   | FRONT BUMPER GRILLE / BR                    |                        | \$ 60.00   | \$ 60.00    |
| 3     | 2   | FRONT BUMPER SIDE RETAINER LH/RH / BR       |                        | \$ 55.00   | \$ 110.00   |
| 4     | 2   | FRONT FOG LAMP COVER LH/RH (LH) - MIS       |                        | \$ 40.00   | \$ 80.00    |
| 5     | 1   | FRONT BUMPER REINFORCEMENT / OD             |                        | \$ 90.00   | \$ 90.00    |
| 6     | 1   | FRONT BUMPER CENTER BEAM                    | ?                      | \$ 45.00   | \$ 45.00    |
| 7     | 1   | FRONT GRILLE TOP / MIS                      |                        | \$ 90.00   | \$ 90.00    |
| 8     | 1   | FRONT GRILLE LOWER / MIS                    |                        | \$ 120.00  | \$ 120.00   |
| 9     | 1   | FRONT GRILLE INNER / MIS                    |                        | \$ 170.00  | \$ 170.00   |
| 10    | 2   | HEADLAMP ASSY LH/RH (LH) / BR (LH & RH)     |                        | \$ 280.00  | \$ 560.00   |
| 11    | 2   | HEADLAMP BRACKET LH/RH / APC                |                        | \$ 10.00   | \$ 20.00    |
| 12    | 1   | BONNET / OD                                 |                        | \$ 200.00  | \$ 200.00   |
| 13    | 1   | BONNET LOCK X                               |                        | \$ 36.00   | \$ 36.00    |
| 14    | 2   | BONNET HINGE LH/RH X                        |                        | \$ 22.00   | \$ 44.00    |
| 15    | 2   | CORNER PANEL LH/RH / OD (LH & RH)           |                        | \$ 55.00   | \$ 110.00   |
| 16    | 1   | BRACE PANEL / OD                            |                        | \$ 22.00   | \$ 22.00    |
| 17    | 1   | FRONT SUPPORT PANEL ?                       |                        | \$ 140.00  | \$ 140.00   |
| 18    | 2   | FRONT SUPPORT REINF LOWER LH/RH ?           |                        | \$ 65.00   | \$ 130.00   |
| 19    | 2   | TOWING COVER (LH) (RH) -                    |                        | \$ 12.00   | \$ 24.00    |
| 20    | 1   | AIR CLEANER BOX ?                           |                        | \$ 230.00  | \$ 230.00   |
| 21    | 1   | TOYOTA LOGO / APC                           |                        | \$ 28.00   | \$ 28.00    |
| 22    | 2   | FRONT STEP GARNISH LH/RH (LH) - MIS         |                        | \$ 55.00   | \$ 110.00   |
| 23    | 1   | CENTER PILLAR RH X                          |                        | \$ 220.00  | \$ 220.00   |
| 24    | 2   | FRONT DOOR LH/RH (LH) - OD                  |                        | \$ 550.00  | \$ 1,100.00 |
| 25    | 1   | FRONT DOOR SIDE MIRROR LH/RH (RH) - MIS     |                        | \$ 240.00  | \$ 240.00   |
| 26    | 2   | HARNESS ASSY, WIRING CASING LH/RH (LH) - BR |                        | \$ 35.00   | \$ 70.00    |
| 27    | 1   | WASHER TANK / CRV                           |                        | \$ 50.00   | \$ 50.00    |
| 28    | 1   | RADIATOR SPARE TANK ?                       |                        | \$ 140.00  | \$ 140.00   |
| 29    | 1   | RADIATOR / BR                               |                        | \$ 520.00  | \$ 520.00   |
| 30    | 1   | CONDENSER / OD                              |                        | \$ 450.00  | \$ 450.00   |
| 31    | 1   | A/C DISCHARGE HOSE ?                        |                        | \$ 120.00  | \$ 120.00   |
| 32    | 1   | A/C SUCTION HOSE ?                          |                        | \$ 250.00  | \$ 250.00   |
| 33    | 1   | A/C LIQUID PIPE ?                           |                        | \$ 150.00  | \$ 150.00   |
| 34    | 1   | CONDENSER FAN BLADE / CUT                   |                        | \$ 65.00   | \$ 65.00    |
| 35    | 1   | CONDENSER FAN MOTOR / jammed                |                        | \$ 350.00  | \$ 350.00   |
| 36    | 2   | RADIATOR FAN BLADE / CUT                    |                        | \$ 65.00   | \$ 130.00   |
| 37    | 1   | RADIATOR FAN MOTOR / jammed                 |                        | \$ 350.00  | \$ 350.00   |
| 38    | 1   | INTERCOOLER                                 |                        | \$ 440.00  | \$ 440.00   |
| 39    | 2   | INTERCOOLER AIR GUIDE ?                     |                        | \$ 45.00   | \$ 90.00    |
| 40    | 1   | RADIATOR FAN COWLING / BR                   |                        | \$ 130.00  | \$ 130.00   |
| 41    | 1   | RADIATOR HOSE TOP ?                         |                        | \$ 65.00   | \$ 65.00    |
| 42    | 1   | RADIATOR HOSE LOWER ?                       |                        | \$ 65.00   | \$ 65.00    |
| 43    | 2   | FRONT WHEEL RIM / CUT (LH & RH)             |                        | \$ 150.00  | \$ 300.00   |
| 44    | 2   | FRONT LOWER ARM LH/RH ?                     |                        | \$ 120.00  | \$ 240.00   |
| 45    | 2   | FRONT ABSORBER LH/RH ?                      |                        | \$ 70.00   | \$ 140.00   |
| 46    | 2   | FRONT KNUCKLE ARM LH/RH ?                   |                        | \$ 165.00  | \$ 330.00   |

|   |                                 |   |             |             |
|---|---------------------------------|---|-------------|-------------|
| 2 | FRONT KNUCKLE BEARING/HUB LH/RH | ? | \$ 90.00    | \$ 180.00   |
| 2 | FRONT STABILIZER LINK LH/RH     | ? | \$ 50.00    | \$ 100.00   |
| 2 | FRONT TIE ROD END LH/RH         | ? | \$ 45.00    | \$ 90.00    |
| 1 | FRONT ENGINE CROSSMEMBER        | ? | \$ 900.00   | \$ 900.00   |
|   |                                 |   | \$ 7,885.00 | \$ 9,864.00 |

|                 |              |
|-----------------|--------------|
| TOTAL PRICE     | \$ 9,864.00  |
| PLUS 10%        | \$ 986.40    |
| SUB TOTAL PRICE | \$ 10,850.40 |

| S/No. | QTY | DESCRIPTION                | CONDITION /<br>REMARKS | UNIT S/NETT | TOTAL S/NETT |
|-------|-----|----------------------------|------------------------|-------------|--------------|
| 1     | 1   | FRONT BUMPER CLIPS SET     | APC                    | \$ 50.00    | \$ 30 50.00  |
| 2     | 1   | FRONT GRILLE CLIPS SET     | APC                    | \$ 50.00    | \$ 20 50.00  |
| 3     | 2   | FRONT DOOR CO.REG. STICKER | APC                    | \$ 30.00    | \$ 60.00     |
| 4     | 1   | TOWING FEE                 | APC                    | \$ 70.00    | \$ 60 70.00  |
| 5     | 1   | FRONT NO. PLATE            | MIS                    | \$ 45.00    | \$ 40 45.00  |
| 6     | 1   | RADIATOR COOLANT           | APC                    | \$ 50.00    | \$ 30 50.00  |
| 7     | 2   | TYRES (From LH & RH) TAN   | 80% of 100             | \$ 100.00   | \$ 200.00    |
|       |     | TOTAL S/NETT               |                        | \$ 395.00   | \$ 525.00    |

#### Labour Charges

|   |                                                                                                                                                                   |             |      |
|---|-------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|------|
| 1 | To cut & weld support panel top and bottom, reinf & center pillar, To panel beat other inner panels, chassis member extension, to remove & replace damaged parts. | \$ 1,500.00 | 1000 |
| 2 | To check and rectify lighting & wiring harness & replace reverse sensor                                                                                           | \$ 150.00   | 30   |
| 3 | To Spray painting for Front LH/RH, REAR, & affected areas.                                                                                                        | \$ 1,300.00 | 1000 |
| 4 | To transfer front door lh/rh components to new door.                                                                                                              | \$ 200.00   | 50   |
| 5 | To remove & refit radiator, condenser, other major components, top up A/C gas.                                                                                    | \$ 150.00   | 50   |
| 6 | To remove & install front undercarriage.                                                                                                                          | \$ 150.00   | ?    |
| 7 | To do wheel alignment.                                                                                                                                            | \$ 100.00   | 60   |

#### TOTAL LABOUR

\$ 3,550.00

#### Total Cost of Repairs

\$ 14,925.40

(Total parts + Total S/Nett + Total Labour Cost)

Steve CLKK) OD-MI AL  
21/6/11, 3:30pm EXPIRE-?  
P/P  
By RL sy  
10 dy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: