

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
GST:201006949C RCB NO:201006949C

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE

3 Anson Road

Springleaf Tower #16-00

Singapore 079909

TEL: 63896111

FAX: 6221033

ATTN: Motor Claim Department \ CHINA

Your Ref No: TP 0621-6407

Claim Type: Third Party

Accident Date: 17/06/2021

TP Veh Reg No: GBL 649 S

Estimate No: EST1507042

Date: 12 Jul 2021

Policy No: 7210012131

Veh Reg No: SMS3109Y

Make/Model: HONDA JAZZ 1.3 CVT

Chassis No: JHMGK3850LS212954

Engine No: L13B15000230

Reg. Date: 21/02/2020

Estimate Repair Cost to Vehicle No :SMS3109Y

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair				
Special Net				
1 REAR BOOT GLASS V-KOOL	350.0000	1 SER	350.00	250 S/W
2 IN-CAR CAMERA & LABOUR CHARGE	500.0000	1 SER	500.00	450 S/W
			850.00	850.00
Total				S\$ 850.00
GST Amount				S\$ 59.50
Total Amount Payable				S\$ 909.50

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

SUPP 850.00

PARTS 3280.64

SN 275.00

LABS 2570.00

6995-64