

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____ After-Paint: _____
 Contacts : _____

Vehicle Nos : **SKT 4029 G**
 Model : Mercedes A180
 Year : _____
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Tailgate	1	\$ 1,505.00	\$ 1,505.00
2	Tailgate logo	1	\$ 68.00	\$ 68.00
3	Tailgate emblem 'A180'	1	\$ 68.00	\$ 68.00
4	Tailgate emblem 'Cycle & Carriage'	1	\$ 72.50	\$ 72.50
5	Tailgate inner trim bottom	1	\$ 293.50	\$ 293.50
6	Tailgate weatherstrip	1	\$ 168.00	\$ 168.00
7	Tailgate inner lock assy	1	\$ 274.00	\$ 274.00
8	Tailgate windscreen moulding	1	\$ 241.60	\$ 241.60
9	Rear bumper	1	\$ 1,480.00	\$ 1,480.00
10	Rear bumper side retainer	2	\$ 56.00	\$ 112.00
11	Rear bumper reinforcement	1	\$ 698.00	\$ 698.00
12	Rear bumper reinforcement bracket	2	\$ 159.00 265.00	\$ 318.00 530.00
13	Rear bumper lower cover	1	\$ 336.50	\$ 336.50
14	Rear bumper bracket	3	\$ 65.00 145.00	\$ 195.00 435.00
15	Rear bumper reverse sensor	4	\$ 80.00 265.00	\$ 320.00 1,060.00
16	Rear bumper heat shield	1	\$ 288.00	\$ 288.00
17	Rear bumper tow cap	1	\$ 75.00	\$ 75.00
18	Rear bumper lower beam garnish	1	\$ 113.90	\$ 113.90
19	Rear end panel outer	1	\$ 290.00	\$ 290.00
20	Rear end panel inner	1	\$ 995.00	\$ 995.00
21	Rear end panel top garnish	1	\$ 135.00	\$ 135.00
22	Taillamp	RH 1 2	\$ 736.00 830.00	\$ 736.00 1,660.00
23	Taillamp bracket	2	\$ 84.70	\$ 169.40

Parts Sub Total : \$ 6150.23 11,068.40

10% Discount \$ 615.02 1,106.84

PARTS TOTAL : \$ 9,961.56

@ 10% 5535.21

DDV
 NEC
 NDX
 NECV
 BRV
 NECV
 BTV
 BRV
 NDX
 BRV
 SCV
 BTV
 BRV
 NSX
 DDV
 NDX
 NDX
 CUTV
 NSX

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 80.00	\$ 80.00	NNX
2	Tailgate sealant	1	\$ 100.00	\$ 100.00	NNX
3	Tailgate inner trim clips	1	\$ 60.00	\$ 30.00 60.00	NECV
4	Tailgate windscreen clips	1	\$ 50.00	\$ 50.00	NSX
5	Tailgate windscreen sealant	1	\$ 100.00	\$ 40.00 100.00	NECV
6	Tailgate windscreen inner seal	1	\$ 60.00	\$ 30.00 60.00	NECV
7	Tailgate windscreen primer & cleaner	1	\$ 80.00	\$ 80.00	NNX
8	Rear bumper clips	1	\$ 60.00	\$ 30.00 60.00	NECV
9	Rear bumper lower cover clips	1	\$ 60.00	\$ 30.00 60.00	NECV
10	Rear bumper reverse sensor seal	4	\$ 22.00 60.00	\$ 88.00 240.00	NECV
11	Rear end panel sealant	1	\$ 100.00	\$ 100.00	NNX
12	Rear end panel top garnish clips	1	\$ 60.00	\$ 60.00	NNX
13	Taillamp clips	2	\$ 60.00	\$ 30.00 120.00	NECV
14	Taillamp seal	2	\$ 60.00	\$ 60.00 120.00	NECV
SPECIAL NETT TOTAL :				\$ 1,290.00	

338.00

Nos.	LABOUR	S\$	
1	R&R tailgate component	\$ 80.00 150.00	/
2	R&R tailgate windscreen	\$ 120.00 250.00	/
3	R&R rear bumper reverse sensor	\$ 60.00 100.00	/
4	Check wiring	\$ 30.00 100.00	/
5	Diagnostic reset fault code	\$ 120.00 300.00	/
6	Upholstery	\$ 300.00	NNX
7	Conduct water leakage test	\$ 180.00	NNX
8	Panel beating	\$ 800.00 1400.00	/
9	Rust proofing	\$ 200.00	NNX
10	Spray painting	\$ 600.00 1400.00	/
LABOUR TOTAL :		\$ 4,380.00	

1810.00

Survey 21/6/2021
 Resurvey 22/6/2021
 TGR in 1530 hrs
 TGR in 1400 hrs
 Lump sum repair
 Repair days 5

PARTS TOTAL : \$ 9,961.56
 SPECIAL NETT TOTAL : \$ 1,290.00
 LABOUR TOTAL : \$ 4,380.00
 GRAND TOTAL : \$ 15,631.56

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Parts 5535.21
 SN 338.00
 Labour 1810.00
 @20% 7683.21
 1536.64
 6146.57

COR LS 6150/2
 TGR in 22/7/2021