

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : SJT7819K

TP ALG.

Model:

SUBARU FORESTER

Accident Date : 21/6/2021

Xiao Tong

(29/10/2009)

Location : SLIP ROAD OF BKE (TUAS) ENTERING KJE

3P:

SLJ6090E (AIG)

JFISHSKS59600964

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper <i>Del</i>	713.04	✓	
2	10pcs	Rear bumper clips <i>new</i>		50.00	30
3	2pcs	Rear bumper screw clips <i>new</i>		20.00	+
4	1pc	Rear bumper enforcement <i>Best</i>	475.40	360	
5	2pcs	Rear bumper o/s & n/s reflector <i>new</i>	225.40	112.70	
6	2pcs	Rear bumper o/s & n/s retainer <i>new</i>	126.40	✓	
7	1 set	Rear reverse sensor <i>new</i>		280.00	20
8	1pc	Rear end panel <i>Dented</i>	423.04	✓	
9	1pc	Rear end panel inner trim <i>Del</i>	136.12	✓	
10	4pcs	Rear end panel inner trim clips <i>new</i>		16.00	✓
11	2pcs	Rear o/s & n/s tail lamp retainer <i>new</i>	110.40	x	
12	2pcs	Rear o/s & n/s tail lamp <i>new</i>			
13	1pc	Rear boot cover <i>Dented</i>	1386.64	1192	
14	1pc	Rear boot cover weatherstrip <i>lit</i>	245.44	✓	
15	1pc	Rear boot cover 'FORESTER' emblem <i>new</i>	79.16	✓	
16	1pc	Rear boot cover 'SUBARU' emblem <i>new</i>	73.56	✓	
17	1pc	Rear boot cover 'STI' emblem	79.60	✓	
18	1pc	Rear boot cover inner trim <i>new</i>	333.00	✓	
19	11pcs	Rear boot cover inner trim clips <i>new</i>		33.00	✓
20	1pc	Rear boot cover lock (Upper) <i>new</i>	372.36	200	
21	1pc	Rear boot cover lock (Lower) <i>new</i>	79.10	x	
22	1 pc	Rear windscreen sealant <i>new</i>		60.00	✓
23	1 pc	Rear windscreen moulding <i>new</i>		220.00	85
24	1 pc	Front bumper <i>Del</i>	713.04	✓	
25	10 pcs	Front bumper clips <i>new</i>		30.00	✓
26	1 pc	Front bumper enforcement <i>Dented</i>	445.96	✓	
27	2 pcs	Front bumper o/s & n/s retainer <i>new</i>	121.60	60.60	
28	1 pc	Front support panel <i>new</i>	repair	+	
29	1 pc	Front grille <i>new</i>	751.40	585	

30	1 pc	Front grille emblem <i>x/cc</i>	87.12		
31	6 pcs	Front grille clips <i>x/cc</i>		30.00	
32	1cs	Front o/s head-lamp <i>Can't find</i>	1,440.40 <i>5920</i>		
33	1 pc	Front reg. no. plate <i>Revised</i>		45.00 <i>30</i>	
34	1 pc	Front reg. no. plate bracket <i>Del'd</i>		25.00	
			Sub-Total:	8,418.22	809.00 0.00
				20%	0% 10%
			After Less %:	6,734.58	809.00 0.00
		Labour			
1		To dismantle damaged parts, straighten & welding.		1,400.00 <i>1100-</i>	
2		To spray painting.		1,000.00 <i>900</i>	
3		To remove & replace rear reverse sensor		30.00	
4		To remove and replace rear tail-gate <i> fittings</i>		80.00	
5		To remove & refit rear windscreen.		140.00 <i>120</i>	
6		To check wiring.		100.00 <i>60</i>	
7		To re-seal anti-rust.		100.00 <i>60</i>	
			Sub-Total:	2,850.00	
			Total:	10,393.58	
			After Less 20%:	8,314.86	

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



Adrian G
21/06/21 4/s.

08 Days.

total: 8397.62

1/s: 67K ✓

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: