

⏪	<	1 of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find   Next
---	---	----------	---	---	---	---	------	---	---	-------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

<b>Affiliated to Federation Internationale Des Experts En Automobile</b>				
SMRT AUTOMOTIVE SERVICES PTE LTD			Ref:	CS3/SMR21006848/Vuf3
60 WOODLANDS INDUSTRIAL PARK			Date:	21/06/2021
E4SINGAPORE 757705			Code:	SMR
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	SHF 253K	Veh. Inspected	SMJ 5685J	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/06/21/2033	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	21/06/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	16/06/2021	Inspection Date	21/06/2021	
Survey held at	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				