

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CCG/CT121006850/Urs3

ASSIGNMENT

From:

Date:

Veh No:

Yr Regn:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Yr Regn:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

w/ until 09-08-2025 LMA#13308

have video at folder

2/3/21 L/S #6600 confirmed w. h. Alar.

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS. \$

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I.: (\$

TOTAL

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

* car Jaslin

not Arthur
LKR
n/6/21
L/s \$6600
5 days.

VEHICLE No: SJY 1797C

1PC	REAR DOOR N/S	body ID	1025.10	\$1,248.20
1PC	REAR DOOR OUTER PROTECTOR N/S	sent	66.20	\$266.50
1PC	REAR DOOR OUTER PROTECTOR CHROME N/S	neu	102.50	\$105.30
1PC	REAR DOOR GLASS OUTER MOULDING N/S	rec	128.50	\$148.20
1PC	REAR DOOR GLASS REGULATOR MOTOR N/S	short/1/1m		\$650.50
1PC	REAR DOOR INNER RUBBER N/S	neu	18.40	\$211.20
1PC	REAR DOOR INNER LOCK N/S	n1		\$455.90 X
1PC	REAR DOOR INNER TRIM BOARD N/S	del/cru	645.10	\$861.10
1SET	REAR DOOR INNER TRIM BOARD CLIPS N/S	neu		\$50.00
1SET	REAR DOOR FRAME BLACK STICKER N/S	neu		\$85.00
1PC	ROCKER PANEL N/S	rec/sent	695.10	\$745.50
1PC	ROCKER PANEL GARISH N/S	To n	688.20	\$755.20
1PC	REAR FENDER N/S	sent/Buc	1219.10	\$1,429.20
1PC	REAR FENDER UNDER SHIELD N/S	n1		\$288.90 X
1PC	REAR QUARTER PANEL N/S	NS		\$50.00 X
1PC	REAR WINDSCREEN MOULDING	neu		\$122.10
1PC	REAR BUMPER	deep cut	466.20	\$566.20
1PC	REAR BUMPER SIDE RETAINER N/S	neu		\$66.50
1SET	REAR BUMPER CLIPS	neu		\$50.00
1PC	REAR ABSORBER N/S	sent/1/1m	292.50	\$322.20
1PC	REAR WHEEL HUB BEARING N/S	dyed	485.50	\$655.80
1PC	REAR AXLE BEAM	n1		\$1,781.10 X
1PC	REAR SPORT RIM N/S	cut/sent		\$850.00 400 5/10
1PC	REAR TYRE N/S	neu		\$200.00 X
				\$11,964.60

TO CHECK WIRING	\$50.00 20
TO DISMANTLE & REFIX REAR REVERSE SENSOR	\$80.00 50
TO DISMANTLE & REFIX REAR WINDSCREEN	\$120.00 120
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00 80
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	\$380.00 120
TO CONDUCT WHEEL ALIGNMENT	\$120.00 80
TO SPRAY RUST PROOFING	\$100.00 80
TO TRANSFER REAR DOOR MECHANISM	\$100.00 60
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,500.00 1000
TO PUTTY & SPRAY PAINTING	\$1,800.00 900

TOTAL

16,334.60

LKR Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-7173.50
25%
P-5380.12
S-4400
L-2510
8290.12