



# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmoto@gmail.com Reg. No. 378091/00W

Our Ref: TF3027/06/21

Your Ref:

MR LEE TECK MENG  
1, Fernvale Close,  
#07-04, Lush Acres  
Singapore 797485

*Not Authorized*  
*14/6/21*  
*5 days*

LKK Auto Consultants hence notify  
the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis

\* No illegal modifications is allowed  
\* Supplementary damage must be resurveyed and  
is subject to final approval from Insurance Company

Date: 14th JUNE 2021

Acknowledged by Repairer

Signature:

Date:

*6397.45*  
*Exless ?*

Estimate cost of repair to TOYOTA SIENNA 1.5 (A) Elegance R/B - SLU 7340 W

|                                           |                  |             |
|-------------------------------------------|------------------|-------------|
| 1 pc front o/s fender                     | <i>Bodily DD</i> | \$ 713.20 ✓ |
| 1 pc front o/s fender inner shield        | <i>Dis/turn</i>  | 216.70 ✓    |
| 8 pcs front o/s fender inner shield clips | <i>neu</i>       | 34.40 ✓     |
| 10 pcs front bonnet insulator clips       | <i>11</i>        | 48.00 X     |
| 1 pc o/s head lamp assy                   | <i>Bro</i>       | 3,435.90 ✓  |
| 1 pc o/s head lamp bracket                | <i>11</i>        | 24.00 X     |
| 1 pc front bumper                         | <i>Dis</i>       | 599.60 ✓    |
| 16 pcs front bumper top & low clips       | <i>neu</i>       | 68.80 ✓     |
| 1 pc front bumper reinforcement           | <i>But</i>       | 383.90 ✓    |
| 1 pc front bumper lower rubber            | <i>11</i>        | 193.30 X    |
| 8 pcs front bumper lower rubber clips     | <i>11</i>        | 35.40 X     |
| 1 pc front bumper top rubber              | <i>neu</i>       | 65.90 ✓     |
| 6 pcs front bumper top rubber clips       | <i>neu</i>       | 25.80 X     |
| 1 pc front bumper o/s fog lamp assy       | <i>one</i>       | 458.10 ✓    |
| 1 pc front bumper o/s fog lamp garnish    | <i>Dis</i>       | 108.50 ✓    |
| 1 pc front bumper o/s side retainer       | <i>one</i>       | 73.90 ✓     |
| 1 pc front bumper o/s top retainer        | <i>But</i>       | 54.90 ✓     |
| 1 pc front grille                         | <i>Dis</i>       | 689.60 ✓    |
| 1 pc front grille logo                    | <i>11</i>        | 80.20 X     |
| 1 pc front grille moulding                | <i>11</i>        | 154.20 X    |
| 6 pcs front grille clips                  | <i>11</i>        | 25.80 X     |
| 1 pc washer tank                          | <i>neu</i>       | 141.40 X    |
| 1 pc front o/s top panel                  | <i>neu</i>       | 213.50 X    |
| 1 pc o/s head lamp panel                  | <i>neu</i>       | 150.30 X    |

Less 25%

\$ 7,991.30

\$ 1,997.83

\$ 5,993.47

To wiring check up & adjust headlight alignment. 50.00 *20*

To check & adjust front wheel alignment & balancing. 120.00 *60*

To respray Tuff-Kote on all affected accident parts. *11* 80.00 X

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out necessary parts, to weld, renew & align above parts, to 950.00 *550*

To putty & respray painting on all affected accident parts. 1,450.00 *880*

HUP MOTOR TRADING & SERVICE

\$ 8,643.47

Dollars : Eight Thousand Six Mundred Forty Three And Cents Forty Seven  
Only.

*2-581660*  
*252*  
*4887.45*  
*6397.45*