

ASSIGNMENT

From: ☒ Estimated Cost:

Date:

Veh No:

SLU7340U

Yr Regn:

12/12/17

To Inspect Vehicle No:

SLU7340C

at Workshop m/s

hapnotor

of

Insured:

Policy No. D19MPC0006144-01

Claims No. MPC2021D0002600

Sum Insured:

Excess:

? 600

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$ 69k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

131

%

3 Val.: Yes or No

CA / REV

REP. / 24 HRS

9261

Vehicle: IN / OUT

Date:

Person Contacted:

27 9500

Date / Time

Action / Instruction

No second hand parts LTA 841709

23/6/21 confirmed p/r \$ 6397.45 with David (Red 2249.02, 26%)

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Sienta

c.c

1496

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

76781

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MHF228H3500045163

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/50R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

13/6/21

D.O.I.

14/6/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

1)

Date/Time, File Return to?

2) 2/7/21-Typist

Add Fee:

☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

) S + RS. SI

) Photos

) Others

Report Format : Merimen

Lump Sum / I.B.I: (\$ 6397.45)

TOTAL

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmoto@gmail.com Reg. No. 378091/00W

Our Ref: TF3027/06/21

Your Ref:

MR LEE TECK MENG
1, Fernvale Close,
#07-04, Lush Acres
Singapore 797485

Not Authorized
14/6/21
5 days

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis

* No illegal modifications is allowed
* Supplementary damage must be resurveyed and
is subject to final approval from Insurance Company

Date: 14th JUNE 2021

Acknowledged by Repairer

Signature:

Date:

Estimate cost of repair to TOYOTA SIENNA 1.5 (A) Elegance R/B - SLU 7340 W

1 pc front o/s fender	<i>Bodily DD</i>	\$ 713.20 ✓
1 pc front o/s fender inner shield	<i>Dis/turn</i>	216.70 ✓
8 pcs front o/s fender inner shield clips	<i>neu</i>	34.40 ✓
10 pcs front bonnet insulator clips	<i>11</i>	48.00 X
1 pc o/s head lamp assy	<i>Bro</i>	3,435.90 ✓
1 pc o/s head lamp bracket	<i>11</i>	24.00 X
1 pc front bumper	<i>Dis</i>	599.60 ✓
16 pcs front bumper top & low clips	<i>neu</i>	68.80 ✓
1 pc front bumper reinforcement	<i>But</i>	383.90 ✓
1 pc front bumper lower rubber	<i>11</i>	193.30 X
8 pcs front bumper lower rubber clips	<i>11</i>	35.40 X
1 pc front bumper top rubber	<i>neu</i>	65.90 ✓
6 pcs front bumper top rubber clips	<i>neu</i>	25.80 X
1 pc front bumper o/s fog lamp assy	<i>one</i>	458.10 ✓
1 pc front bumper o/s fog lamp garnish	<i>Dis</i>	108.50 ✓
1 pc front bumper o/s side retainer	<i>one</i>	73.90 ✓
1 pc front bumper o/s top retainer	<i>But</i>	54.90 ✓
1 pc front grille	<i>Dis</i>	689.60 ✓
1 pc front grille logo	<i>11</i>	80.20 X
1 pc front grille moulding	<i>11</i>	154.20 X
6 pcs front grille clips	<i>11</i>	25.80 X
1 pc washer tank	<i>neu</i>	141.40 X
1 pc front o/s top panel	<i>neu</i>	213.50 X
1 pc o/s head lamp panel	<i>neu</i>	150.30 X

Less 25%

\$ 7,991.30

\$ 1,997.83

\$ 5,993.47

To wiring check up & adjust headlight alignment. 50.00 *20*

To check & adjust front wheel alignment & balancing. 120.00 *60*

To respray Tuff-Kote on all affected accident parts. *11* 80.00 X

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out necessary parts, to weld, renew & align above parts, to 950.00 *550*

To putty & respray painting on all affected accident parts. 1,450.00 *880*

HUP MOTOR TRADING & SERVICE

\$ 8,643.47

Dollars : Eight Thousand Six Mundred Forty Three And Cents Forty Seven
Only.

2-581660
252
4887.45
6397.45