

ASS. REC. BY:

LA

lpc

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Motor Image

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$600

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLD 9016H

Yr Regn:

30 Jun 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaru Forester c.c 1995

Colour:

Black

A/C: Insured / Std / NI / NA

Sp Reading

17745

T/Radio: Insured / Std / NI / NA

Eng/No:

JF15J5KC566072517

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/60R17

R:

1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

28-06-21

Survey held at

w/s

11230

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Insp (\$)
☐ : Asst Insp (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Other:

TOTAL



19 Lorong 8 Toa Payoh
Singapore 319255



ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SLD9016H	MODEL : FORESTER 2.0I-L AWD CVT
REF NO: INS/IC/CHI/0123/2021	YEAR: 30-JUN-2016
ENGINE NO: FB20Y292690	CHASSIS NO: JF1SJ5KC5GG072517
DOA: 12/06/2021	TOA: 1640HRS
TYPE OF CLAIM: TP CLAIM	INS COMPANY: LONPAC

S/N	NATURE OF JOB	AMOUNT
1.	REPAIR/REPLACE REAR BUMPER, TAILGATE, BEAM & PANEL 3 (560)	\$3360.00 1680 ✓
2.	RESpray REAR BUMPER, TAILGATE, BEAM & PANEL 4 (420)	\$2520.00 1680 ✓
3.	REMOVE & REFIX EXHAUST X NN	\$150.00 X ✓
4.	TRANSFER TAILGATE MECHANISM	\$150.00 X ✓
5.	WHEEL ALIGNMENT X NN	\$200.00 X ✓
6.	REMOVE & REFIX CARPET, SEATS TO FACILITATE REPAIRS X NN	\$400.00 X ✓
7.	REMOVE & REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	\$150.00 X ✓
8.	FAULT DIAGNOSTIC	\$280.00 235 ✓
9.	TO REMOVE & REFIX FUEL TANK X NN	\$200.00 X ✓
10.	TO CONDUCT REAR LIGHTING TEST	\$50.00 X ✓
11.	TO CONDUCT REAR PROTECTANT COATING	\$500.00 300 ✓
12.	TO CONDUCT REAR ANTI RUST COATING X NN	\$590.00 X ✓
13.	TO SUPPLY & INSTALL REVERSE SENSOR - 2 EYES DM	\$300.00 X ✓
14.	SUNDRIES	\$100.00 20 ✓
Total Labour		\$8950.00

DATE APPROVAL:
TIME APPROVAL:
SURVEY BY:
HP / EMAIL:
BEFORE PAINT:
DAYS GIVEN:

Gue Qian
8288 0282

6

before paint photos.
29/6/2021.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate

Date 06 / 15 / 2021

001 / 002

Name	QUOTATION FOR SLD9016H	Tel (Home)	
Address		Tel (Office)	
E-Mail		Tel (Portable)	
		Fax	
		Model Name	S13
		Body Model	SJ5DK7C
		Vin-Code	JF1SJ5KC5GG072517

Part Number	Part Code Name	Part Code	Q'ty	Price	
63019SG000	GLASS-REAR GATE / <i>McL</i>	FIG-621 63011	1	799.20	✓
63232SG010	RUBBER-REAR GATE / <i>McL</i>	FIG-621 63232	1	12.60	✓
63232SG000	DAM RUBBER-REAR GATE GLASS / <i>McL</i>	FIG-621 63232C	2	7.20	✓
59122SG060	MUD GUARD, REAR RIGHT X	FIG-541 59112	1	57.60	X
59122SG070	MUD GUARD, REAR LEFT X	FIG-541 59112A	1	57.60	X
96072SG020	PLATE-AIR FLAP, RIGHT X	FIG-921 96072	1	7.20	X
96072SG030	PLATE-AIR FLAP, LEFT X	FIG-921 96072A	1	7.20	X
60809SG0109P	PANEL-REAR GATE / <i>Buc</i>	FIG-620 60810	1	1,072.80	✓
63032FG102	LATCH & ACTUATOR-REAR GATE X	FIG-622 63176A	1	144.00	X
63264AG100	STRIKER-REAR GATE X	FIG-622 63264	1	21.60	X
63516SG001	WEATHER STRIP-REAR GATE X NN	FIG-901 63516	1	111.60	X
94026SG000VH	TRIM PANEL-REAR SKIRT X NN	FIG-940 94046	1	36.00	X
57704SG012	BUMPER-FACE, REAR / <i>ee</i>	FIG-591 57704A	1	540.00	✓
57711SG0219P	BACK BEAM COMPLETE-REAR BT photo	FIG-591 57711D	1	288.00	✓
57707SG080	BRACKET-REAR BUMPER SIDE, RIGHT BT	FIG-591 57707H	1	14.40	✓
57707SG090	BRACKET-REAR BUMPER SIDE, LEFT X NN	FIG-591 57707I	1	14.40	
Page-Total				3,191.40	

Memo

Grand Total
4,144.80

--

Tel

Estimate

Date 06 / 15 / 2021

002 / 002

Name	QUOTATION FOR SLD9016H	Tel (Home)	
Address		Tel (Office)	
E-Mail		Tel (Portable)	
		Fax	
		Model Name	S13
		Body Model	SJ5DK7C
		Vin-Code	JF1SJ5KC5GG072517

Part Number	Part Code Name	Part Code	Q'ty	Price	
57707SG060	BRACKET-REAR BUMPER CORNER, RIG HT	FIG-591 57707AC	1	18.00	X
57707SG070	BRACKET-REAR BUMPER CORNER, LEF T	FIG-591 57707AD	1	18.00	X
57731SG010NN	COVER-REAR BUMPER	FIG-591 57731C	1	12.60	✓
44370FG002	TAIL PIPE CUTTER	FIG-440 44371	1	72.00	✓
84281SC000	REFLEX REFLECTOR ASSEMBLY-RIGH T	FIG-842 84281	1	20.40	X
84281SC010	REFLEX REFLECTOR ASSEMBLY-LEFT	FIG-842 84281A	1	20.40	X
84912SG121	LENS & BODY-REAR COMBINATION L AMP RIGHT	FIG-842 84912B	1	432.00	✓
91111SG000	GARNISH ASSEMBLY-REAR GATE, B	FIG-914 91111P	1	144.00	✓
91713SG000	PROTECTOR-REAR GARNISH	FIG-914 91713	1	21.60	✓
91713SG010	PROTECTOR-REAR GARNISH	FIG-914 91713C	2	10.80	✓
93033SG001	ORNAMENT	FIG-914 93033D	1	79.20	✓
93079SG000	LETTER MARK-REAR	FIG-919 93073Y	1	39.60	✓
93079SG030	LETTER MARK-REAR	FIG-919 93073Y	1	64.80	✓
		Page-Total		953.40	
		Sub-Total		4,144.80	
		Total		4,144.80	
		Tax		0.00	
		Grand Total		4,144.80	

Memo

Grand Total
4,144.80

--

3610.8
 -20%: 2888.64
 5010
 7898.64

Tel



SUBARU

Motor Image Enterprises Pte Ltd
19 Lorong 8 Ton Payoh
Singapore 319255
Tel (65) 6703 8101/8102
Fax (65) 6253 5535
WIN WJKTUJF011884 141
Co Reg No 198702032R

Insurance Co: LONPAC

Survey Date: 29/06/2021

SUPPLEMENTARY LABOUR FOR VEHICLE REGISTRATION NO SLD 9016 H

Surveyor: GUO QIANG

LABOUR DESCRIPTION

AMOUNT

1	REMOVE & INSTALL REAR WINDSCREEN ✓	\$ 300.00 ✓
2	TO SUPPLY & INSTALL REAR WINDSCREEN TINTED FILM ✓	NEC \$ 145.00 ✓
3		
4		
5		
6		
7		
8		
9		
10		
11		
12		

Guo Qiang
29/6/2021