

(08/11/13) wef
ASS REC. BY: *Marcus*

REF:

CS/7P21006861/4qf3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: *Jun 6427*
at Workshop m/s *Enofie 11an*
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *Rm 20k*
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: *3* days Res.: Yes or No
Lum Sum: *21* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *Jun 6427* Yr Regn: *29/3/21*
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: *Yamaha MT-25* c.c *250*
Colour: *Blue* A/C: Insured / Std / NI / NA
Sp.Reading: *3292* T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: *PMYRG6510L0001189*
Gen. Cond: *Good* / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Burn / STD A/Rim or
Tyre Size: F: *110/70 R17*
R: *140/70 R17*
BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front *9* Rear *9*
R/Bal. mm R/Bal. mm
L/Bal. mm L/Bal. mm
D.O.A. *3/5/21* D.O.I. *21/6/21*
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
0/5 Body.
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*19/7/21 During survey to owner already replaced R/L tyre never took back.
1/5 \$ 2300 confirmed with me 760 (Red \$7254, 76%)*

Marcus said bill \$300/- exclude GST due to this case wksp claims against public liability & don't know will success to claim it & ask for discount.

Date/Time, File Pass to? ☐ : Preli. Report

21/07 Typist ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: **3**

Resurvey No. of Trip: **1**

Survey Fee:

Transportation:

____ \$ + RS. ____ \$

) Photos

) Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format : **TP**

Lump Sum ~~4121~~ \$ **2300**

TOTAL

300

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Name : Ng Wei Bank

Accident Date : 03-May-21

Vehicle No : JUN6427

Vehicle Model : Yamaha MT25

Estimated Repair Costs

Qty	Description List Items		Amount S(\$)
1	Front fork assy Svc		\$ 1,800.00 X
1	Fork under bracket 17		\$ 480.00 X
1	Front fender Cuv	105	\$ 135.00 ✓
1	Front rim R		\$ 580.00 X
1	Front rim shaft 17		\$ 70.00 X
1	Mirror - R/H Svc	95	\$ 180.00 ✓
1	Front signals - R/H 17		\$ 150.00 X
1	Brake lever Svc	68	\$ 120.00 ✓
1	Handle-bar Svc	150	\$ 280.00 ✓
1	Handle-bar end - R/H Svc	35	\$ 95.00 ✓
1	Front side fairing - R/H Cuv		\$ 220.00 ✓
1	Front fairing inner side cover - R/H Svc		\$ 185.00 X
1	Tank side cover - R/H Cuv		\$ 285.00 ✓
1	Front side lower cover Svc		\$ 185.00 X
1	Front footrest - R/H Daged	70	\$ 105.00 ✓
1	Front footrest bracket - R/H 17		\$ 165.00 X
1	Brake pedal Cuv		\$ 135.00 ✓
1	Rear footrest - R/H Cuv	70	\$ 105.00 ✓
1	Rear footrest bracket - R/H 17		\$ 155.00 X
1	Rear side cover Svc		\$ 165.00 X
1	Exhaust assy Daged	780	\$ 950.00 ✓
1	Exhaust protector Daged	148	\$ 180.00 ✓
1	Radiator cover Daged	80	\$ 165.00 ✓
1	Engine cover 272		\$ 680.00 X
			\$ 7,570.00
		Less 10%	\$ 757.00
			\$ 6,813.00

Not Authorised

Liu

21/6/21

3 days

L / S \$ 2300

When photo taken rep-

2241
10%
P-201690
S-N 598
L 300

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Name : Ng Wei Bank

Accident Date : 03-May-21

Vehicle No : JUN6427

Vehicle Model : Yamaha MT25

Estimated Repair Costs

Special Net Items

1	Nbumber plate (1 set)	for new	\$	38.00	10
2	Fork oils	17	\$	68.00	X
2	Fork oil seals	17	\$	100.00	X
1	Steering cone	17	\$	125.00	X
1	Engine oil	17	\$	120.00	X
1	Engine cover gasket	17	\$	95.00	X
1	Rear box	300	\$	480.00	300
1	Rear box bracket	X	\$	180.00	X
1	Front tyre	Dyed	\$	245.00	144
1	Rear tyre	Dyed	\$	280.00	144
		LP 180			
		LP 180			
		80Z			
		80Z			
			\$	1,731.00	

S/No. Labour

1	To check wiring and reset headlamp focusing	\$	17 80.00	X
2	To repair body frame	\$	17 450.00	X
3	To provide labour	\$	480.00	300
		\$	1,010.00	

Grand Total

\$ 9,554.00

Singapore Dollars: Nine Thousand Five Hundred and Fifty-Four only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: