

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

After-Paint:

Vehicle Nos : **SMK 1719 Z**

Model : Honda City

Year :

Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Bootlid	1	\$ 985.00	\$ 985.00	DDV
2	Bootlid logo	1	\$ 68.70	\$ 68.70	NECV
3	Bootlid emblem " CITY "	1	\$ 62.40	\$ 62.40	
4	Bootlid emblem " I-VTEC "	1	\$ 65.00	\$ 65.00	
5	Bootlid inner lock	1	\$ 185.30	\$ 185.30	JMV
6	Bootlid lock stricker	1	\$ 65.70	\$ 65.70	NDX
7	Bootlid hinge	2	\$ 69.40	\$ 138.80	NDX
8	Bootlid inner trim board	1	\$ 190.60	\$ 190.60	NDX
9	Bootlid weatherstrip	1	\$ 167.90	\$ 167.90	TNV
10	Bootlid chrome moulding	1	\$ 387.20	\$ 387.20	DDV
11	Bootlid lamp	2	\$ 456.80	\$ 913.60	BRV
12	Bootlid number plate lamp	2	\$ 58.00	\$ 116.00	DLV
13	Bootlid solenoid switch	1	\$ 149.20	\$ 149.20	NSX
14	Bootlid reverse camera	1	\$ 620.00	\$ 620.00	SCV
15	Bootlid antenna sensor	1	\$ 308.20	\$ 308.20	BRV
16	Bootlid smart buzzer	1	\$ 188.20	\$ 188.20	NSX
17	Rear bumper	1	\$ 891.00	\$ 891.00	BRX
18	Rear bumper side retainer	2	\$ 79.20	\$ 158.40	NECV
19	Rear bumper bracket	2	\$ 48.90	\$ 97.80	NSX
20	Rear bumper reflector	2	\$ 189.90	\$ 379.80	BRV
21	Rear end panel	1	\$ 353.20	\$ 353.20	DDV
22	Rear end panel top garnish	1	\$ 125.50	\$ 125.50	NDX
23	Rear fender	2	\$ 1,086.60	\$ 2,173.20	CutXR
24	Rear fender inner trim board	2	\$ 168.50	\$ 337.00	NDX
25	Taillamp	2	\$ 564.60	\$ 1,129.20	BRV
26	Taillamp base panel	1	\$ 124.80	\$ 124.80	DDV
Parts Sub Total :				\$ 10,506.50	
20% Discount				\$ 2,101.30	
PARTS TOTAL :				\$ 8,405.20	

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 80.00	\$ 80.00	NNX
2	Bootlid sealant	1	\$ 100.00	\$ 40.00 100.00	NEC
3	Bootlid inner trim board clips	1	\$ 50.00	\$ 50.00	NNX
4	Bootlid chrome moulding clips	1	\$ 50.00	\$ 20.00 50.00	NECV
5	Bootlid lamp clips	2	\$ 50.00	\$ 100.00	NSX
6	Bootlid lamp seal	2	\$ 60.00	\$ 30.00 120.00	NECV
7	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00	NECV
8	Rear end panel sealant	1	\$ 100.00	\$ 40.00 100.00	NECV
9	Rear end panel top garnish clips	1	\$ 50.00	\$ 50.00	NNX
10	Rear fender sealant	2	\$ 100.00	\$ 200.00	NNX
11	Rear fender inner trim board clips	2	\$ 50.00	\$ 100.00	NNX
12	Taillamp clips	2	\$ 50.00	\$ 40.00 100.00	NECV
13	Taillamp seal	2	\$ 60.00	\$ 30.00 120.00	NECV
14	Taillamp base panel sealant	2	\$ 100.00	\$ 200.00	NNX
15	Rear bumper reverse sensor	4	\$ 250.00	\$ 200.00 1,000.00	SLV
16	Rear number plate w/casing	1	\$ 80.00	\$ 50.00 80.00	BTX
SPECIAL NETT TOTAL :				\$ 2,500.00	

Nos.	LABOUR	S\$	
1	R&R bootlid component	\$ 80.00 150.00	—
2	R&R bootlid reverse camera	\$ 20.00 100.00	—
3	R&R rear bumper reverse sensor	\$ 60.00 100.00	—
4	Check wiring	\$ 30.00 100.00	—
5	Upholstery	\$ 300.00	NNX
6	Panel beating	\$ 800.00 1,600.00	—
7	Rust proofing	\$ 200.00	NNX
8	Spray painting	\$ 800.00 1,600.00	—
LABOUR TOTAL :		\$ 4,150.00	

Survey
21/6/2021
Teri in lin
1630 hrs

Resurvey
22/6/2021
Teri in lin
1400 hrs

Lump sum repair
Repair days 5

PARTS TOTAL : \$ 8,405.20
SPECIAL NETT TOTAL : \$ 2,500.00
LABOUR TOTAL : \$ 4,150.00
GRAND TOTAL : \$ 15,055.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: