

TP Budget Direct.

Xiao Chen.

SCH66H 2015 Jan.

Mercedes Benz 8400L 2996CC

WDD2221652A066711

Front Number Plate } 30(SN) X
NH

Front Number Plate Holder } 30(SN) X
NH

Front Bumper Defend 2019. /

Front Bumper Clips. NH 50(SN) /

Front Bumper Side Holder x 02 110 x 2 = 220 X

Front Bumper Reinforcement ? 815 X
NH

Front Bumper Sponge NH 245 X

Front Bumper Lower Grille could 488 /

Front Bumper Sensor x 02 1 piece damaged. 265 x 2 = 530 265. /

Front Grille - Cut 1025 /

Headlamp LH. Cut 5704. /

9501 S.N: 50.

8550.90

SCH66H.

Panel Beating

Spray Painting.

Wiring.

To remove front bumper. Sensor

To perform diagnostic test.

~~600~~ 350

~~400~~ 250

~~100~~ 30

~~120~~ 60

~~200~~ 100

total: 9380.90

L/S: 7.5K.

03Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

~~7500~~

7500