

# SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM\_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

25/06/2021

# 01-43

Singapore 417883

Accident date : 20/06/2021

Estimated repair cost for vehicle no: SLW2200M MITSUBISHI ATTRAGE

CHASSIS: MMBSTA13AJH001426 (2017)

| S/N | Qty | Items                                      | U/price             | Amount                |
|-----|-----|--------------------------------------------|---------------------|-----------------------|
| 1   | 1   | REAR BUMPER <i>Neu</i>                     | \$708.60            | + \$708.60            |
| 2   | 1   | REAR BUMPER SIDE RETAINER RH <i>Neu</i>    | \$98.60             | + \$98.60             |
| 3   | 1   | REAR TAILLAMP RH <i>graded</i> SVC         | \$276.40            | X \$276.40            |
| 4   | 1   | REAR TAILLAMP INNER PANEL RH <i>Neu</i>    | \$228.60            | + \$228.60            |
| 5   | 1   | REAR TAILLAMP LOWER BRACKET RH             | \$65.30             | + \$65.30             |
| 6   | 1   | RH REAR FENDER <i>Distorted</i>            | \$961.40            | ✓ \$961.40            |
| 7   | 1   | RH REAR FENDER INNER PANEL <i>Regis</i>    | \$556.40            | + \$556.40            |
| 8   | 1   | RH REAR FENDER INNER TRIM BAORD <i>Neu</i> | \$334.50            | + \$334.50            |
| 9   | 1   | RH REAR FENDER INNER SHIELD <i>Neu</i>     | \$195.40            | + \$195.40            |
| 10  | 1   | RH REAR DOOR <i>Dented</i>                 | <del>\$831.00</del> | ✓ <del>\$831.00</del> |
| 11  | 1   | RH REAR DOOR INNER TRIM BOARD <i>Neu</i>   | \$298.60            | + \$298.60            |
| 12  | 1   | RH REAR DOOR BLACK STICKER <i>Neu</i>      | \$78.10             | ✓ \$78.10             |
| 13  | 2   | RH REAR DOOR HINGE <i>Neu</i>              | \$55.80             | + \$111.60            |
| 14  | 1   | RH REAR DOOR CHECKER <i>Neu</i>            | \$32.60             | + \$32.60             |
| 15  | 1   | RH REAR DOOR LOCK <i>Neu</i>               | \$186.40            | + \$186.40            |
| 16  | 1   | RH REAR DOOR OUTER HANDLER <i>Neu</i>      | \$148.60            | + \$148.60            |
| 17  | 1   | RH FRONT DOOR <i>Regis</i>                 | \$518.30            | + \$518.30            |
| 18  | 1   | RH FRONT DOOR BLACK STICKER <i>Neu</i>     | \$78.10             | + \$78.10             |
| 19  | 1   | REAR WINDSCREEN GLASS MOULDING <i>Neu</i>  | \$195.40            | ✓ \$195.40            |

TOTAL : *105* \$5,611.80

LESS 10 % \$561.18

SUB-TOTAL : \$5,050.62

5313.51

2251.90

2026.81

| S/N | Qty | ITEMS / SPECIAL NETT                     | U/price  | Amount                        |
|-----|-----|------------------------------------------|----------|-------------------------------|
| 1   | 1   | REAR WINDSCREEN GLASS SEALANT <i>new</i> | \$120.00 | <i>60</i> <del>\$120.00</del> |
| 2   | 1   | REAR BUMPER CLIPS <i>new</i>             | \$80.00  | <i>+</i> <del>\$80.00</del>   |
| 3   | 1   | REAR TAILLAMP CLIPS <i>new</i>           | \$5.60   | <i>2</i> <del>\$5.60</del>    |

*60*

TOTAL: \$205.60

TOTAL PARTS : \$5,256.22

### Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS
- 5 LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS
- 6 LABOUR FOR REMOVE & TRANSFER BOTH LH DOORS FITTING
- 7 LABOUR FOR REMOVE & REFIX LH UPHOLSTERY/ ROOF LINING

*600* ~~\$1,800.00~~  
*600* ~~\$1,200.00~~  
*30* ~~\$80.00~~  
*60* ~~\$300.00~~  
*120* ~~\$150.00~~  
*80* ~~\$300.00~~  
*60* ~~\$300.00~~

*1550*

Subtotal :- \$4,130.00

**9649.11** Total:- \$9,386.22

*L/s 07/07/21*

*05 Days*

*total: 3636.71*

*L/s 2.7K 2.7K*

*(2.7K)*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: