

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

25/06/2021

01-43

Singapore 417883

Accident date : 20/06/2021

Estimated repair cost for vehicle no: SLW2200M MITSUBISHI ATTRAGE

CHASSIS: MMBSTA13AJH001426 (2017)

S/N	Qty	Items	U/price	Amount
1	1	REAR BUMPER <i>Neu</i>	\$708.60	<i>+</i> \$708.60
2	1	REAR BUMPER SIDE RETAINER RH <i>Neu</i>	\$98.60	<i>+</i> \$98.60
3	1	REAR TAILLAMP RH Coated SVC	\$276.40	<i>X</i> \$276.40
4	1	REAR TAILLAMP INNER PANEL RH <i>3 Neu</i>	\$228.60	<i>+</i> \$228.60
5	1	REAR TAILLAMP LOWER BRACKET RH	\$65.30	<i>+</i> \$65.30
6	1	RH REAR FENDER <i>Distorted</i>	\$961.40	<i>✓</i> \$961.40
7	1	RH REAR FENDER INNER PANEL <i>Reps</i>	\$556.40	<i>+</i> \$556.40
8	1	RH REAR FENDER INNER TRIM BAORD <i>Not Neu</i>	\$334.50	<i>+</i> \$334.50
9	1	RH REAR FENDER INNER SHIELD <i>Not Neu</i>	\$195.40	<i>+</i> \$195.40
10	1	RH REAR DOOR <i>Dented</i>	\$538.90	<i>✓</i> \$538.90 <i>\$831.00</i>
11	1	RH REAR DOOR INNER TRIM BOARD <i>Not Neu</i>	\$298.60	<i>+</i> \$298.60
12	1	RH REAR DOOR BLACK STICKER <i>Neu</i>	\$78.10	<i>✓</i> \$78.10
13	2	RH REAR DOOR HINGE <i>Neu</i>	\$55.80	<i>+</i> \$111.60
14	1	RH REAR DOOR CHECKER <i>Neu</i>	\$32.60	<i>+</i> \$32.60
15	1	RH REAR DOOR LOCK <i>Not Neu</i>	\$186.40	<i>+</i> \$186.40
16	1	RH REAR DOOR OUTER HANDLER <i>Neu</i>	\$148.60	<i>+</i> \$148.60
17	1	RH FRONT DOOR <i>Reps</i>	\$518.30	<i>+</i> \$518.30
18	1	RH FRONT DOOR BLACK STICKER <i>Neu</i>	\$78.10	<i>+</i> \$78.10
19	1	REAR WINDSCREEN GLASS MOULDING <i>Neu</i>	\$195.40	<i>✓</i> \$195.40

TOTAL : *105* \$5,611.80

LESS 10 % \$561.18

SUB-TOTAL : \$5,050.62

5313.51

2251.90

2026.81

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR WINDSCREEN GLASS SEALANT <i>new</i>	\$120.00	<i>60</i> \$120.00
2	1	REAR BUMPER CLIPS <i>new</i>	\$80.00	<i>+</i> \$80.00
3	1	REAR TAILLAMP CLIPS <i>new</i>	\$5.60	<i>2</i> \$5.60

60

TOTAL: \$205.60

TOTAL PARTS : \$5,256.22

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS
- 5 LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS
- 6 LABOUR FOR REMOVE & TRANSFER BOTH LH DOORS FITTING
- 7 LABOUR FOR REMOVE & REFIX LH UPHOLSTERY/ ROOF LINING

600 ~~\$1,800.00~~
600 ~~\$1,200.00~~
30 ~~\$80.00~~
60 ~~\$300.00~~
120 ~~\$150.00~~
80 ~~\$300.00~~
60 ~~\$300.00~~

Subtotal :- \$4,130.00

9649.11 Total:- \$9,386.22

h/s 07/07/21

05 Days

total: 3636.71

h/s 2.7K 2.7K

(2.9K)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: