

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006875/UPA3Q2**Date:** 06/02/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700012711
Claimant Vehicle No :	SMC3179D	Insured Vehicle No :	SKP63D
Date of Loss:	18/06/2021	Nature of Claim:	TP
		Claim No:	7164787677SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC3179D	Engine No:	2ZR8438259
Make & Model:	TOYOTA C-HR HYBRID, 1.8 S CVT (A)	Chassis No:	ZYX102120204
Reg. Date:	28/06/2018 (Man. Year: 2018)	Odometer:	143637 km
Colour:	Grey		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,644.00	3,641.50	5,002.50	57.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	1,370.00	1,090.00	44.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,104.00	5,011.50	6,092.50	54.87
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	11,104.00	4,000.00	7,104.00	63.98
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	21/06/2021	Profi Automotive (KB)
Date Inspected:	23/06/2021 Inspected At:	10 KAKI BUKIT ROAD 2, #01-05 FIRST EAST CENTRE
Estimated Period of Repair:	4.0 days	Singapore 417868

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deep Cut / Deformed	1,150.00 FL	*1,150.00 FL
2	2		*FRONT BUMPER RETAINER	Not Necessary	38.00 FL	*- FL
3	2		*FRONT BUMPER BRACKET	Not Necessary	72.00 FL	*- FL
4	1		*FRONT BUMPER LOWER GARNISH	Grazed	219.00 FL	*219.00 FL
5	1		*FRONT HEADLAMP O/S	Scratched	2,581.00 FL	*1,380.50 FL
6	1		*FRONT BONNET	Repair	1,156.00 FL	*- FL
7	1		*FRONT BONNET HINGE O/S	Not Necessary	96.00 FL	*- FL
8	1		*FRONT FENDER O/S	Badly Dented	918.00 FL	*845.00 FL
9	1		*FRONT FENDER INNER SHIELD O/S	Torn	155.00 FL	*155.00 FL
10	1		*FRONT FENDER OUTER GARNISH O/S	Distorted	302.00 FL	*147.50 FL
11	1		*FRONT KNUCKLE ARM O/S	Not Necessary	660.00 FL	*- FL
12	1		*FRONT KNUCKLE ARM BEARING O/S	Damaged	395.00 FL	*265.00 FL
13	1		*FRONT SHOCK ABSORBER O/S	Not Necessary	791.00 FL	*- FL
14	1		*FRONT LOWER ARM O/S	Not Necessary	419.00 FL	*- FL
15	1		*SET FRONT BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
16	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	30.00 FS	*30.00 FS
17	1		*RIM	Cut / Bent	1,200.00 FS	*450.00 FS
18	1		*TYRE	Serviceable	600.00 FS	*- FS
19	1		*BOT BRAKE FUILD	Not Necessary	60.00 FS	*- FS
					Sub Total (\$\$)	10,882.00 4,682.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	2,238.00 1,040.50
					Total Parts (\$\$)	8,644.00 3,641.50

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK FRONT WIRING AND LIGHTING SYSTEM	New	80.00	20.00
2	COMPUTERISED FRONT WHEEL ALIGNMENT	New	180.00	80.00
3	REMOVE AND RENEW FRONT UNDERCARRIAGE PARTS	New	250.00	120.00
4	PANEL BEATING AND RENEW DAMAGE PARTS ON AFFECTED AREAS	New	800.00	520.00
5	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	600.00
6	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	30.00
Gross Labour Cost (\$\$)			2,460.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >