

6876 (Ae)

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: CHINA	DATE	: 16/06/2021
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SMY9533J	Asher.	
MODEL	: TOYOTA HARRIER		
CHASSIS NO		MX4A800019504	
<u>ACCIDENT DETAILS</u>		DATE	: 14/06/2021
		TIME	: 16:30HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER(TOP) <i>Delud</i>	1	\$ 1,855.60	\$ 1,855.60
2	REAR BUMPER(LOW) <i>Delud</i>	1	\$ 655.30	\$ 655.30
3	REAR BUMPER SIDE RETAINER <i>Me y</i>	2	\$ 62.40	\$ 124.80
4	REAR BUMPER CENTRE CHROME <i>could</i>	1	\$ 455.60	\$ 455.60
5	REAR BUMPER REINFORCEMENT BAR <i>me</i>	1	\$ 580.60	\$ 580.60
6	REAR BUMPER SPONGE <i>could</i>	1	\$ 211.60	\$ 211.60
7	REAR BUMPER PARKING SENSOR <i>me</i>	1	\$ 280.20	\$ 280.20
8	TAILLAMP LAMP RH <i>at</i>	1	\$ 510.50	\$ 510.50
9	TAILLAMP LAMP LOWER BRACKET RH <i>could</i>	1	\$ 110.00	\$ 110.00
10	END PANEL <i>Rego Dented</i>	1	\$ 655.50	\$ 655.50
11	REAR FENDER LH <i>Rego Rys</i>	1	\$ 1,455.90	\$ 1,455.90

TOTAL PRICE \$ 6,895.60

LESS 25% \$ 1,723.90

SUB TOTAL PRICE \$ 5,171.70

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
-----	-------------	-----	-------------	--------------

1	REAR BUMPER CLIP(SET) <i>Nu</i>	1	\$ 30.00	\$ 30.00	✓
---	---------------------------------	---	----------	----------	---

30

TOTAL \$ 30.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	<i>600</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	<i>600</i>	
3	TUFF COAT	\$ 180.00	<i>60</i>	
4	WIRING CHECK	\$ 120.00	<i>30</i>	
5	REMOVE AND REFIX REAR REVERSE SENSOR	\$ 100.00	<i>50</i>	

1340

TOTAL \$3,200.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,201.70
TOTAL LABOUR COST : \$ 3,200.00
TOTAL REPAIR COST : \$ 8,401.70

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

PART BY PART / LUMP SUM :
NO OF DAYS :

FAX :

Adrian L
4/5 17/06/21.

05 days.

total: 334070
h/s: 3.1K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: