

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21006882/AGS3Q2
Date: 31/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900236823
Claimant Vehicle No :	SKS7273C	Insured Vehicle No :	SKN182D
Date of Loss:	18/06/2021	Nature of Claim:	TP
		Claim No:	2794763635SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS7273C		
Make & Model:	AUDI A3, 1.4 TFSI S-TRONIC (A)	Engine No:	CZC244190
Reg. Date:	30/04/2015 (Man. Year: 2015)	Chassis No:	WAUZZZ8V6F1115526
Colour:	Bronze	Odometer:	104360 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,729.00	2,670.56	10,058.44	79.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,682.00	2,872.00	3,810.00	57.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,411.00	5,542.56	13,868.44	71.45
+ GST 7.00/7.00% (S\$)	1,358.77	387.98	970.79	71.45

Nett Amount (S\$)	20,769.77	5,930.54	14,839.23	71.45
		+ Car Rental (5.0 x S\$100.00/day) (S\$)	500.00	
		+ Doc/Search Fee (S\$)	2.00	
		Nett Liability (S\$)	6,432.54	

INSPECTION

Date of Assignment: 22/06/2021

Date Inspected: 22/06/2021

Estimated Period of Repair: 5.0 days

Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	2,070.00 FS	*1,656.00 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	193.00 FS	*- FS
3	2		*REAR BUMPER GUIDE SECTION LH/RH	Not Necessary	32.00 FS	*- FS
4	2		*GUIDE SECTION LOCKING MECHANISM LH/RH	Not Necessary	59.00 FS	*- FS
5	1		*REAR BUMPER SPOILER	Cut	237.00 FS	*189.60 FS
6	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	82.00 FS	*- FS
7	2		*REAR LID LED TAILLIGHT LH/RH	Not Necessary	1,754.00 FS	*- FS
8	2		*REAR LID LED TAILLIGHT TRIM LH/RH	Not Necessary	60.00 FS	*- FS
9	2		*LED LICENCE PLATE LIGHT	Not Necessary	115.00 FS	*- FS
10	1		*REAR BUMPER REINFORCEMENT BEAM	Dented	603.00 FS	*482.00 FS
11	2		*REAR BUMPER BRACKET RH/LH	Not Necessary	26.00 FS	*- FS
12	2		*REAR BUMPER LOWER GUIDE SECTION LH/RH	Not Necessary	126.00 FS	*- FS
13	1		*REAR PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
14	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
15	1		*SET REAR BUMPER WIRING	Not Necessary	515.00 FS	*- FS
16	1		*REAR LID	Repair	3,404.00 FS	*- FS
17	1		*REAR LID ATTACHMENT PARTS	Not Necessary	295.00 FS	*- FS
18	2		*REAR LID HINGE LH/RH	Not Necessary	512.00 FS	*- FS
19	1		*REAR LID GASKET FLAP	Not Necessary	205.00 FS	*- FS
20	1		*REAR LID STRIKER	Not Necessary	205.00 FS	*- FS
21	1		*REAR LID LOCK	Not Necessary	189.00 FS	*- FS
22	1		*REAR LID LOCK COVER	Not Necessary	8.00 FS	*- FS
23	1		*REAR LID PUSH BUTTON ACTUATOR	Not Necessary	177.00 FS	*- FS
24	1		*REAR LID PUSH BUTTON ACTUATOR COVER	Not Necessary	16.00 FS	*- FS
25	1		*REAR LID PACKING ADHESIVE	Necessary	19.00 FS	*14.88 FS
26	1		*AUDI EMBLEM	Necessary	138.00 FS	*110.00 FS
27	1		*A3 EMBLEM	Necessary	99.00 FS	*79.04 FS
28	1		*TFSI EMBLEM	Necessary	99.00 FS	*79.04 FS
29	1		*REAR CROSS PANEL TRIM	Not Necessary	155.00 FS	*- FS
30	1		*REAR SILENCER	Not Necessary	720.00 FS	*- FS
31	2		*REAR SILENCER RETAINER	Not Necessary	83.00 FS	*- FS
32	1		*REAR SILENCER DUAL CLIP	Not Necessary	59.00 FS	*- FS
33	1		*REAR NO PLATE	Dented	60.00 FS	*60.00 FS
34	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					12,729.00	2,670.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND INSTALL REAR PARKING AID REAR LID KICK SENSOR	New	280.00	280.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	0.00
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID TO REPAIR REAR END PANELLING .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	2,450.00	750.00
4	TO RESPRAY REAR BUMPER REAR LID ,HINGES AND REAR END PANELLING	New	3,000.00	1,650.00
5	TO RENEW LHS REAR EXHAUST SILENCER AND ALIGN TO POSITION	New	480.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			6,682.00	2,872.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >