

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0511/2021/KS
DATE : 22-Jun-21
WIP : 32044

Ceilia

~~\$2307.60.~~

\$5542.56

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/06/2021

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : M/S YAN SAN METALS PTE LTD
ADDRESS : 17 TUAS AVENUE A
SINGAPORE 639368
TELEPHONE : HP +65 96374542
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO :
VEHICLE NO : SKS 7273 C
MODEL CODE : A3 SEDAN 1.4 TFSI S TRONIC
MODEL YEAR : 30/4/2015
ENGINE NO : CZC 244910
CHASSIS NO : WAUZZZ8V6F1115526
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Jun-21
PLACE OF ACCIDENT : TUAS ROUNDABOUT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 2069 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND INSTALL REAR PARKING AID AND REAR LID KICK SENSOR	\$ 280.00	✓
2	TO REMOVE ANDS TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS/	S/N \$ 280.00	X NN
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,450.00	500 750 888.
4	TO RESPRAY REAR BUMPER, REAR LID, HINGES AND REAR END PANELLING.	\$ 3,000.00	1100 1650 888.
5	TO RENEW LHS REAR EXHAUST SILENCER AND ALIGN TO POSITION.	S/N \$ 480.00	X NN
6	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 6,682.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKS 7273 C

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER <i>Distorted</i>	1	\$ 2,070.00	✓	1656.00
2	REAR BUMPER FIXING PARTS <i>new</i>	1	\$ 193.00	✓	
3	REAR BUMPER GUIDE SECTION LH / RH <i>new</i>	2	\$ 32.00	✓	
4	GUIDE SECTION LOCKING MECHANISM LH / RH <i>new</i>	2	\$ 59.00	✓	
5	REAR BUMPER SPOILER <i>cut</i>	1	\$ 237.00	✓	189.60
6	REAR BUMPER REFLECTOR LH / RH <i>new</i>	2	\$ 82.00	✗	
7	REAR LID LED TAILLIGHT LH / RH <i>new</i>	2	\$ 1,754.00	✗	
8	REAR LID LED TAILLIGHT TRIM LH / RH <i>new</i>	2	\$ 60.00	✗	
9	LED LICENCE PLATE LIGHT <i>new</i>	2	\$ 115.00	✓	
10	REAR BUMPER REINFORCEMENT BEAM <i>Dented.</i>	1	\$ 603.00	✓	482.00
11	REAR BUMPER BRACKET LH / RH <i>new</i>	2	\$ 26.00	✗	
12	REAR BUMPER LOWER GUIDE SECTION LH / RH <i>new</i>	2	\$ 126.00	✗	
13	REAR PARKING AID SENSOR <i>new</i>	1	TBC	✗	
14	REAR PARKING AID SENSOR SEAL RING <i>new</i>	4	\$ 14.00	✗	
15	REAR BUMPER WIRING SET <i>new</i>	1	\$ 515.00	✗	
16	REAR LID <i>Repair</i>	1	\$ 3,404.00	✗	
17	REAR LID ATTACHMENT PARTS <i>new</i>	1	\$ 295.00	✗	
18	REAR LID HINGE LH / RH <i>new</i>	2	\$ 512.00	✗	
19	REAR LID GASKET FLAP <i>new</i>	1	\$ 205.00	✗	
20	REAR LID STRIKER <i>new</i>	1	\$ 205.00	✗	
SUBTOTAL SPARE PARTS			\$ 10,507.00		

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKS 7273 C

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	REAR LID LOCK <i>green</i>	1	\$ 189.00	X	
22	REAR LID LOCK COVER <i>green</i>	1	\$ 8.00	X	
23	REAR LID PUSH BUTTON ACTUATOR <i>green</i>	1	\$ 177.00	X	
24	REAR LID PUSH BUTTON ACTUATOR COVER <i>green</i>	1	\$ 16.00	X	
25	REAR LID PACKING ADHESIVE <i>an</i>	1	\$ 19.00	✓	14.88
26	"AUDI" EMBLEM <i>green</i>	1	\$ 138.00	✓	110.00
27	"A3" EMBLEM <i>green</i>	1	\$ 99.00	✓	79.04
28	"TFSI" EMBLEM <i>green</i>	1	\$ 99.00	✓	79.04
29	REAR CROSS PANEL TRIM <i>new</i>	1	\$ 155.00	X	
30	REAR SILENCER <i>green</i>	1	\$ 720.00	X	
31	REAR SILENCER RETAINER <i>green</i>	2	\$ 83.00	X	
32	REAR SILENCER DUAL CLIP <i>green</i>	1	\$ 59.00	X	
33	REAR NO PLATE <i>Dented</i>	S/N	\$ 60.00	✓	
34	SUNDRIES <i>Not ne</i>		\$ 400.00	X	
TOTAL SPARE PARTS		:	\$ 12,729.00		
TOTAL LABOUR CHARGES		:	\$ 6,682.00		
GRAND TOTAL		:	\$ 19,411.00		

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE : *22/06/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days.* *05 Days.*
SL.S.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT