



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2106300

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 09/09/2021
Reference CS3/III21006883/Bqf3e2
Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. SLX 1435D
Insured Veh. GBK 5141L
Claim No. MFL2021D0002614
Policy No. D19MFL0005549_01
Accident Date 18/06/2021
Inspection Date 22/06/2021

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 22.06.2021 02.37pm	
- Dismantle Inspection 23.06.2021 12.14pm	
Merimen Fee	11.00
Subtotal	131.00
GST (7%)	9.17
Grand Total	140.17

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM