



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
FOO MEI LIN ROSELINE MRS.KONG MEI LIN ROSELINE 8 ELLIOT WALK  SINGAPORE 458663  Contact No	Cust No/Name KCV12020/FOO MEI LIN ROSELINE MRS.KONG M Reg No/Reg Date SMP240K*DC17P/ 06/09/201 Date In/Mileage / 0 Chassis No MMBSTA13AKH002668 Engine No 3A92UHX8994 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KCV12020	CRDVCH	21/06/2021/ 17:35	BLC	442 / CocoLu	12306

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW BONNET, FRT BUMPER, FRT FENDER RH, FRT SUPPORT PANEL 4 x 457				1800.00 ✓
REPAIR FRT DOOR RH,				1750.00 ✓
E PNT98000 SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH, FRT DOOR RH 5 x 350				100.00 X
FRT SUPPORT PANEL 1				50.00 ✓
E PNT88000 REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR (photo)				30.00 ✓
M SUNDRY FRT NUMBER PLATE WITH FRAME - BR				120.00 ✓
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				40.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				20.00 ✓
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION				80.00 X
M SUNDRY Sundry				
A 54900099 CHASSIS ELECTRICAL FREE TEXT (Top up A/c gas) (photo)				
M FACE,FR BUMPER - BR	1.00	706.00	00.00	706.00
M COVER,HEADLAMP SUPT PANEL - CUT	1.00	62.00	00.00	62.00
M BRACKET,FR BUMPER,RH - BR	1.00	13.00	00.00	13.00
M GARNISH,FR BUMPER,RH - CRU	1.00	127.00	00.00	127.00
M AIR DAM,SIDE,FR RH - BR	1.00	18.00	00.00	18.00
M MARK,THREE-DIA - APC	1.00	70.00	00.00	70.00
M GRILLE,RADIATOR - CUT	1.00	557.00	00.00	557.00
M GRILLE,FR UNDER - BR	1.00	165.00	00.00	165.00
M COVER,FR BUMPER - CRU	1.00	12.00	00.00	12.00
M HOOD - D/H	1.00	737.00	00.00	737.00
M HINGE,HOOD,LH - xnn	1.00	56.00	00.00	56.00
M HINGE,HOOD,RH - xnn	1.00	56.00	00.00	56.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
FOO MEI LIN ROSELINE MRS.KONG MEI LIN ROSELINE 8 ELLIOT WALK  SINGAPORE 458663  Contact No	Cust No/Name KCV12020/FOO MEI LIN ROSELINE MRS.KONG M Reg No/Reg Date SMP240K*DC17P/ 06/09/201 Date In/Mileage / 0 Chassis No MMBSTA13AKH002668 Engine No 3A92UHX8994 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KCV12020	CRDVCH	21/06/2021/ 17:35	BLC	442 / CocoLu	12306			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	LATCH, HOOD	X nn			1.00	69.00	00.00	69.00
M	FENDER, FR RH	00	?	X nn	1.00	500.00	00.00	500.00
M	SHIELD, FR WHEELHOUSE, RH				1.00	98.00	00.00	98.00
M	PANEL ASSY, FR END	00	?	X nn	1.00	1055.00	00.00	1055.00
M	PANEL, HEADLAMP SUPPORT, UPR				1.00	66.00	00.00	66.00
M	GARNISH, FR FENDER	BR			1.00	65.00	00.00	65.00
M	GARNISH, FR PILLAR, RH	BR			1.00	30.00	00.00	30.00
M	HEADLAMP ASSY, RH	BR			1.00	663.00	00.00	663.00
M	HEADLAMP ASSY, LH	?	X nn		1.00	663.00	00.00	663.00
M	LAMP ASSY, FOG, FR LH	?	X nn		1.00	305.00	00.00	305.00
M	MOTOR, WINDSHIELD WASHER	?	X nn		1.00	30.00	00.00	30.00
M	TANK, WINDSHIELD WASHER	?	X nn		1.00	75.00	00.00	75.00
M	CONDENSER ASSY, A/C REFRIGE	?	X nn		1.00	762.00	00.00	762.00
M	HOSE, A/C COMPR SUCTION	?	X nn		1.00	231.00	00.00	231.00
M	PIPE, A/C CONDENSER OUTLET	?	X nn		1.00	305.00	00.00	305.00
M	PANEL, AIR GUIDE	BR			1.00	112.00	00.00	112.00
M	RADIATOR ASSY	X nn			1.00	972.00	00.00	972.00

*Estimate*

Sterk (CLKK) 00- Nm AL  
 22/6/21, 12.9pm EXPRS -?  
 P/P  
 My Bel sy  
 8 d/s

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Confirm & accepted by

- Third party survey is on a "Without prejudice" basis
- Any modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:

Authorized signatory and company stamp

**Nett 12,570.00**  
**7% GST on 12570.00 879.90**  
**Total Payable 13,449.90**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.