



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 632E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT LH FENDER	BENT	945.00	945.00
1	FRONT LH RIM	SERVICEABLE	2,398.00	-
1	FRONT LH DOOR	TO REPAIR SEE LABOUR	1,538.00	-
1	FRONT LH DOOR PROTECTOR WITH CHROME MOULDING	CUT	365.00	365.00
1	REAR LH DOOR	TO REPAIR SEE LABOUR	1,484.00	-
1	REAR LH DOOR PROTECTOR WITH CHROME MOULDING	CUT	257.00	257.00
1	LH DOOR SIDE SKIRT	SERVICEABLE	648.00	-
1	REAR LH FENDER	TO REPAIR SEE LABOUR	1,349.00	-
1	REAR LH RIM	DENTED	2,398.00	1,201.00
1	REAR BUMPER	TO REPAIR SEE LABOUR	783.00	-
	LESS 10% DISCOUNT		-1,216.50	-276.80
			10,948.50	2,491.20
	<u>LABOUR</u>			
	REMOVE & REFIT FRONT LH FENDER,LH DOOR SIDE SKIRT.	NOT NECESSARY	300.00	-
	REMOVE AND REFIT FRONT LH WHEEL,REAR LH WHEEL.BALANCING FRONT LH WHEEL,BALANCING REAR LH WHEEL.		100.00	20.00
	REMOVE AND TRANSFER FRONT LH DOOR NECESSARY ATTACHMENT SPARE PART ITEMS.REMOVE AND REFIT FRONT LH DOOR,FRONT LH DOOR PROTECTOR.	NOT NECESSARY	300.00	-
	REMOVE AND TRANSFER REAR LH DOOR NECESSARY ATTACHMENT SPARE PART ITEMS.REMOVE AND REFIT REAR LH DOOR,REAR LH DOOR PROTECTOR.	NOT NECESSARY	600.00	-
	REMOVE AND TRANSFER REAR BUMPER NECESSARY ATTACHMENT SPARE PART ITEMS.REMOVE AND REFIT REAR BUMPER.	NOT NECESSARY	200.00	-
	UNDER COATING ON LH DAMAGED PORTION.	NOT NECESSARY	150.00	-
	PUTTY/PRIMER APPLICATION,SPRAY PAINTING FRONT LH FENDER,FRONT LH DOOR,REAR LH DOOR,REAR LH FENDER,REAR BUMPER (PEARL WHITE).		700.00	600.00

Report Ref No. CS/AGI21006886/Ktf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	HEAT/WELD/CUT/RENEW REAR LH FENDER,HEAT/WELD/BEATING/PULL/STRAIGHTEN/ALIGN REAR CHASSIS FRAME BY CHASSIS ALIGNMENT JACK.INCLUSIVE OF THE REPAIR OF FRONT LH DOOR,REAR LH DOOR,REAR LH FENDER AND REAR BUMPER.		500.00	400.00
			2,850.00	1,020.00
GRAND TOTAL			13,798.50	3,511.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,800.00

Report Ref No. CS/AGI21006886/Ktf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.