



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21006887/R1uf3n2	
			Date: 17/11/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 5685K	Veh. Inspected	SLX 9612G
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/06/21/2040	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	22/06/2021
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 2 SEDAN 1.5 AT	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	MM6DL2SAAJW374691	Colour	BLUE
	Odometer	40312 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/65 R15	DUNLOP	5 mm
	L/H Front Tyre	185/65 R15	DUNLOP	5 mm
	R/H Rear Tyre	185/65 R15	DUNLOP	5 mm
	L/H Rear Tyre	185/65 R15	DUNLOP	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	20/06/2021	Inspection Date	25/06/2021
	Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	