

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21006889/AQCN2**Date:** 14/09/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00064652100

**Claimant Vehicle No :** SLW4176L **Insured Vehicle No :** SLJ6959A

Date of Loss: 14/06/2021 Nature of Claim: TP Claim No: SNM21D203397/C2/IRENE

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLW4176L**

Make & Model: TOYOTA C-HR HYBRID, 1.8 S (A) Engine No: 2ZR8233674

Reg. Date: 09/02/2018 (Man. Year: 2017) Chassis No: ZYX102084816

Colour: Yellow Odometer: 257807 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17

Front Left Side: APLUS 6 mm Rear Left Side: APLUS 6 mm

Front Right Side: APLUS 6 mm Rear Right Side: APLUS 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 13,421.77         | 4,107.82          | 9,313.95          | 69.39         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 5,530.00          | 1,370.00          | 4,160.00          | 75.23         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>18,951.77</b>  | <b>5,477.82</b>   | <b>13,473.95</b>  | <b>71.10</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>4,300.00</b>   |                   |               |
| <b>(S\$)</b>                             | 18,951.77         | 4,300.00          | 14,651.77         | 77.31         |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 1,326.62          | 301.00            | 1,025.62          | 77.31         |
| <b>Nett Amount (S\$)</b>                 | <b>20,278.39</b>  | <b>4,601.00</b>   | <b>15,677.39</b>  | <b>77.31</b>  |

**INSPECTION**

Date of Assignment: 22/06/2021

Date Inspected: 30/06/2021 Inspected At: RICO 60 AUTO SERVICES PTE LTD  
BLK 8, KAKI BUKIT AVENUE 4, #02-24  
PREMIER@KAKI BUKIT SINGAPORE 415875

Estimated Period of Repair: 5.0 days

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 13 Sep 2021)                  |
| <b>Parts:</b>        | M1-SUV                                                                                                                                                                       | TOYOTA C-HR HYBRID 1.8 S (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                              |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLW4176L)                                                                                                                                    |                                                                |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                |

### Recommended Parts

| No. | Qty | Part No. | Particulars                     | Condition     | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *FRONT BUMPER                   | Not Necessary | 1,050.70 FL | *- FL        |
| 2   | 2   |          | *FRONT BUMPER SIDE RETAINER     | Not Necessary | 150.00 FL   | *- FL        |
| 3   | 1   |          | *HEADLAMP RH                    | Not Necessary | 1,763.20 FL | *- FL        |
| 4   | 1   |          | *HEADLAMP LOWER BRACKET RH      | Not Necessary | 75.40 FL    | *- FL        |
| 5   | 1   |          | *FRONT FENDER RH                | Dented        | 855.00 FL   | *695.00 FL   |
| 6   | 1   |          | *FRONT FENDER EMBLEM (HYBRID)   | Necessary     | 112.40 FL   | *112.40 FL   |
| 7   | 1   |          | *FRONT FENDER ARCH GARNISH RH   | Cut           | 317.40 FL   | *201.00 FL   |
| 8   | 1   |          | *FRONT FENDER INNER BRACKET RH  | Not Necessary | 90.00 FL    | *- FL        |
| 9   | 1   |          | *FRONT FENDER COWLING RH        | Not Necessary | 212.00 FL   | *- FL        |
| 10  | 1   |          | *FRONT ABSORBER RH              | Not Necessary | 593.60 FL   | *- FL        |
| 11  | 1   |          | *FRONT LOWER ARM RH             | Bent          | 780.10 FL   | *497.00 FL   |
| 12  | 1   |          | *FRONT WHEEL BEARING RH         | Damaged       | 697.10 FL   | *278.00 FL   |
| 13  | 1   |          | *FRONT DOOR RH                  | Dented        | 1,347.10 FL | *1,347.10 FL |
| 14  | 2   |          | *FRONT DOOR BLACK STICKER RH    | Necessary     | 90.00 FL    | *90.00 FL    |
| 15  | 1   |          | *FRONT DOOR LOWER PROTECTOR RH  | Cut           | 311.00 FL   | *311.00 FL   |
| 16  | 1   |          | *FRONT DOOR SIDE MIRROR RH      | Not Necessary | 1,548.80 FL | *- FL        |
| 17  | 1   |          | *FRONT DOOR OUTER MOULDING RH   | Not Necessary | 180.80 FL   | *- FL        |
| 18  | 1   |          | *FRONT DOOR OUTER HANDLE RH     | Not Necessary | 247.90 FL   | *- FL        |
| 19  | 2   |          | *FRONT DOOR HINGE RH            | Not Necessary | 194.00 FL   | *- FL        |
| 20  | 1   |          | *FRONT DOOR CHECKER RH          | Not Necessary | 119.70 FL   | *- FL        |
| 21  | 1   |          | *FRONT DOOR INNER LOCK RH       | Not Necessary | 419.00 FL   | *- FL        |
| 22  | 1   |          | *FRONT DOOR LOCK CATCH RH       | Not Necessary | 46.00 FL    | *- FL        |
| 23  | 1   |          | *FRONT DOOR WEATHERSTRIP RH     | Not Necessary | 189.00 FL   | *- FL        |
| 24  | 1   |          | *REAR DOOR RH                   | Repair        | 1,254.20 FL | *- FL        |
| 25  | 2   |          | *REAR DOOR BLACK STICKER RH     | Not Necessary | 90.00 FL    | *- FL        |
| 26  | 1   |          | *REAR DOOR WEATHERSTRIP RH      | Not Necessary | 189.00 FL   | *- FL        |
| 27  | 1   |          | *REAR DOOR LOWER PROTECTOR RH   | Cut           | 311.60 FL   | *311.60 FL   |
| 28  | 1   |          | *SIDE SKIRT RH                  | Cut           | 754.00 FL   | *754.00 FL   |
| 29  | 1   |          | *FRONT ORIGINAL RIM RH          | Cut           | 1,596.15 FS | *600.00 FS   |
| 30  | 1   |          | *FRONT BUMPER CLIP              | Not Necessary | 50.00 FS    | *- FS        |
| 31  | 1   |          | *FRONT FENDER COWLING CLIP      | Not Necessary | 40.00 FS    | *- FS        |
| 32  | 1   |          | *FRONT FENDER ARCH GARNISH CLIP | Necessary     | 40.00 FS    | *20.00 FS    |
| 33  | 1   |          | *FRONT DOOR INNER TRIM CLIP     | Not Necessary | 40.00 FS    | *- FS        |
| 34  | 1   |          | *FRONT DOOR PROTECTOR CLIPS     | Necessary     | 40.00 FS    | *20.00 FS    |
| 35  | 1   |          | *REAR DOOR PROTECTOR CLIPS      | Necessary     | 40.00 FS    | *20.00 FS    |
| 36  | 1   |          | *SIDE SKIRT CLIPS               | Not Necessary | 60.00 FS    | *- FS        |
| 37  | 1   |          | *TYRE                           | Not Necessary | 500.00 FS   | *- FS        |
| 38  | 1   |          | *FRONT KNUCKLE ARM RH           | Not Necessary | 698.50 FL   | *- FL        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                 |
|------------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>17,093.65</b> | <b>5,257.10</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | 3,671.88         | 1,149.28        |
| <b>Total Parts (\$\$)</b>                                  | <b>13,421.77</b> | <b>4,107.82</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                      | Lab.Type | Repairer's      | Amount          |
|---------------------------------|------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                  |          |                 |                 |
| 1                               | PANEL BEATING,REMOVAL AND REPLACING PARTS                        | New      | 1,800.00        | 600.00          |
| 2                               | TO SPRAY PAINT AFFECTED AREA                                     | New      | 1,800.00        | 400.00          |
| 3                               | TO APPLY TUFF COAT                                               | New      | 180.00          | 0.00            |
| 4                               | PERFORM REAR WIRING CHECK                                        | New      | 100.00          | 30.00           |
| 5                               | REMOVE & REFIX FRONT DOOR PART                                   | New      | 200.00          | 80.00           |
| 6                               | REMOVE & REFIX FRONT UNDER CARRIAGE                              | New      | 600.00          | 180.00          |
| 7                               | REMOVE & REFIX REAR DOOR PART                                    | New      | 200.00          | 0.00            |
| 8                               | REMOVE AND REFIX UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR | New      | 400.00          | 0.00            |
| 9                               | TO CHECK FOUR WHEEL ALIGHMENT                                    | New      | 150.00          | 80.00           |
| 10                              | CONDUCT WATER LEAKAGE TEST                                       | New      | 100.00          | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |                                                                  |          | <b>5,530.00</b> | <b>1,370.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >