

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21006892/UEA3Q2
Date: 29/10/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000461
Claimant Vehicle No :	FBM1181L	Insured Vehicle No :	XE1415U
Date of Loss:	16/06/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002595

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBM1181L		
Make & Model:	HONDA CB150R, 149cc	Engine No:	KC32E0019242
Reg. Date:	21/04/2018 (Man. Year: 2018)	Chassis No:	MLHKC2888J5019242
Colour:	Red	Odometer:	26814 km
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110/70 R17	Rear Tyre Size:	150/60 R17
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,254.60	798.40	3,456.20	81.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,065.00	415.00	650.00	61.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,319.60	1,213.40	4,106.20	77.19
Approved Total (Overridden) (S\$)		970.00		

Nett Amount (S\$)	5,319.60	970.00	4,349.60	81.77
+ Loss of Use (5.0 x S\$20.00/day) (S\$)		100.00		
+ Other Costs (S\$)		35.00		
Nett Liability (S\$)		1,105.00		

INSPECTION

Date of Assignment: 21/06/2021

Date Inspected: 22/06/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
 1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Oct 2021)	
Parts:	N/A	HONDA CB150R 149cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBM1181L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Not Necessary	175.00 FL	*- FL
2	1		*FRONT FORK -L/R/H	Not Necessary	960.00 FL	*- FL
3	1		*FRONT FORK UNDER BRACKET	Not Necessary	255.00 FL	*- FL
4	1		*FRONT RIM SHAFT	Not Necessary	68.00 FL	*- FL
5	1		*FRONT WHEEL RIM	Not Necessary	850.00 FL	*- FL
6	1		*HANDLE -BAR	Serviceable	155.00 FL	*- FL
7	1		*HANDLE -BAR ENDS	O/S Cut	128.00 FL	*40.00 FL
8	1		*SET HAND GRIPS (TORN)	Not Consistent With The Impact	80.00 FL	*- FL
9	1		*BRAKE LEVER	Scratched	75.00 FL	*68.00 FL
10	1		*SET FRONT SIDE MIRROR	Damaged	150.00 FL	*140.00 FL
11	1		*TROTTLER CABLE	Not Necessary	145.00 FL	*- FL
12	1		*FRONT FOOTREST -R/H	Cut	75.00 FL	*75.00 FL
13	1		*FRONT FOOTREST BRACKET -R/H	Not Necessary	245.00 FL	*- FL
14	1		*BRAKE PEDAL	Cut	95.00 FL	*95.00 FL
15	1		*REAR FOOTREST -R/H	Serviceable	70.00 FL	*- FL
16	1		*RADIATOR SIDE COVER -R/H	Scratched	158.00 FL	*158.00 FL
17	1		*TANK SIDE COVER-R/H	Repair	300.00 FL	*- FL
18	1		*SET NUMBER PLATE	Not Necessary	28.00 FS	*- FS
19	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
20	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
21	1		*SET STEERING CONE	Not Necessary	95.00 FS	*- FS
22	1		*REAR FOOD BAG	Torn	280.00 FS	*280.00 FS
23	1		*REAR BOX BRACKET	Repair	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,653.00	856.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	398.40	57.60

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)						4,254.60
						798.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE (LOD)	New	35.00	35.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO RESPRAY PAINT	New	200.00	180.00
4	TO REPAIR BODY FRAME	New	350.00	0.00
5	TO PROVIDE LABOUR	New	400.00	200.00
Gross Labour Cost (S\$)			1,065.00	415.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >