

**Supplementary Estimate**

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.**Date****Service Advisor****Pages****Regn No****Model No**

PA/OD/0507/2021/KS

25-Jun-21

CHANG

1 of 1

SMQ 1942 G

AUDI A3 SEDAN 1.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	FRONT FENDER BRACKET - RH REAR <i>Bent</i>	\$ 39.00	✓ 30.72
GRAND TOTAL		\$ 39.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian L;
25/06/21
[Signature]



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMQ 1942 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING LID.	S/N \$ 360.00	x.
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER CONTROL.	S/N \$ 350.00	250.
3	TO REMOVE AND REINSTALL AIRCOND CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. TO REPAIR BOTH FRONT FENDER TOP SUPPORTS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00	1000 (without lock carrier). 2250 (with lock carrier) 1650
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, HINGES AND BONNET.	\$ 3,000.00	x.
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 10,202.00	

+ 3 days
H.K.

Car in 24/6/14.

wp = 32075

PREMIUM AUTOMOBILES

L2/Hong



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

E-MAIL: NGRA.KHA1@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

AIG - Adnan

- 6 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 1942 G

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Dented</i>	1	\$ 1,987.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 187.00	X
3	FRONT BUMPER GUIDE SECTION RH <i>Not in</i>	1	\$ 39.00	✓
4	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 160.00	X
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$ 536.00	✓
6	FRONT BUMPER CLOSING ELEMENT - RH <i>could be</i>	1	\$ 297.00	✓
7	FRONT BUMPER COVER TRIM RH <i>new</i>	1	\$ 163.00	X
8	FRONT WHEEL HOUSING LINER ADAPTOR RH <i>Not in</i>	1	\$ 38.00	✓
9	RADIATOR GRILLE <i>could</i>	1	\$ 1,406.00	✓
10	RADIATOR GRILLE CLOSING ELEMENT <i>could</i>	1	\$ 191.00	✓
11	FRONT BUMPER AIR GUIDE GRILLE RH <i>new</i>	1	\$ 188.00	✓
12	"A/C" STICKER <i>new</i>	1	\$ 8.00	✓
13	"CAUTION" STICKER <i>new</i>	1	\$ 14.00	✓
14	FRONT REINFORCEMENT BEAM <i>Dented</i>	1	\$ 795.00	✓
15	REINFORCEMENT BEAM FOAM FILLER PIECE <i>could</i>	1	\$ 189.00	✓
16	REINFORCEMENT BEAM COVER <i>could</i>	1	\$ 172.00	✓
17	SIGNAL HORN RH <i>Not in</i>	1	\$ 200.00	✓
18	FRONT FENDER RH <i>Buckled</i>	1	\$ 851.00	✓
19	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 72.00	X
20	FRONT FENDER BRACKET RH <i>Buckled</i>	1	\$ 28.00	✓
SUBTOTAL SPARE PARTS			\$ 7,471.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Add

N 016 1857 X 6



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 1942 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACE RH <i>Best</i>	1	\$ 96.00	✓
22	FRONT WHEEL HOUSING LINER RH <i>rel m</i>	1	\$ 169.00	+
23	FRONT WHEEL HOUSING LINER ATTACHMENT PART RH <i>rel m</i>	1	\$ 89.00	+
24	BONNET <i>Rel</i>	1	\$ 3,134.00	+
25	BONNET ATTACHMENT PARTS	1	\$ 165.00	+
26	BONNET HINGE LH / RH	2	\$ 124.00	+
27	BONNET CATCH HOOK	1	\$ 90.00	+
28	BONNET STRIKER LH / RH	2	\$ 220.00	+
29	BONNET EDGE PROTECTION	1	\$ 28.00	+
30	BONNET LOCK WITH MICRO SWITCH	2	\$ 427.00	+
31	BONNET BOWDEN CABLE CENTER	1	\$ 58.00	+
32	BONNET BOWDEN CABLE COVER CENTER	1	\$ 10.00	+
33	LED HEADLIGHT RH <i>crushed</i>	1	\$ 5,455.00	✓
34	HEADLIGHT POWER MODULE RH	1	\$ 758.00	+
35	LED WITH HEAT SINK RH	1	\$ 733.00	+
36	HEADLIGHT CONTROL UNIT RH	1	\$ 557.00	+
37	HEADLIGHT BREATHER HOSE RH	1	\$ 40.00	+
38	LIFT CYLINDER RH	1	\$ 142.00	?
39	LIFT CYLINDER HOSE RH <i>rel m</i>	1	\$ 68.00	+
40	LOCK CARRIER <i>crushed</i>	1	\$ 727.00	✓
SUBTOTAL SPARE PARTS		:	\$ 13,090.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 1942 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	RADIATOR AIR GUIDE RH <i>cm Ld</i>	1	\$ 25.00	✓
42	RADIATOR AIR GUIDE RH - UPPER CENTRE ?	1	\$ 12.00	?
43	RADIATOR COOLANT <i>me</i>	6	\$ 266.00	✓
44	FRONT NO PLATE <i>aler</i>	S/N	\$ 60.00	✓
45	SUNDRIES ?	1	\$ 350.00	?
TOTAL SPARE PARTS		:	\$ 21,274.00	
TOTAL LABOUR CHARGES		:	\$ 10,202.00	
GRAND TOTAL		:	\$ 31,476.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

Adrian G
 25/06/21
SPS