

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0507/2021/KS
DATE : 21-Jun-21
WIP : 32075

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/06/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

**8 days exclude 1 Sunday - Johnny Boo
20-Sep-21**

OWNER'S NAME : MR WONG TUCK HUEI
ADDRESS : BLK 159 YISHUN ST11
#08-174
SINGAPORE760159
TELEPHONE : HP +65 91847672
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900235910-01
VEHICLE NO : **SMQ 1942 G**
MODEL CODE : A3 SEDAN 1.0 TFSI
MODEL YEAR : 10/31/2019
ENGINE NO : CHZ C31207
CHASSIS NO : WAUZZZ8V8KA096455
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Jun-21
PLACE OF ACCIDENT : 307 CHANGI RD, NEAR KATONG LAKSA PARKING LOT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMQ 1942 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND TRANSFER FRONT WIRE HARNES FOR HEADLIGHTS , HORNS , OUTSIDE TEMPERATURE SENSOR , HEADLIGHT WASHER ASSY AND FRONT PARKING LID. <i>(L/Carrier replaced)</i>	S/N \$	360.00	\$ 360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER CONTROL.	S/N \$	350.00	\$ 250.00
3	TO REMOVE AND REINSTALL AIRCOND CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$	1,400.00	\$ 1,400.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. TO REPAIR BOTH FRONT FENDER TOP SUPPORTS. RE- ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,900.00	\$ 2,250.00
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, HINGES AND BONNET.	\$	3,000.00	\$ 1,650.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 10,202.00	\$ 6,102.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG
MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 1942 G

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 1,987.00	\$	1,589.60
2	FRONT BUMPER FIXING PARTS	1	\$ 187.00		
3	FRONT BUMPER GUIDE SECTION RH	1	\$ 39.00		
4	FRONT BUMPER GRILLE - CENTER	1	\$ 160.00		
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 536.00		
6	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 297.00	\$	237.20
7	FRONT BUMPER COVER TRIM RH	1	\$ 163.00		
8	FRONT WHEEL HOUSING LINER ADAPTOR RH	1	\$ 38.00		
9	RADIATOR GRILLE	1	\$ 1,406.00	\$	1,124.80
10	RADIATOR GRILLE CLOSING ELEMENT	1	\$ 191.00	\$	152.40
11	FRONT BUMPER AIR GUIDE GRILLE RH	1	\$ 188.00		
12	"A/C" STICKER	1	\$ 8.00	\$	5.68
13	"CAUTION" STICKER	1	\$ 14.00	\$	10.88
14	FRONT REINFORCEMENT BEAM	1	\$ 795.00	\$	636.00
15	REINFORCEMENT BEAM FOAM FILLER PIECE	1	\$ 189.00	\$	151.20
16	REINFORCEMENT BEAM COVER	1	\$ 122.00	\$	97.20
17	SIGNAL HORN RH	1	\$ 200.00		
18	FRONT FENDER RH	1	\$ 851.00	\$	680.40
19	FRONT FENDER ATTACHMENT PARTS	1	\$ 72.00		
20	FRONT FENDER BRACKET RH	1	\$ 28.00	\$	21.84
SUBTOTAL SPARE PARTS		:	\$ 7,471.00	\$	4,707.20

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG
MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 1942 G

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	4,707.20
21	FRONT FENDER BRACE RH	1	\$ 96.00	\$	76.48
22	FRONT WHEEL HOUSING LINER RH	1	\$ 169.00		
23	FRONT WHEEL HOUSING LINER ATTACHMENT PART RH	1	\$ 89.00		
24	BONNET	1	\$ 3,134.00		
25	BONNET ATTACHMENT PARTS	1	\$ 165.00		
26	BONNET HINGE LH / RH	2	\$ 124.00		
27	BONNET CATCH HOOK	1	\$ 90.00		
28	BONNET STRIKER LH / RH	2	\$ 220.00		
29	BONNET EDGE PROTECTION	1	\$ 28.00		
30	BONNET LOCK WITH MICRO SWITCH	2	\$ 427.00		
31	BONNET BOWDEN CABLE CENTER	1	\$ 58.00		
32	BONNET BOWDEN CABLE COVER CENTER	1	\$ 10.00		
33	LED HEADLIGHT RH	1	\$ 5,455.00	\$	4,364.00
34	HEADLIGHT POWER MODULE RH	1	\$ 758.00		
35	LED WITH HEAT SINK RH	1	\$ 733.00		
36	HEADLIGHT CONTROL UNIT RH	1	\$ 557.00		
37	HEADLIGHT BREATHER HOSE RH	1	\$ 40.00		
38	LIFT CYLINDER RH	1	\$ 142.00		
39	LIFT CYLINDER HOSE RH	1	\$ 68.00		
40	LOCK CARRIER	1	\$ 727.00	\$	581.60
SUBTOTAL SPARE PARTS		:	\$ 13,090.00	\$	9,729.28

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 1942 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 9,729.28
41	RADIATOR AIR GUIDE RH	1	\$ 25.00	\$ 19.44
42	RADIATOR AIR GUIDE RH - UPPER CENTRE	1	\$ 12.00	
43	RADIATOR COOLANT	6	\$ 266.00	\$ 214.56
44	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
45	Added parts - see attached		\$ 39.00	\$ 30.72
46	SUNDRIES	1	\$ 350.00	\$ 20.64
TOTAL SPARE PARTS		:	\$ 21,313.00	\$ 10,074.64
TOTAL LABOUR CHARGES		:	\$ 10,202.00	\$ 6,102.00
GRAND TOTAL		:	\$ 31,515.00	\$ 16,176.64

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0507/2021/KS 25-Jun-21 CHANG 1 of 1 SMQ 1942 G AUDI A3 SEDAN 1.0 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	FRONT FENDER BRACKET - RH REAR	\$ 39.00	\$	30.72
	GRAND TOTAL	\$ 39.00	\$	30.72

For Premium Automobiles Pte Ltd

Authorised Signature



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT