



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0507/2021/KS
DATE : 21-Jun-21
WIP : 32075

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/06/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR WONG TUCK HUEI
ADDRESS : BLK 159 YISHUN ST11
#08-174
SINGAPORE 760159
TELEPHONE : HP +65 91847672
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900235910-01
VEHICLE NO : **SMQ 1942 G**
MODEL CODE : A3 SEDAN 1.0 TFSI
MODEL YEAR : 31/10/2019
ENGINE NO : CHZ C31207
CHASSIS NO : WAUZZZ8V8KA096455
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Jun-21
PLACE OF ACCIDENT : 307 CHANGI RD, NEAR KATONG LAKSA PARKING LOT

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMQ 1942 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS , HORNS , OUTSIDE TEMPERATURE SENSOR , HEADLIGHT WASHER ASSY AND FRONT PARKING LID.	S/N \$ 360.00	x. ✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER CONTROL.	S/N \$ 350.00 250	✓
3	TO REMOVE AND REINSTALL AIRCOND CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	? ✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. TO REPAIR BOTH FRONT FENDER TOP SUPPORTS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00	1000 (without lock carrier). 2250 (with lock carrier) ✓
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, HINGES AND BONNET.	\$ 3,000.00	1650 ✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 10,202.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 1942 G

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Dehnd</i>	1	\$ 1,987.00 ✓	1589.6	
2	FRONT BUMPER FIXING PARTS <i>neu</i>	1	\$ 187.00 x		
3	FRONT BUMPER GUIDE SECTION RH <i>neu</i>	1	\$ 39.00 x		
4	FRONT BUMPER GRILLE - CENTER <i>neu</i>	1	\$ 160.00 x		
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>neu</i>	1	\$ 536.00 x		
6	FRONT BUMPER CLOSING ELEMENT - RH <i>neu</i>	1	\$ <i>cracked</i> 297.00 x	237.2	
7	FRONT BUMPER COVER TRIM RH <i>neu</i>	1	\$ 163.00 x		
8	FRONT WHEEL HOUSING LINER ADAPTOR RH <i>neu</i>	1	\$ 38.00 x		
9	RADIATOR GRILLE <i>cracked</i>	1	\$ 1,406.00 ✓	1406	
10	RADIATOR GRILLE CLOSING ELEMENT ? <i>cracked</i>	1	\$ 191.00 ?	152.4	
11	FRONT BUMPER AIR GUIDE GRILLE RH <i>neu</i>	1	\$ 188.00 x		
12	"A/C" STICKER } <i>neu</i>	1	\$ 8.00 ✓	5.68	
13	"CAUTION" STICKER }	1	\$ 14.00 ✓	10.88	
14	FRONT REINFORCEMENT BEAM ? <i>dented</i>	1	\$ 795.00 ?	636	
15	REINFORCEMENT BEAM FOAM FILLER PIECE ? <i>cracked</i>	1	\$ 189.00 ?	151.2	
16	REINFORCEMENT BEAM COVER ? <i>cracked</i>	1	\$ 122.00 ?	97.2	
17	SIGNAL HORN RH <i>neu</i>	1	\$ 200.00 x		
18	FRONT FENDER RH <i>Buckled</i>	1	\$ 851.00 ✓	680.4	
19	FRONT FENDER ATTACHMENT PARTS <i>neu</i>	1	\$ 72.00 x		
20	FRONT FENDER BRACKET RH <i>Buckled</i>	1	\$ 28.00 ✓	21.84	
SUBTOTAL SPARE PARTS		:	\$ 7,471.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 1942 G

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT FENDER BRACE RH ? bent	1	\$ 96.00	76.48	
22	FRONT WHEEL HOUSING LINER RH not m	1	\$ 169.00	x	
23	FRONT WHEEL HOUSING LINER ATTACHMENT PART RH not m	1	\$ 89.00	x	
24	BONNET Regis	1	\$ 3,134.00	x	
25	BONNET ATTACHMENT PARTS }	1	\$ 165.00	x	
26	BONNET HINGE LH / RH	2	\$ 124.00	x	
27	BONNET CATCH HOOK	1	\$ 90.00	x	
28	BONNET STRIKER LH / RH not m	2	\$ 220.00	x	
29	BONNET EDGE PROTECTION	1	\$ 28.00	x	
30	BONNET LOCK WITH MICRO SWITCH }	2	\$ 427.00	x	
31	BONNET BOWDEN CABLE CENTER not m	1	\$ 58.00	x	
32	BONNET BOWDEN CABLE COVER CENTER	1	\$ 10.00	x	
33	LED HEADLIGHT RH cracked	1	\$ 5,455.00	4364	
34	HEADLIGHT POWER MODULE RH }	1	\$ 758.00	x	
35	LED WITH HEAT SINK RH }	1	\$ 733.00	x	
36	HEADLIGHT CONTROL UNIT RH not m	1	\$ 557.00	x	
37	HEADLIGHT BREATHER HOSE RH	1	\$ 40.00	x	
38	LIFT CYLINDER RH ? nn	1	\$ 142.00	x	
39	LIFT CYLINDER HOSE RH not m	1	\$ 68.00	x	
40	LOCK CARRIER ? cracked	1	\$ 727.00	581.60	
SUBTOTAL SPARE PARTS		:	\$ 13,090.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 1942 G

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	RADIATOR AIR GUIDE RH <i>?</i> cracked	1	\$ 25.00	<i>?</i>	19.44
42	RADIATOR AIR GUIDE RH - UPPER CENTRE <i>?</i> nn	1	\$ 12.00	<i>?</i>	
43	RADIATOR COOLANT <i>?</i> nec	6	\$ 266.00	<i>?</i>	214.56
44	FRONT NO PLATE <i>Mer</i>	S/N	\$ 60.00	<i>✓</i>	60
45	SUNDRIES <i>?</i> nec	1	\$ 350.00	<i>?</i>	20.64
TOTAL SPARE PARTS		:	\$ 21,274.00		
TOTAL LABOUR CHARGES		:	\$ 10,202.00		
GRAND TOTAL		:	\$ 31,476.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lij*
SURVEYED DATE : *21/06/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 06 Days Without Lock Carrier
09 Days With Lock Carrier*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

8days

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT