



DICKSON GROUP

Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
TEL: 6668 1122 | FAX: 6668 1123

QUOTATION

QUOTATION FOR

NAME:
COMPANY NAME: India International Insurance
STREET ADDRESS: 64 Cecil Street #04, #05, IOB Building
POSTAL CODE: 049711
PHONE:

DATE: 21/6/2021

REF:
VEHICLE NO.: SMM1436Y
MAKE: KIA
MODEL: STONIC 1.0
PREPARED BY: MAHIRAH

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
	LABOUR						
1	To remove & refit reverse sensor and wiring				\$ -		\$ 120.00
2	To provide skill labour to remove all rear damaged parts, panel beating, cut and weld if necessary.				\$ -		\$ 600.00
3	To provide skill labour & material to put all rear damaged parts & panels and to respray with 2K paint with oven				\$ -		\$ 600.00
	PARTS						
1	Rear Bumper Upper				\$ -		\$ 330.00
2	Rear Bumper Lower				\$ -		\$ 110.00
3	Rear Bumper Beam				\$ -		\$ 377.30
4	Rear Bumper Reflector LH				\$ -		\$ 99.50
5	Rear Bumper Reflector RH				\$ -		\$ 99.50
6	Rear Bumper Sensor				\$ -		\$ 170.10
7	Rear End Panel				\$ -		\$ 310.90
8	Tail Gate				\$ -		\$ 1,011.00
SUBTOTAL					\$ -	SUBTOTAL	\$ 3,828.30
GST 7%					1.07	GST 7%	1.07
TOTAL					\$ -	TOTAL	\$ 4,096.28

REMARKS:

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD

(CUSTOMER'S SIGNATURE AND
COMPANY STAMP)

(AUTHORISED SIGNATURE)

