

DICKSON AUTO CARE CENTRE PTE LTD 29 UBI ROAD 4, DICKSON AUTO CENTRE SINGAPORE 408619 TEL: 6668 1122 | FAX: 6668 1123

QUOTATION

DATE: 21/6/2021

REF:

VEHICLE NO.: SMM1436Y

MAKE: KIA

MODEL: STONIC 1.0 PREPARED BY: MAHIRAH

QUOTATION FOR

NAME:

COMPANY NAME: India International Insurance

STREET ADDRESS: 64 Cecil Street #04, #05, IOB Building

POSTAL CODE: 049711

PHONE:

S/N	DESCRIPTION	NOM UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
	LABOUR					
1	To remove & refit reverse sensor and wiring			s -		\$ 120-00
2	To provide skill labour to remove all rear damaged parts, panel beating, cut and weld if necessary.	40		s -		\$ 600.00
3	To provide skill labour & material to put all rear damaged parts & panels and to respray with 2K paint with oven			\$ -		\$ 60000
	PARTS					
1	Rear Bumper Upper			s -		\$ 330.00
2	Rear Bumper Lower			\$ -		\$ 110.00
3	Rear Bumper Beam			s -		\$ 377.30
4	Rear Bumper Reflector LH XVI m			\$ -		\$ 99.50
5	Rear Bumper Reflector RH			\$ -		\$ 99.50
6	Rear Bumper Sensor			\$ -		\$ 170.10
7	Rear End Panel Page			\$ -		\$ 310.96

TPIII

Xino Tony

REMARKS:

SUBTOTAL

GST 7%

TOTAL

1.07

SUBTOTAL GST 7% TOTAL

1.07 4,096.28

1,011.00

3.828.30

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE

FOR DICKSON AUTO CARE CENTRE PTE LTD

LKK Auto Consultants heads notificature and the Repairer of the following meany stamp)

Rear End Panel

Tail Gate

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NATURE)

96893735