



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0508/2021/TF
DATE : 22-Jun-21
WIP : 32210

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/6/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Steve

9 days exclude 1 Sunday

Johnny Boo 20 Aug 21

OWNER'S NAME : MR. NI SHUCHANG, KEVIN
ADDRESS : BLK 28 WOODLANDS DRIVE 16
#03-19
SINGAPORE 737768
TELEPHONE : HP +65 9477 5752
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070179107
VEHICLE NO : **SLJ 6090 E**
MODEL CODE : Q3 SPORTBACK 1.4 TFSI S tronic
MODEL YEAR : 30/12/2020
ENGINE NO : CZD C21588
CHASSIS NO : WAUZZZF36M1054631
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-Jun-21
PLACE OF ACCIDENT : BKE/KJE TOWARDS PIE

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLJ 6090 E

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS'S CONTROL UNIT AND POWER MODULE.	S/N \$	800.00	\$	500.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$	1,700.00	\$	1,700.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FENDERS, AND BOTH HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	6,400.00	\$	2,500.00
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER SPOILER, BOTH FRONT FENDER, HINGES, BONNET AND BOTH FRONT WHEEL ARCH TRIMS.(\$200 each)	\$	5,900.00	\$	1,500.00
6	TO REAPPLY PAINT COATING FOR AFFECTED AREA. (BY OWNER)	S/N \$	50.00	\$	50.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 15,522.00	\$	6,922.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLJ 6090 E

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,815.00	\$	2,251.60
2	FRONT BUMPER FIXING PARTS	1	\$ 414.00		
3	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 118.00		
4	FRONT BUMPER CENTER TRIM (MANHATTAN GREY)	1	\$ 356.00		
5	FRONT BUMPER GRILLE - CENTER	1	\$ 217.00		
6	FRONT BUMPER SENSOR SUPPORT	2	\$ 50.00		
7	FRONT BUMPER LOWER COVER - CENTER	1	\$ 51.00		
8	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 190.00		
9	FRONT BUMPER SPOILER	1	\$ 763.00		
10	FRONT BUMPER SPOILER BRACKET	1	\$ 21.00		
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 306.00		
12	FRONT BUMPER AIR GUIDE TRIM - LH / RH	2	\$ 328.00		
13	FRONT BUMPER SIDE SENSOR SUPPORT - LH / RH	2	\$ 50.00		
14	FRONT RADIATOR GRILLE	1	\$ 1,928.00	\$	1,542.40
15	FRONT RADIATOR GRILLE STRIKER PLATE	1	\$ 244.00	\$	194.80
16	FRONT RADIATOR GRILLE LOGO COVER	1	\$ 56.00		
17	FRONT BUMPER BRACKET	1	\$ 41.00		
18	FRONT BUMPER SECURING PLATE	1	\$ 33.00		
19	FRONT RADIATOR GRILLE COVER	1	\$ 244.00	\$	194.80
20	FRONT CAMERA	1	\$ 1,141.00		
SUB TOTAL SPARE PARTS			\$ 9,366.00	\$	4,183.60

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLJ 6090 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
	<i>c/f</i>			\$ 4,183.60
21	FRONT BUMPER CARRIER	1	\$ 916.00	
22	FRONT BUMPER CARRIER FOAM	1	\$ 102.00	
23	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 78.00	
24	FRONT BUMPER TOP COVER	1	\$ 123.00	\$ 98.00
25	CAUTION STICKER	1	\$ 14.00	\$ 10.88
26	A/C STICKER	1	\$ 8.00	\$ 5.68
27	FRONT BUMPER PARKING AID SENSOR	2	TBC	
28	FRONT BUMPER PARKING AID SENSOR SEAL	4	\$ 16.00	
29	FRONT BUMPER WIRING SET	1	\$ 572.00	\$ 479.20
30	HORN - LH / RH	2	\$ 267.00	
31	HORN BRACKET - LH / RH	2	\$ 44.00	
32	FRONT FENDER - LH / RH	2	\$ 2,572.00	
33	FRONT FENDER ATTACHMENT PARTS	1	\$ 63.00	
34	FRONT FENDER BRACE - LH / RH	2	\$ 176.00	
35	FRONT FENDER BRACKET - LH / RH	2	\$ 64.00	
36	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 480.00	
37	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 101.00	
38	FRONT BONNET	1	\$ 3,508.00	\$ 2,806.40
39	FRONT BONNET HINGE - LH / RH	2	\$ 146.00	
40	FRONT BONNET ATTACHMENT PARTS	1	\$ 296.00	
SUB TOTAL SPARE PARTS			\$ 9,546.00	\$ 7,583.76

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLJ 6090 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 7,583.76
41	FRONT BONNET STRIKER - LH / RH	2	\$ 220.00	
42	FRONT BONNET SOUND ABSORBER	1	\$ 219.00	
43	FRONT BONNET INPACT PROTECTION	1	\$ 28.00	\$ 21.84
44	FRONT BONNET LOCK	2	\$ 427.00	\$ 170.80
45	FRONT BONNET RELEASE ELEMENT	1	\$ 58.00	
46	FRONT BONNET RELEASE LEVER	1	\$ 14.00	
47	FRONT BONNET BOWDEN CABLE	1	\$ 58.00	
48	FRONT BONNET BOWDEN CABLE COVER	1	\$ 10.00	
49	FRONT HEADLIGHT MOUNTING - LH / RH	2	\$ 236.00	\$ 188.80
50	FRONT HEADLIGHT - LH / RH	2	\$ 11,178.00	\$ 8,942.40
51	FRONT HEADLIGHT LIFT CYLINDER - LH / RH	2	\$ 420.00	
52	FRONT HEADLIGHT LIFT CYLINDER HOSE	1	\$ 80.00	
53	FRONT WHEEL ARCH TRIM - LH / RH	2	\$ 1,072.00	\$ 857.60
54	FRONT LOCK CARRIER	1	\$ 1,272.00	\$ 1,017.60
55	A/C CONDENSER	1	\$ 551.00	\$ 440.80
56	TEMPERATURE SENSOR	1	\$ 7.00	
57	ADDITIONAL RADIATOR	1	\$ 920.00	
58	RADIATOR	1	\$ 1,035.00	
59	COOLANT	6	\$ 266.00	\$ 214.56
60	RADIATOR AIR GULDE- LH / RH / UPPER / LOWER	1	\$ 160.00	\$ 59.52
SUB TOTAL SPARE PARTS			\$ 18,231.00	\$ 19,497.68

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLJ 6090 E

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
		<i>c/f</i>		\$ 19,497.68
61	FRONT TOP AIR GUIDE	1	\$ 56.00	
62	INTAKE AIR DUCT COVER	1	\$ 29.00	
63	INTAKE AIR GUIDE	1	\$ 20.00	
64	INTAKE AIR GUIDE HOSE	1	\$ 34.00	
65	FRONT NO. PLATE	S/N	\$ 60.00	\$ 60.00
66	SUNDRIES		\$ 400.00	\$ 12.80
TOTAL SPARE PARTS			\$ 37,742.00	\$ 19,570.48
TOTAL LABOUR CHARGES			\$ 15,522.00	\$ 6,922.00
GRAND TOTAL			\$ 53,264.00	\$ 26,492.48

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-29/07/21



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
[EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT