

08/11/13) wef
ASS. REC. BY: Rasul

REF:

369K

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHD 6128K Yr Regn: 2015 / NOV
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: TOYOTA PRIMS TAXI c.c. 1798
Colour: MAROON A/C: Insured / Std / NI / NA
Sp. Reading: 532911 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JDKN36U 805766681
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or _____
Brake: Inorder / Jammed / Leaked / Burnt or _____
Modi: Nil / SRIM / STD A/Rim or _____
Tyre Size: F: 195/65R15
R: 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front 6 mm Rear 6 mm
R/Bal. 6 mm L/Bal. 6 mm
L/Bal. 6 mm D.O.A. 20/06/24 D.O.I. 21/06/24
Survey held at SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: _____

2)

Transportation: _____

Report Format :

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

) S + RS, SI

) Photos

) Others

TOTAL

Case Details

Case Reference Number : TAX/06/21/2036
Type of Repair : Accident Repair
Vehicle Registration Number : SHD6128K

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-15207-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
Accident Date and Time : 20/06/2021 01:30 PM
Vehicle Age(In Months) : 67

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace	de
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	na
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give	X ^{ny}
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Check	?
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Not Give	X ^{ny}
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Not Give	X ^{ny}
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give	X ^{ny}
One Time Key In	Main			BUMPER GRILLE SUB-ASSY,LOWER	1	311.10	311.10	25.00	233.33	Replace	0	0	Not Give	X ^{ny}
One Time Key In	Main			FOG LAMP LH	1	280.10	280.10	10.00	252.09	Replace	0	0	Not Give	X ^{ny}
One Time Key In	Main			LENS & BODY,FR TURN LH	1	511.80	511.80	10.00	460.62	Replace	0	0	Not Give	X ^{ny}

Total Spare Part Cost 10,667.07

Surveyor Total 1,143.82

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 8,533.66

Final Sur Total 915.06

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, RADIATOR	1	122.80	122.80	25.00	92.10	Replace	0	0	Not Give	Xan
One Time Key In	Main			GRILLE, RADIATOR	1	310.60	310.60	25.00	232.95	Replace	0	0	Not Give	Xan
One Time Key In	Main			GRILLE, RADIATOR LOWER NO.2	1	94.60	94.60	25.00	70.95	Replace	0	0	Not Give	Xan
One Time Key In	Main			BUMPER LIP FRT	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	Xan
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Not Give	Xan
One Time Key In	Main			UNDER COVER CENTER	1	448.30	448.30	25.00	336.23	Replace	0	0	Not Give	Xan
One Time Key In	Main			UNDER COVER SIDE/LH	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Give	Xan
One Time Key In	Main			HOOD PANEL	1	748.10	748.10	25.00	561.08	Replace	0	0	Not Give	Xan
One Time Key In	Main			HOOD HINRE LH	1	55.90	55.90	25.00	41.92	Replace	0	0	Not Give	Xan
One Time Key In	Main			HOOD HINGE RH	1	55.90	55.90	25.00	41.92	Replace	0	0	Not Give	Xan
One Time Key In	Main			HEAD LAMP LH	1	945.20	945.20	10.00	850.68	Replace	0	0	Check	?
One Time Key In	Main			DOOR FRT/LH	1	894.40	894.40	25.00	670.80	Replace	1	0	Repair	R
One Time Key In	Main			FENDER LINER PAD, FR WHEEL LH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	Xan
One Time Key In	Main			FENDER APRON SUB FRT/LH	1	637.80	637.80	25.00	478.35	Replace	0	0	Check	\$?
One Time Key In	Main			WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0	Repair	Repair

Total Spare Part Cost 10,667.07

Lump Sum Discount (%) 20.00

Final Spare Part Cost 8,533.66

Surveyor Total 1,143.82

Lump Sum Dis (%) 20

Final Sur Total 915.06

ASSIGNMENT

Date:

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	Xsu
One Time Key In	Main			MOULDING BODY, LH	1	673.60	673.60	25.00	505.20	Replace	0	0	Not Give	Xnn
One Time Key In	Main			TIE ROD END LH	1	159.30	159.30	25.00	119.48	Replace	0	0	Check	fn?
One Time Key In	Main			WHEEL HUB FRT	1	549.70	549.70	25.00	412.28	Replace	0	0	Check	?
One Time Key In	Main			PILLAR, FR BODY, LH	1	363.10	363.10	25.00	272.33	Replace	0	0	Not Give	Xsu
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	na
One Time Key In	Main			HINGE LOWER LHF, DOOR	1	90.10	90.10	25.00	67.57	Replace	0	0	Not Give	Xnn
One Time Key In	Main			HINGE UPPER LHF, DOOR	1	80.50	80.50	25.00	60.38	Replace	0	0	Not Give	Xnn
One Time Key In	Main			CHECK ASSY, FR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Not Give	Xnn
One Time Key In	Main			QUARTER GLASS FRT/LH	1	234.90	234.90	25.00	176.18	Replace	0	0	Not Give	fn
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	Xnn
One Time Key In	Main			MIRROR ASSY,LH	1	1,224.90	1,224.90	25.00	918.68	Replace	0	0	Not Give	Xnn
One Time Key In	Main			MIRROR LAMP LH	1	65.30	65.30	10.00	58.77	Replace	0	0	Not Give	fn
One Time Key In	Main			COVER, OUTER MIRROR, LH	1	107.40	107.40	25.00	80.55	Replace	0	0	Not Give	Xnn
One Time Key In	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	542.55	Replace	buc

Total Spare Part Cost 10,667.07

Lump Sum Discount (%) 20.00

Final Spare Part Cost 8,533.66

Surveyor Total 1,143.82

Lump Sum Dis (%) 20

Final Sur Total 915.06

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace ▾	na /
One Time Key In	Main			FENDER PROTECTOR FRT/LH UPPER	1	46.10	46.10	25.00	34.58	Replace	0	0	Check ▾	?
One Time Key In	Main			PROTECTOR, FRONT FENDER SIDE PANEL LH	1	114.50	114.50	25.00	85.88	Replace	0	0	Check ▾	?
One Time Key In	Main			SEAL, FRONT FENDER TO COWL SIDE LH	1	15.20	15.20	25.00	11.40	Replace	0	0	Check ▾	?
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	1	128.77	Replace ▾	de /
Total Spare Part Cost									10,667.07	Surveyor Total 1,143.82				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									8,533.66	Final Sur Total 915.06				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	676.00	400	
Total:			676.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0	Xan
3	Main	TO REPSRAY FRONT HOOD	378.00	0	Xan
4	Main	TO RESPRAY FRONT DOOR LH	378.00	200	
5	Main	RESPRAY MIRROR COVER LH	180.00	0	Xan
6	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
7	Main	TO RESPRAY APRON PANEL LH	180.00	0	Xan
8	Main	TO RESPRAY RIM	180.00	50	
Total:			2,592.00	650.00	

No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
9	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	0	X17
10	Main	TO RESPRAY FRONT PILLAR LH	180.00	0	X17
Total:			2,592.00	650.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE AND REFIX WING MIRROR	120.00	0	X17
2	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	
4	Main	TO REPLACE SUNDRY PARTS	100.00	0	X17
5	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
6	Main	TO WASH AND VACUUM	60.00	0	X17
7	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	445.32	296.88	
Total:			1,045.32	416.88	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	8,533.66	915.06
Total Labour Cost	676.00	400.00
Total Spray Painting	2,592.00	650.00
Other	1,045.32	416.88
Overall Total	12,846.98	2,381.94
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	12,850.00	2,400.00
Surveyor Approved Amount		2,400.00
No of Repair Days*	6	5
Remarks	-	lump sum repair / after paint photo / if got damage on UNDERCARRIAGE portion . DAMAGE PARTS PHOTO AND AFTER WHEEL ALIGNMENT REPORT required .
Surveyor Name		Rasul

Signature

Estimator Assessment(\$)

Surveyor Assessment(\$)



Save

Clear

Survey Date

21/06/2021

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 21/06/2021 13:24 (SGT)
Date of Accident 20/06/2021 21:30 (SGT)
Exact Location of Accident Jln Anggerek, Singapore
Additional Location Information JALAN ANGGEREK / JALAN RAYA
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHD6128K

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner SMRT TAXIS PTE LTD
Company Reg No 1XXXXX369K
Email Address AUOT-SVC-TARC@SMRT.COM.SG
Mobile Phone No (Phone) +65-68662671
Alternative Phone No (Office) +65-68662672

VEHICLE PARTICULARS

Manufacturer Toyota
Model Prius
Variant -
Exact purpose for which vehicle was being used at time of accident -
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Taxi
Transmission Auto
CC 1800

INSURANCE COMPANY

Name of Insurance Company MS First Capital Insurance Ltd
Type of Coverage ThirdParty
Fleet Policy Yes
Policy Number D-21097466MFSH
Cover Note Number -

DRIVER

Name of Driver MUHAMAD HAIRI BIN RIPIN
NRIC No SXXXX459E

Date of Birth	09/01/1976
Occupation	Outdoor
Date Of Driving Pass	12/08/1998
Driving experience	22 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-68662672
Alt. Phone Number	-
Email Address	AUTO-SVC-TARC@SMRT.COM.SG
Address	11
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	MOHAMAD SUHIAMI BIN MOHAMED ELIAS
Gender	Male

PASSENGER 2

Name	UNKNOWN
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS TRAVELLING ALONG JALAN ANGGEREK WITH 2 PASSENGERS (MALAY COUPLE) ON BOARD. SUDDENLY A LORRY GBK220A CAME OUT OF JALAN RAYA WITHOUT STOPPING AT THE STOP LINE AND COLLIDED ONTO THE LEFT FRONT PORTION OF MY TAXI.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE TOO BIG
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBK220A
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	ISLAM MD AMINUL
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

 21/06/2021
Driver's Signature (If driver is not the policyholder) / Date & Time

 21/6/2021
Witnessed by Reporting Centre Personnel

Sketch Plan



of the Accident

We declare the foregoing particulars are true in every respect.



Hi 21/06/2021

Mr 21/6/2021

Owner ID Type:	Company
Owner ID:	369K
Vehicle No.:	SHD6128K
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Jun 2021
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2015
Engine No.:	2ZR6551643
Chassis No.:	JTDKN36U805766681
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$29,508.00
Original Registration Date:	06 Nov 2015
First Registration Date:	06 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Nov 2023
PARF Rebate Amount:	\$3,500.00
COE Expiry Date:	05 Nov 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$45,267.00
COE Rebate Amount:	\$13,433.00
Total Rebate Amount:	\$16,933.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 21 Jun 2021

OK

Maroon