


Section A - Accident Details

Registration Number	SHD6128K
Case Reference Number	TAX/06/21/2036
Registration Date	6/11/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	MUHAMAD HAIRI BIN RIPIN
Type of Accident	Side Swipe
Accident Date and Time	20/6/2021 9:30 PM
Accident Reported Date and Time	21/6/2021 11:02 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24111323
Special Instruction to ARC, if any	TP/DRIVE IN/ LEFT FRONT PORTION
Prepared Date and Time	21/6/2021 1:16 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$400.00
Total Spray Cost	\$2,592.00	\$650.00
Total Spare Part Cost	\$9,214.20	\$1,595.62
Total Other Cost	\$1,045.32	\$416.88
TOTAL COST	\$13,527.52	\$3,062.50
Lump Sum Total	\$13,550.00	\$3,050.00 (L/S)
Number of Repair Days	6.0	5.0
Prepared / Adjusted By	Ang Bang Kien	RASUL (LKK) / AIG
ARC / Surveyor Sign Off Date	25/06/2021 10:32 AM	24/06/2021 5:09 PM
Signature		
Remarks	Total number of repair days = 5 days. SUP = 0 day.	lump sum repair / after paint photo / if got damage on UNDERCARRIAGE portion . DAMAGE PARTS PHOTO AND AFTER WHEEL ALIGNMENT REPORT required .

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2107-0129	Invoice Number	
Quotation Date	13.07.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$676.00	\$400.00
Total Labour	\$676.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT PILLAR LH	\$180.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
TO RESPRAY RIM	\$180.00	\$50.00
TO RESPRAY APRON PANEL LH	\$180.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
RESPRAY MIRROR COVER LH	\$180.00	\$0.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO REPSRAY FRONT HOOD	\$378.00	\$0.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$2,592.00	\$650.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$445.32	\$296.88
Total Other Costs	\$1,045.32	\$416.88

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		53410-47070	HOOD HINGE RH	0.00	\$55.90	0.00	\$0.00	Replace	Not Given
		81170-47500	HEAD LAMP LH	0.00	\$945.20	0.00	\$0.00	Replace	Check
		67002-47070	DOOR FRT/LH	1.00	\$894.40	100.00	\$0.00	Replace	Repair
		53852-47020	FENDER LINER PAD, FR WHEEL. LH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given
		53702-47050	FENDER APRON SUB FRT/LH	0.00	\$637.80	0.00	\$0.00	Replace	Check
		42611-47140	WHEEL DISC. FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given

XNN
XSVR
R
XNN
XSVR
R
XSVR

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/07/2021

User ID : PohSuan

		75852-47900	MOULDING BODY, LH	0.00	\$673.60	0.00	\$0.00	Replace	Not Given	X NN
		45047-49165	TIE ROD END LH	0.00	\$159.30	0.00	\$0.00	Replace	Check	X NN
		43550-47011	WHEEL HUB FRT	0.00	\$549.70	0.00	\$0.00	Replace	Check	X SVR
		53876-47030	FENDER LINER FRT/LH	1.00	\$171.70	25.00	\$128.78	Replace	Replace	√ DE
		53867-47030	SEAL, FRONT FENDER TO COWL SIDE LH	0.00	\$15.20	0.00	\$0.00	Replace	Check	X SVR
		53828-47060	PROTECTOR, FRONT FENDER SIDE PANEL LH	0.00	\$114.50	0.00	\$0.00	Replace	Check	X SVR
		53826-47010	FENDER PROTECTOR FRT/LH UPPER	0.00	\$46.10	0.00	\$0.00	Replace	Check	X SVR
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	√ NEC
		53802-47050	FENDER FRT/LH	1.00	\$723.40	25.00	\$542.55	Replace	Replace	√ BUC
		87945-74010	COVER, OUTER MIRROR, LH	0.00	\$107.40	0.00	\$0.00	Replace	Not Given	X NN
		81740-52040	MIRROR LAMP LH	0.00	\$65.30	0.00	\$0.00	Replace	Not Given	X NN
		87940-47310	MIRROR ASSY, LH	0.00	\$1,224.90	0.00	\$0.00	Replace	Not Given	X NN
			SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X NN
		62120-47021	QUARTER GLASS FRT/LH	0.00	\$234.90	0.00	\$0.00	Replace	Not Given	X NN
		68610-47021	CHECK ASSY, FR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given	X NN
		68720-15151	HINGE UPPER LHF, DOOR	0.00	\$80.50	0.00	\$0.00	Replace	Not Given	X NN
		68740-12120	HINGE LOWER LHF, DOOR	0.00	\$90.10	0.00	\$0.00	Replace	Not Given	X NN
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	√ NEC
		61132-47030	PILLAR, FR BODY, LH	0.00	\$363.10	0.00	\$0.00	Replace	Not Given	X NN
		53420-47070	HOOD HINRE LH	0.00	\$55.90	0.00	\$0.00	Replace	Not Given	X NN
		53301-47060	HOOD PANEL	0.00	\$748.10	0.00	\$0.00	Replace	Not Given	X NN
		51444-12050	UNDER COVER SIDE/LH	0.00	\$46.10	0.00	\$0.00	Replace	Not Given	X NN
		51410-12105	UNDER COVER CENTER	0.00	\$448.30	0.00	\$0.00	Replace	Not Given	X NN
		52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Not Given	X NN
		76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	X NN
		53113 - 47040	GRILLE, RADIATOR LOWER NO.2	0.00	\$94.60	0.00	\$0.00	Replace	Not Given	X NN
		53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Not Given	X NN
		53289-47032	COVER, RADIATOR	0.00	\$122.80	0.00	\$0.00	Replace	Not Given	X NN
		81521-47050	LENS & BODY,FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given	X NN
		81220-12230	FOG LAMP LH	0.00	\$280.10	0.00	\$0.00	Replace	Not Given	X NN
		53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Not Given	X NN
		57014-47030	ARM SUB-ASSY,FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	X NN
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Not Given	X NN
		52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Not Given	X NN
		52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Check	X SVR
		52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given	X NN
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace	√ NEC
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace	√ DE
Total					\$13,773.15		\$1,143.84			

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/07/2021

User ID : PohSuan

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		81170-47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace
Total					945.20		\$850.68		

√ CRA

1,994.52
 -20%
 1595.62
 400.00
 1066.88
 3,062.50

L/S \$3,050/-

