



Exceptional Journeys

Surveyor : STEVE LKK
Claim : TP CHINA TAIPING
DOA : 21.06.2021
Emailed : 15.09.2021, 10am
Date survey : 01.07.2021

VEHICLE NO : SKK 1986 K
MODEL : CITROEN DS 7 CROSSBACK 180
WIP : 16642

Material	:	\$	<u>7,449.00</u>
Labour	:	\$	<u>5,045.00</u>
Sub-Total	:	\$	<u>12,494.00</u>
	:		<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>12,494.00</u>
GST 7%	:	\$	<u>874.58</u>
Grand Total	:	\$	<u>13,368.58</u>
Finalise By/Date	:		<u>LOI / 15/09/2021</u>

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☒ REPAIR TOOK 8 WORKING DAYS + 2 Days (1) Weekends
+ 0 Days (0) Public holiday
TOTAL DAYS REPAIR TOOK = 10

☒ TP claim GBJ 2687 D

☒ Claim GIA / LTA fee \$2.00

☒ Claim Loss of ☐ Use / ☒ Rental

☒ Claim Medical Fee / Others \$74.90

☐ Third Party Report -

PRO-FORMA INVOICE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address				Owner Name & Vehicle Info				
FRESHMART SINGAPORE PTE LTD				Cust No/Name	FCV01969/ FRESHMART SINGAPORE PTE LTD			
204 PANDAN LOOP				Reg No/Reg Date	SKK1986K / 17/09/2020			
SINGAPORE 128394				Date In/Mileage	18/08/2021/ 16185			
Contact No Mobile: 96195250				Chassis/Package	VR1J45GFRKY027058			
				Engine No	10FKA72526574			
				Make/Model	CIT/DS 7 CROSSBACK 180 PERFORMANCE LINE			
				Colour/Trim	F3M ROUGE ULTIMATE / 56F DS PERFORMANCE			
								
Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No		
CTP00073	Cash	13/09/2021/ 14:47	TLK	260 / AiTing	16642	0		
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, TAILGATE, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 1520.00
E PNT88000 REMOVE & INSTALL TAILGATE GLASS AND CONDUCT WATER LEAK TEST								✓ 300.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR TO FACILITATE REPAIR								✓ 120.00
E PNT88000 REMOVE & INSTALL TAILGATE TRIMS AND REAR COMPARTMENT TRIMS TO FACILITATE REPAIR								✓ 280.00
E PNT98000 RESPRAY ON REAR BUMPER, TAILGATE, LH REAR FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 1650.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM								✓ 50.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								✓ 380.00
M SUNDRY SUPPLY C & C LOGO								✓ 40.00
M SUNDRY APPLY SEALANT ON TAILGATE GLASS								✓ 80.00
M SUNDRY SUNDRIES								✓ 20.00
E PNT88000 REPAIR ON REAR END PANEL								380.00
E PNT98000 RESPRAY ON REAR END PANEL								225.00
X REAR BUMPER					1.00	✓ 1518.00	0.00	1518.00
X RECESS DOOR					1.00	✓ 74.00	0.00	74.00
X BUMPER MOULDING LH					1.00	✓ 717.00	0.00	717.00
X BUMPER MOULDING					1.00	✓ 255.00	0.00	255.00
X BUMPER ABSORBER					1.00	? 533.00	0.00	533.00

Payment should be made strictly by NETS, credit cards or PayNow (via QR code or UEN) only. Thank you.
 Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
FRESHMART SINGAPORE PTE LTD		Cust No/Name	FCV01969/ FRESHMART SINGAPORE PTE LTD
204 PANDAN LOOP		Reg No/Reg Date	SKK1986K / 17/09/2020
SINGAPORE 128394		Date In/Mileage	18/08/2021/ 16185
Contact No	Mobile: 96195250	Chassis/Package	VR1J45GFRKY027058
		Engine No	10FKA72526574
		Make/Model	CIT/DS 7 CROSSBACK 180 PERFORMANCE LINE
		Colour/Trim	F3M ROUGE ULTIMATE / 56F DS PERFORMANCE

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
CTP00073	Cash	13/09/2021/ 14:47	TLK	260 / AiTing	16642	0

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X LOW RR PAN FIX	1.00	✓ 152.00	0.00	152.00
X FIXING STUD	1.00	✓ 32.00	0.00	32.00
X TAILGATE A PEINDRE	1.00	✓ 3101.00	0.00	3101.00
X TAILGATE FIX	1.00	✓ 185.00	0.00	185.00
X BADGE	1.00	✓ 61.00	0.00	61.00
X BADGE	1.00	✓ 59.00	0.00	59.00
X SENSOR	1.00	✓ 192.00	0.00	192.00
X WING MOULDING LH	1.00	✓ 249.00	0.00	249.00
X TAIL-LIGHT LH	1.00	✓ 204.00	0.00	204.00
X BADGE	1.00	✓ 117.00	0.00	117.00

Z TEXT
 TP CLAIM CHINA TAIPING GBJ2687D
 DOA : 21.06.21
 SURVEYOR STEVE LKK 01.07.21
 REPAIR 6D+2D=8D

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	7,449.00	Nett	12,494.00
Labour	4,905.00	7% GST on	874.58
Standard Menu	0.00		
Specialist Job	0.00	Total Payable	13,368.58
Diagnostics Job	0.00	Paid	0.00
Sundry/Others	140.00	Total Due	13,368.58
Total(w/o GST)	12,494.00		

Payment should be made strictly by NETS, credit cards or PayNow (via QR code or UEN) only. Thank you.
Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : **CHINA TAIPING**


Supplementary Parts For Registration No.: **SKK 1986 K**

<u>Labour</u>		<u>Cost (\$)</u>
1	Repair rear end panel	380.00 ✓
2	Respray rear end panel	225.00 ✓

Total Labour		605.00
Taxable amount		605.00
7% GST		42.35

Grand total		<u>\$ 647.35</u>

Thank You.
Yours faithfully


LOI AI TING
Senior Officer-Admin
CITROEN SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240