

# 趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd  
  
  
Accident Date : 08.06.2021

Policy No: Third Party  
  
Date: 21.06.2021

Specialised in Car Painting, Welding,  
Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts
	Estimate Cost Of Repair To "Mercedes C180" Reg. No. SKF593DX Claiming Against Your Insured Reg. No. SKS2717Y		
1pc	Rear Bumper		CM 1,150.00 ✓
14pcs	Rear Bumper Clips	9.00	126.00 ✓
2pcs	Rear Bumper Chrome Mouldings	245.00	490.00 ✓
1pc	Rear Bumper Center Chrome Moulding		155.00 ✓
1pc	Rear Bumper Corner Retainer		56.00 X
1pc	Rear Bumper Reinforcement		550.00 X
1pc	Rear Bumper Beam (Plastic)		380.00 X
1pc	Rear Bumper Core LH		115.00 X
1pc	Rear Door Chrome Moulding LH		140.00 ✓
1pc	Front Door Chrome Moulding LH		140.00 ✓
1pc	Rear Wheel Rim		595.00 ✓
	Less 10%		3,897.00
			389.70
			3,507.30
	Rear Bumper Distance Sensor LH		285.00 SN X
	To Conduct Computerize Wheel Alignment Test		80.00 60/
	Labour Charge - Panel Beating, Repairing Of N/S Front Door, Rear Door, Rear Fender and Parts Replacement		550.00 350/
	To Respray Affected Areas		800/
			1,200.00
		Total :	5,622.30

NOT Authorized  
L/Rap &  
Resurvey After Repair

LKK Auto Consultants hence notify  
the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: