

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

Estimate Quotation

Quotation No	Jun 002/2021
Date	22/6/2021
Vehicle No	SLV6191J
Make / Model	Honda Vezel

Hui Zhen

2011230840

To: Auto & General Insurance (Singapore) Pte Ltd

Address: 190 Clemenceau Avenue #03-01 Singapore Shopping Centre Singapore 239924

Qty	DESCRIPTION	UNIT	Amount
1 pc	rear bumper Distorted		\$ ✓ 645.00
2 pcs	rear bumper side retainer <i>na</i>	\$ 55.00	\$ ✓ 110.00
1 set	rear bumper reverse sensor <i>Def</i>		\$ ✓ 200.00
1 pc	n/s rear fender <i>Reis</i>		\$ + 1,235.00
2 pcs	rear fender arch garnish <i>Del</i>		\$ 198 252.00
1 set	n/s rear fender arch garnish clip <i>na</i>		\$ ✓ 30.00
2 pcs	rear bumper side garnish <i>LH Del</i>	\$ 275.00	\$ 195 550.00
1 set	rear bumper side garnish clip <i>na</i>		\$ 15 30.00
2 pcs	taillamp <i>Cracked</i>	\$ 595.00	\$ 964 1,190.00
2 pcs	tailgate reflector <i>LH RH Cracked</i>	\$ 348.00	\$ ✓ 696.00
2 pcs	rear bumper reflector <i>RH Cracked</i>	\$ 195.00	\$ 195 390.00
1 pc	tailgate Distorted		\$ 1100 1,450.00
1 pc	tailgate inner lock <i>Scanned</i>		\$ 247 326.00
1 pc	tailgate inner lock catch <i>na</i>		\$ ✓ 355.00
1 pc	tailgate w/strip <i>2x</i>		\$ 188 358.00
1 pc	tailgate inner garnish <i>Cracked</i>		\$ 285 367.00
1 set	tailgate inner garnish clip <i>na</i>		\$ ✓ 30.00
1 pc	tailgate glass sealant <i>na</i>		\$ 60 80.00
1 pc	rear end panel <i>Distorted</i>		\$ ✓ 515.00
1 pc	rear end panel top garnish clip <i>na</i>		\$ 10 30.00
1 pc	rear end panel garnish <i>Del</i>		\$ ✓ 117.00
1 pc	tailgate "VEZEL" emblem <i>na</i>		\$ 55 78.00
1 pc	tailgate "H" emblem <i>na</i>		\$ + 48.00
1 pc	spare tyre compartment tray (sponge) <i>Cracked</i>		\$ ✓ 287.00
1 pc	spare tyre compartment panel <i>Paper</i>		\$ + 835.00
1 pc	rear splash shield <i>na</i>		\$ ✓ 165.00
1 pc	rear number plate <i>Not na</i>		\$ + 60.00
1 pc	rear compartment top board <i>Del</i>		\$ ✓ 249.00
1 pc	tailgate wiper motor <i>Not na</i>		\$ + 247.00
1 pc	tailgate reverse camera <i>na</i>		\$ + 350.00
1 pc	exhaust silencer <i>Not na Best</i>		\$ 7330 685.00
2 pcs	rear fender inner shield <i>na</i>		\$ + 125.00
1 pc	tailgate outer garnish <i>na</i>		\$ + 476.00
1 pc	tailgate inner handle cover <i>na</i>		\$ + 33.00
1 pc	antenna <i>Cracked</i>		\$ 5864 135.00

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

	Labour Charge		
1	to dismantle damaged parts, panel beat, repair		\$ 1000. 1200
2	to putty and spray painting on affected area		\$ 700.00
3	anti rust		\$ 900 1000.00
4	wiring check		\$ 80 100.00
6	remove and replace fuel tank		\$ 30 50.00
7	check and adjust wheel alignment		\$ x 80.00
8	R&R w/screen glass		\$ x 120.00
9	transfer tailgate fittings	2320	\$ 120 150.00
10	cushion seat, roof lining, carpet etc		\$ 80.00
11	reverse sensor damaged		\$ 60 250.00
			\$ 50 80.00
Subtotal:			\$ 14,464.00

BEST SOLUTION AUTOCARE PTE LTD

Authorised Signature

Adrian L
h/s 24/06/21.

06 Days.

Supplementary : 68

total : 8252

h/s : 6.6K.

6.6K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Printed:

Date:

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

Supplementary Quotation

Quotation No	Jun 002/2021
Date	22/6/2021
Vehicle No	SLV6191J
Make / Model	Honda Vezel

To: Auto & General Insurance (Singapore) Pte Ltd

Add res: 190 Clemenceau Avenue #03-01 Singapore Shopping Centre Singapore 239924

Qty	DESCRIPTION	UNIT	Amount
1 pc	Items Buzzer <i>cracked.</i>		\$ <i>85</i> 157.00
Subtotal:			\$ 157.00

BEST SOLUTION AUTOCARE PTE LTD

Authorised Signature

85
Supplementary: 68