

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21006915/T1UCE2

Date: 13/10/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00188402000
Claimant Vehicle No : SFX1A **Insured Vehicle No :** SLH208J
Date of Loss: 13/06/2021 Nature of Claim: TP Claim No: SNM21D203352/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFX1A**
Make & Model: MERCEDES-BENZ S300L, 3.0 (A) Engine No: 27294631356943
Reg. Date: 16/12/2009 (Man. Year: 2009) Chassis No: WDD2211542A303205
Colour: Black Odometer: 118049 km
Engine Capacity: 2997 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/45 R18 Rear Tyre Size: 255/45 R18
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,490.50	12,718.75	4,771.75	27.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,540.00	1,580.00	960.00	37.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,030.50	14,298.75	5,731.75	28.62
Approved Total (Overridden) (S\$)		11,400.00		
(S\$)	20,030.50	11,400.00	8,630.50	43.09
+ GST 7.00/7.00% (S\$)	1,402.14	798.00	604.14	43.09
Nett Amount (S\$)	21,432.64	12,198.00	9,234.64	43.09

INSPECTION

Date of Assignment: 22/06/2021
Date Inspected: 24/06/2021 Inspected At: Em-1 Auto Pte Ltd (HQ)
Blk 8 Sin Ming Industrial Estate Sector C, #01-68
Singapore 575643
Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Oct 2021)
Parts:	143	MERCEDES-BENZ S300L 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFX1A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR ALUMINIUM RH	Bent	6,564.00 FL	*5,891.95 FL
2	1		*FRONT DOOR LOCK RH	Not Necessary	1,592.00 FL	*- FL
3	1		*FRONT DOOR OUTER CHROME MOULDING RH	Not Necessary	351.00 FL	*- FL
4	1		*FRONT DOOR CHROME PROTECTOR RH	Cut	172.00 FL	*172.00 FL
5	18		*FRONT DOOR REGUALTOR BOARD RIVET RH	Necessary	90.00 FL	*90.00 FL
6	1		*FRONT DOOR WEATHERSTRIP RH	Necessary	376.00 FL	*376.00 FL
7	1		*FRONT DOOR BOTTOM RUBBER RH	Necessary	92.00 FL	*92.00 FL
8	1		*REAR DOOR ALUMINIUM RH	Bent	7,323.00 FL	*6,573.00 FL
9	1		*REAR DOOR OUTER CHROME MOULDING RH	Not Necessary	462.00 FL	*- FL
10	1		*REAR DOOR FRAME TOP CHROME MOULDING RH	Not Necessary	371.00 FL	*- FL
11	1		*REAR DOOR QUARTER GLASS RUBBER RH	Necessary	219.00 FL	*219.00 FL
12	1		*REAR DOOR WEATHERSTRIP RH	Necessary	361.00 FL	*361.00 FL
13	1		*REAR DOOR BOTTOM RUBBER RH	Necessary	92.00 FL	*92.00 FL
14	1		*REAR DOOR CHROME PROTECTOR RH	Cut	175.00 FL	*175.00 FL
15	18		*REAR DOOR REGULATOR BAORD RIVET RH	Necessary	90.00 FL	*90.00 FL
16	1		*REAR SPORT RIM RH	Repair	800.00 FS	*- FS
17	1		*FRONT DOOR FRAME TOP CHROME MOULDING RH	Not Necessary	215.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,345.00	14,131.95
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,854.50	1,413.20
Total Parts (\$\$)	17,490.50	12,718.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	600.00
2	SPRAY PAINTING	New	1,200.00	800.00
3	CHECK WIRING	New	40.00	30.00
4	ANTI RUST	New	100.00	30.00
5	REMOVE AND INSTALL BOTH DOOR PARTS	New	200.00	120.00
Gross Labour Cost (\$)			2,540.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >