

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Derrick Tan Ming Chye

Date: 24 Jun 2021

Preliminary Advice

Vehicle No	: SMK6498X	Accident Date	: 19/06/2021
Make	: HONDA VEZEL	Policy No.	: D20MPC0001554-01
Assignment Date	: 22/06/2021	Excess	: S\$0.00
Date of Inspection	: 23/06/2021	Est. Duration of Repair	: 9
Inspection At	: JEC AUTO SERVICE (HQ) 1 KAKI BUKIT AVENUE 6 #02-11, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,850.16
Revised Amount	:S\$	6,818.88
Check Items (Estimated)	:S\$	8,752.88
Total	:S\$	15,571.76

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	80,000.00
COE / PARF Rebate	:S\$	34,113.00
Salvage Value	:S\$	
Margin for Repair	:S\$	45,887.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :