

ASS. REC. BY:

Tanjith

REF:

CS / ASM 21006918 / T, f, c

ASSIGNMENT

WE 2026 March

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$37K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKC 4152Y

Yr Regn:

2011 / Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Elantra 1.6 c.c 1591

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

143114

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KM HD41 CM C. 237567-

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

791111

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

23/6/21 @ 3:30pm

Survey held at

TSL Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt 2/3, 1/5, 4/10

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

finalise lump sum \$10,000, 10days

red: 32,189.54; 76%

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B. / C

Days Of Repair:

10

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SKC4152Y Hyundai Elantra

No	Qty	Parts Description	Estimated Parts Price	
1	1	Front bumper assy	\$ 1,482.00	inv ✓
2	1	Front bumper right bracket	\$ 83.00	x
3	1	Front bumper right retainer	\$ 84.00	de ✓
4	1	Front bumper lower grille	\$ 187.00	?
5	1	Front bumper reinforcement	\$ 393.00	bt ✓
6	1	Front bumper sponge	\$ 291.00	as ✓
7	1	Front bumper tow cover	\$ 87.00	de ✓
8	1	Front grille assy	\$ 380.00	?
9	1	Front grille emblem	\$ 128.00	?
10	1	Front bonnet assy	\$ 1,697.00	bt ✓
11	1	Front right wing mirror complete assy	\$ 595.00	de ✓
12	1	Front right fender	\$ 892.00	bt ✓
13	1	Front right fender inner cowl	\$ 255.00	de ✓
14	1	Front right HID headlamp	\$ 2,480.00	env ✓
15	1	Front right HID headlamp bracket	\$ 85.00	env ✓
16	1	Front right HID headlamp wire harness	\$ 450.00	x
17	1	Front right fog lamp	\$ 280.00	mis ✓
18	1	Front right fog lamp garnish	\$ 125.00	x
19	1	Front right door panel assy	\$ 1,297.00	bt ✓
20	1	Front right door outer handle	\$ 129.00	x
21	1	Front right door lock mechanism	\$ 178.00	x
22	1	Front right door regulator with motor	\$ 479.00	?
23	1	Front right door outer moulding	\$ 198.00	x
24	1	Front right door inner board	\$ 432.00	x
25	2	Front right door hinges	\$ 108.00	?
26	1	Front right door weatherstrip	\$ 188.00	na ✓
27	1	Front right door checker linkage	\$ 166.00	x
28	1	Front right sill panel	\$ 1,287.00	Rx
29	1	Front right lower arm	\$ 483.00	bt ✓
30	1	Front right suspension assy	\$ 964.00	?
31	1	Front right brake disc	\$ 283.00	x
32	1	Front right brake disc housing	\$ 78.00	x
33	1	Front right knuckle arm	\$ 465.00	bt ✓
34	1	Front right wheel hub bearing	\$ 292.00	bt ✓
35	1	Front right drive shaft	\$ 1,103.00	x
36	1	Front right stabilizer link	\$ 179.00	x
37	1	Front engine crossmember	\$ 1,800.00	x
38	1	Front power steering rack and pinion assy	\$ 2,400.00	x
39	1	Front horn	\$ 88.00	x
40	1	Front wiper tank	\$ 85.00	?
41	1	Front air duct assy	\$ 265.00	?

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SKC4152Y Hyundai Elantra

No	Qty	Parts Description	Estimated Parts Price
42	1	Front top support panel assy	\$ 893.00 } ?
43	1	Front lower support panel assy	\$ 897.00 }
44	1	Front left support panel side garnish	\$ 110.00 x
45	1	Front right support panel side garnish	\$ 110.00 ?
46	1	Air con condenser	\$ 1,150.00 \$?
47	1	Air con inlet pipe	\$ 250.00 x
48	1	Air con discharge pipe	\$ 250.00 x
49	1	Radiator assy	\$ 1,289.00 x
50	1	Radiator top hose	\$ 78.00 x
51	1	Radiator lower hose	\$ 78.00 x
52	1	Radiator fan complete assy	\$ 568.00 x
53	1	Radiator spare tank	\$ 87.00 x
54	1	Front wiper top garnish assy	\$ 435.00 x
			<u>\$ 29,116.00</u>
		less 20%	<u>\$ 5,823.20</u>
			<u>\$ 23,292.80</u>

Special Nett Items

1	10	Front bumper clips	\$ 60.00 30 per ✓
2	4	Front bumper lower grille clips	\$ 40.00 10
3	1	Front right aluminium rim	\$ 780.00 bt ✓
4	1	Front right tyre	\$ 350.00 ?
5	6	Front right fender inner cowling clips	\$ 45.00 20 per ✓
6	8	Front right door inner board clips	\$ 40.00 20
7	6	Front grille assy clips	\$ 30.00 15
8	4	Front left support panel side garnish clips	\$ 30.00 } 20
9	4	Front right support panel side garnish clips	\$ 30.00 }
10	1	Front air-con gas	\$ 100.00 ru ✓
11	2	Front radiator coolant	\$ 100.00 60
			<u>\$ 1,605.00</u>

Total parts **\$ 24,897.80**

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SKC4152Y Hyundai Elantra

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy	\$ 1,181.00 <i>de</i>
2	1	Rear bumper right bracket	\$ 63.00 <i>x</i>
3	1	Rear bumper right side retainer	\$ 64.00 <i>re</i>
4	1	Rear right door panel assy	\$ 1,278.00 <i>bt</i>
5	1	Rear right door outer handle	\$ 129.00 <i>x</i>
6	1	Rear right door lock mechanism	\$ 178.00 <i>x</i>
7	1	Rear right door regulator with motor	\$ 479.00 <i>?</i>
8	1	Rear right door outer moulding	\$ 198.00 <i>?</i>
9	1	Rear right door inner board	\$ 432.00 <i>x</i>
10	2	Rear right door hinges	\$ 108.00 <i>x</i>
11	1	Rear right door weatherstrip	\$ 188.00 <i>re</i>
12	1	Rear right door checker linkage	\$ 166.00 <i>x</i>
13	1	Rear right fender	\$ 1,699.00 <i>?</i>
14	1	Rear axle beam assy	\$ 1,883.00 <i>?</i>
15	1	Rear right shock absorber assy	\$ 685.00 <i>?</i>
16	1	Rear right wheel hub with bearing	\$ 208.00 <i>?</i>
17	1	Rear windscreen glass moulding	\$ 288.00 <i>?</i>
			<hr/>
			\$ 9,227.00
		less 20%	\$ 1,845.40
			<hr/>
			\$ 7,381.60

Special Nett Items

1	10	Rear bumper clips	\$ 60.00 <i>30</i>
2	1	Rear right aluminium rim	\$ 780.00 <i>cn</i>
3	1	Rear right tyre	\$ 200 350.00 <i>80% put</i>
4	1	Rear windscreen glass sealant	\$ 100.00 <i>x</i>
5	8	Rear right door inner board clips	\$ 40.00 <i>20</i>
6	1	Rear right fender sealant	\$ 100.00 <i>?</i>
			<hr/>
			\$ 1,430.00

Total parts

\$ 8,811.60

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SKC4152Y Hyundai Elantra

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front and front right affected area and replace front and front right damaged parts.	\$ 1,400.00 700.
2	To putty and spray painting front and front right portion.	\$ 1,400.00 1000.
3	To check wiring and focus front headlamp.	\$ 50.00 30.
4	To remove and install air con system to facilitate the repair and refill gas.	\$ 150.00 100
5	To remove and install cooling system to facilitate the repair and check for leakage.	\$ 150.00 x
6	To apply anti rust proofing to front and front right affected area.	\$ 140.00 30.
7	Labour for panel beating, cut, weld, straighten rear and rear right affected area and replace rear and rear right damaged parts.	\$ 1,400.00 700
8	To putty and spray painting rear and rear right portion.	\$ 1,400.00 600
9	To apply anti rust proofing to rear and rear right affected area.	\$ 140.00 30.
10	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00 x120
11	To remove and install front right undercarriage parts.	\$ 350.00 120
12	To remove and install rear right undercarriage parts.	\$ 350.00 120
13	To balance front right wheel.	\$ 50.00 30
14	To balance rear right wheel.	\$ 50.00 30.
15	To conduct wheel alignment.	\$ 120.00 80.
16	To synchronise front right wing mirror for function.	\$ 120.00 30
17	To remove and install front right door lock mechanism.	\$ 80.00 x
18	To remove and install rear right door lock mechanism.	\$ 80.00 x
19	To check front right and rear right door central locking for function.	\$ 80.00 x
20	To transfer front right door glass to new door.	\$ 80.00 x
21	To transfer rear right door glass to new door.	\$ 80.00 x
22	To remove and install front right door regulator with motor assy.	\$ 80.00 60
23	To remove and install rear right door regulator with motor assy.	\$ 80.00 60
24	Towing service.	\$ 100.00 60.
25	To remove and install rear fuel tank to facilitate the repair.	\$ 180.00 x
26	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 150.00 60
27	To remove and install rear bumper reverse sensor.	\$ 80.00 30.
Total labour :		\$ 8,480.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total parts : \$ 33,709.40
Total labour : \$ 8,480.00
Total repair cost : \$ 42,189.40

Taufik 97495749
10/8/21 @ 3:30pm
1/5 Resurvey after repair
taufik@lkkauto.
10-12 days.