

ASS. REC. BY:

Tanjith

REF:

CS / ASM 21006918 / T,tc

## ASSIGNMENT

WE 2026 March

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value:

\$37K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKC 4152Y

Yr Regn:

2011 / Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Elantra 1.6 c.c 1591

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

143114

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KM HD41 CM C. 237567-

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

791111

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

23/6/21 @ 330pm

Survey held at

TSL Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt 2/3, 1/5, 4/10

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B. / C

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

**TSL Auto Garage**  
**Blk 4 Joo Chiat Complex**  
**#12-1171 Joo Chiat Road**  
**Singapore 420004**

**SKC4152Y Hyundai Elantra**

|    |     |                                           | Estimated   |          |       |
|----|-----|-------------------------------------------|-------------|----------|-------|
|    |     |                                           | Parts Price |          |       |
| No | Qty | Parts Description                         |             |          |       |
| 1  | 1   | Front bumper assy                         | \$          | 1,482.00 | inv ✓ |
| 2  | 1   | Front bumper right bracket                | \$          | 83.00    | x     |
| 3  | 1   | Front bumper right retainer               | \$          | 84.00    | de ✓  |
| 4  | 1   | Front bumper lower grille                 | \$          | 187.00   | ?     |
| 5  | 1   | Front bumper reinforcement                | \$          | 393.00   | bt ✓  |
| 6  | 1   | Front bumper sponge                       | \$          | 291.00   | as ✓  |
| 7  | 1   | Front bumper tow cover                    | \$          | 87.00    | de ✓  |
| 8  | 1   | Front grille assy                         | \$          | 380.00   | ?     |
| 9  | 1   | Front grille emblem                       | \$          | 128.00   | ?     |
| 10 | 1   | Front bonnet assy                         | \$          | 1,697.00 | bt ✓  |
| 11 | 1   | Front right wing mirror complete assy     | \$          | 595.00   | de ✓  |
| 12 | 1   | Front right fender                        | \$          | 892.00   | bt ✓  |
| 13 | 1   | Front right fender inner cowl             | \$          | 255.00   | de ✓  |
| 14 | 1   | Front right HID headlamp                  | \$          | 2,480.00 | env ✓ |
| 15 | 1   | Front right HID headlamp bracket          | \$          | 85.00    | env ✓ |
| 16 | 1   | Front right HID headlamp wire harness     | \$          | 450.00   | x     |
| 17 | 1   | Front right fog lamp                      | \$          | 280.00   | mis ✓ |
| 18 | 1   | Front right fog lamp garnish              | \$          | 125.00   | x     |
| 19 | 1   | Front right door panel assy               | \$          | 1,297.00 | bt ✓  |
| 20 | 1   | Front right door outer handle             | \$          | 129.00   | x     |
| 21 | 1   | Front right door lock mechanism           | \$          | 178.00   | x     |
| 22 | 1   | Front right door regulator with motor     | \$          | 479.00   | ?     |
| 23 | 1   | Front right door outer moulding           | \$          | 198.00   | x     |
| 24 | 1   | Front right door inner board              | \$          | 432.00   | x     |
| 25 | 2   | Front right door hinges                   | \$          | 108.00   | ?     |
| 26 | 1   | Front right door weatherstrip             | \$          | 188.00   | na ✓  |
| 27 | 1   | Front right door checker linkage          | \$          | 166.00   | x     |
| 28 | 1   | Front right sill panel                    | \$          | 1,287.00 | Rx    |
| 29 | 1   | Front right lower arm                     | \$          | 483.00   | bt ✓  |
| 30 | 1   | Front right suspension assy               | \$          | 964.00   | ?     |
| 31 | 1   | Front right brake disc                    | \$          | 283.00   | x     |
| 32 | 1   | Front right brake disc housing            | \$          | 78.00    | x     |
| 33 | 1   | Front right knuckle arm                   | \$          | 465.00   | bt ✓  |
| 34 | 1   | Front right wheel hub bearing             | \$          | 292.00   | bt ✓  |
| 35 | 1   | Front right drive shaft                   | \$          | 1,103.00 | x     |
| 36 | 1   | Front right stabilizer link               | \$          | 179.00   | x     |
| 37 | 1   | Front engine crossmember                  | \$          | 1,800.00 | x     |
| 38 | 1   | Front power steering rack and pinion assy | \$          | 2,400.00 | x     |
| 39 | 1   | Front horn                                | \$          | 88.00    | x     |
| 40 | 1   | Front wiper tank                          | \$          | 85.00    | ?     |
| 41 | 1   | Front air duct assy                       | \$          | 265.00   | ?     |

**TSL Auto Garage**  
**Blk 4 Joo Chiat Complex**  
**#12-1171 Joo Chiat Road**  
**Singapore 420004**

**SKC4152Y Hyundai Elantra**

| No       | Qty | Parts Description                      | Estimated<br>Parts Price |
|----------|-----|----------------------------------------|--------------------------|
| 42       | 1   | Front top support panel assy           | \$ 893.00 } ?            |
| 43       | 1   | Front lower support panel assy         | \$ 897.00 }              |
| 44       | 1   | Front left support panel side garnish  | \$ 110.00 x              |
| 45       | 1   | Front right support panel side garnish | \$ 110.00 ?              |
| 46       | 1   | Air con condenser                      | \$ 1,150.00 \$ ?         |
| 47       | 1   | Air con inlet pipe                     | \$ 250.00 x              |
| 48       | 1   | Air con discharge pipe                 | \$ 250.00 x              |
| 49       | 1   | Radiator assy                          | \$ 1,289.00 x            |
| 50       | 1   | Radiator top hose                      | \$ 78.00 x               |
| 51       | 1   | Radiator lower hose                    | \$ 78.00 x               |
| 52       | 1   | Radiator fan complete assy             | \$ 568.00 x              |
| 53       | 1   | Radiator spare tank                    | \$ 87.00 x               |
| 54       | 1   | Front wiper top garnish assy           | \$ 435.00 x              |
|          |     |                                        | <hr/>                    |
|          |     |                                        | \$ 29,116.00             |
| less 20% |     |                                        | \$ 5,823.20              |
|          |     |                                        | <hr/>                    |
|          |     |                                        | \$ 23,292.80             |

Special Nett Items

|    |    |                                              |                   |
|----|----|----------------------------------------------|-------------------|
| 1  | 10 | Front bumper clips                           | \$ 60.00 30 one ✓ |
| 2  | 4  | Front bumper lower grille clips              | \$ 40.00 10       |
| 3  | 1  | Front right aluminium rim                    | \$ 780.00 bt ✓    |
| 4  | 1  | Front right tyre                             | \$ 350.00 ?       |
| 5  | 6  | Front right fender inner cowling clips       | \$ 45.00 20 one ✓ |
| 6  | 8  | Front right door inner board clips           | \$ 40.00 20       |
| 7  | 6  | Front grille assy clips                      | \$ 30.00 15       |
| 8  | 4  | Front left support panel side garnish clips  | \$ 30.00 } 20     |
| 9  | 4  | Front right support panel side garnish clips | \$ 30.00 }        |
| 10 | 1  | Front air-con gas                            | \$ 100.00 ru ✓    |
| 11 | 2  | Front radiator coolant                       | \$ 100.00 60      |
|    |    |                                              | <hr/>             |
|    |    |                                              | \$ 1,605.00       |

**Total parts** **\$ 24,897.80**

**TSL Auto Garage**  
**Blk 4 Joo Chiat Complex**  
**#12-1171 Joo Chiat Road**  
**Singapore 420004**

**SKC4152Y Hyundai Elantra**

| No | Qty | Parts Description                    | Estimated Parts Price |
|----|-----|--------------------------------------|-----------------------|
| 1  | 1   | Rear bumper assy                     | \$ 1,181.00 <i>de</i> |
| 2  | 1   | Rear bumper right bracket            | \$ 63.00 <i>x</i>     |
| 3  | 1   | Rear bumper right side retainer      | \$ 64.00 <i>re</i>    |
| 4  | 1   | Rear right door panel assy           | \$ 1,278.00 <i>bt</i> |
| 5  | 1   | Rear right door outer handle         | \$ 129.00 <i>x</i>    |
| 6  | 1   | Rear right door lock mechanism       | \$ 178.00 <i>x</i>    |
| 7  | 1   | Rear right door regulator with motor | \$ 479.00 <i>?</i>    |
| 8  | 1   | Rear right door outer moulding       | \$ 198.00 <i>?</i>    |
| 9  | 1   | Rear right door inner board          | \$ 432.00 <i>x</i>    |
| 10 | 2   | Rear right door hinges               | \$ 108.00 <i>x</i>    |
| 11 | 1   | Rear right door weatherstrip         | \$ 188.00 <i>re</i>   |
| 12 | 1   | Rear right door checker linkage      | \$ 166.00 <i>x</i>    |
| 13 | 1   | Rear right fender                    | \$ 1,699.00 <i>?</i>  |
| 14 | 1   | Rear axle beam assy                  | \$ 1,883.00 <i>?</i>  |
| 15 | 1   | Rear right shock absorber assy       | \$ 685.00 <i>?</i>    |
| 16 | 1   | Rear right wheel hub with bearing    | \$ 208.00 <i>?</i>    |
| 17 | 1   | Rear windscreen glass moulding       | \$ 288.00 <i>?</i>    |
|    |     |                                      | <hr/>                 |
|    |     |                                      | \$ 9,227.00           |
|    |     | less 20%                             | \$ 1,845.40           |
|    |     |                                      | <hr/>                 |
|    |     |                                      | \$ 7,381.60           |

Special Nett Items

|   |    |                                   |                                    |
|---|----|-----------------------------------|------------------------------------|
| 1 | 10 | Rear bumper clips                 | \$ 60.00 <i>30</i>                 |
| 2 | 1  | Rear right aluminium rim          | \$ 780.00 <i>cn</i>                |
| 3 | 1  | Rear right tyre                   | \$ 200 350.00 <i>80% punctured</i> |
| 4 | 1  | Rear windscreen glass sealant     | \$ 100.00 <i>x</i>                 |
| 5 | 8  | Rear right door inner board clips | \$ 40.00 <i>20</i>                 |
| 6 | 1  | Rear right fender sealant         | \$ 100.00 <i>?</i>                 |
|   |    |                                   | <hr/>                              |
|   |    |                                   | \$ 1,430.00                        |

**Total parts**

**\$ 8,811.60**

**TSL Auto Garage**  
**Blk 4 Joo Chiat Complex**  
**#12-1171 Joo Chiat Road**  
**Singapore 420004**

**SKC4152Y Hyundai Elantra**

| No                    | Description                                                                                                                          | Labour Charges     |
|-----------------------|--------------------------------------------------------------------------------------------------------------------------------------|--------------------|
| 1                     | Labour for panel beating, cut, weld, straighten front and front right affected area and replace front and front right damaged parts. | \$ 1,400.00 700.   |
| 2                     | To putty and spray painting front and front right portion.                                                                           | \$ 1,400.00 1000.  |
| 3                     | To check wiring and focus front headlamp.                                                                                            | \$ 50.00 30.       |
| 4                     | To remove and install air con system to facilitate the repair and refill gas.                                                        | \$ 150.00 100      |
| 5                     | To remove and install cooling system to facilitate the repair and check for leakage.                                                 | \$ 150.00 x        |
| 6                     | To apply anti rust proofing to front and front right affected area.                                                                  | \$ 140.00 30.      |
| 7                     | Labour for panel beating, cut, weld, straighten rear and rear right affected area and replace rear and rear right damaged parts.     | \$ 1,400.00 700    |
| 8                     | To putty and spray painting rear and rear right portion.                                                                             | \$ 1,400.00 600    |
| 9                     | To apply anti rust proofing to rear and rear right affected area.                                                                    | \$ 140.00 30.      |
| 10                    | To remove and install rear windscreen glass to facilitate the repair.                                                                | \$ 140.00 x120     |
| 11                    | To remove and install front right undercarriage parts.                                                                               | \$ 350.00 120      |
| 12                    | To remove and install rear right undercarriage parts.                                                                                | \$ 350.00 120      |
| 13                    | To balance front right wheel.                                                                                                        | \$ 50.00 30        |
| 14                    | To balance rear right wheel.                                                                                                         | \$ 50.00 30.       |
| 15                    | To conduct wheel alignment.                                                                                                          | \$ 120.00 80.      |
| 16                    | To synchronise front right wing mirror for function.                                                                                 | \$ 120.00 30       |
| 17                    | To remove and install front right door lock mechanism.                                                                               | \$ 80.00 x         |
| 18                    | To remove and install rear right door lock mechanism.                                                                                | \$ 80.00 x         |
| 19                    | To check front right and rear right door central locking for function.                                                               | \$ 80.00 x         |
| 20                    | To transfer front right door glass to new door.                                                                                      | \$ 80.00 x         |
| 21                    | To transfer rear right door glass to new door.                                                                                       | \$ 80.00 x         |
| 22                    | To remove and install front right door regulator with motor assy.                                                                    | \$ 80.00 60        |
| 23                    | To remove and install rear right door regulator with motor assy.                                                                     | \$ 80.00 60        |
| 24                    | Towing service.                                                                                                                      | \$ 100.00 60.      |
| 25                    | To remove and install rear fuel tank to facilitate the repair.                                                                       | \$ 180.00 x        |
| 26                    | To remove and install rear inner garnish and trim to facilitate the repair.                                                          | \$ 150.00 60       |
| 27                    | To remove and install rear bumper reverse sensor.                                                                                    | \$ 80.00 30.       |
| <b>Total labour :</b> |                                                                                                                                      | <b>\$ 8,480.00</b> |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**Total parts : \$ 33,709.40**

**Total labour : \$ 8,480.00**

**Total repair cost : \$ 42,189.40**

Taufik 97495749  
10/8/21 @ 3:30pm  
1/5 Resurvey after repair  
taufik@lkkauto  
10-12 days.