REPAIR ESTIMATE\*

VEHICLE NO SHC7623X

MAKE

.....

DATE 19/06/2021

**CHIANG /NTUC** 

MODEL	: HYUNDAI IONIQ G4		CHIANG /NTUC		1
Qty	Parts Description/ Labour	Туре	Unit Price	Amount	& ∩
	1FRONT BUMPER COVER			\$418.30	K
	1 FRONT BUMPER BRACKET RH			\$35.00	
	1 FRONT DAY LIGHT RH			\$642.50	XJU
	1FRONTSIDE GRILLE RH			\$186.90	1300
	1FRONT WHEEL CAP RH			\$189.50	
	1RH WING MIRROR			\$1,391.70	1
	1FENDER EMBLEM BLUE -DRIVE			\$26.60	4
	THE WOLK ENGLESS			\$2,890.50	
	20.00%			\$578.10	
	DISCOUNTED TOTAL			\$2,312.40	
	<b>DISCOUNT</b>				
					]
	Labarra Change				
	Labour Charge			\$700.00	325
	Panel Beating			\$600.00	250
	Spray Paint			\$90.00	XNA
	Reset wheel alignment			\$60.00	XNI
	Check lighting TOTAL LABOUR			\$1,450.00	1
	TOTAL DABOOK				1
	ESTIMATE TOTAL			\$3,762.40	1
	ESTIMATE TOTAL				1
	LKK Auto Consultants hence notify				
	the Repairer of the following:				
	<ul> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> </ul>				
	<ul> <li>Parts prices are subject to confirmation</li> </ul>				
	<ul> <li>Third party survey is on a "Without Prejudice" basis</li> </ul>				
1	No illegal modification(s) is allowed				
	<ul> <li>Supplementary item(s) must be resurveyed <u>and</u></li> <li>is subject to final approval from Insurance Company</li> </ul>				
	Acknowledged by Repairer	1			
	Signature:				
	Date:				
					-
	Date:  This is an initial estimate based on a visual inspection of the	ne above v	ehicle. The final repair (	quantum will	-

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZUKK 2111 /2021 1555 PIP 1 2 DAYD AFTER REPAR PHYTU