

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21006923/AGS3Q2**Date:** 17/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100507205
Claimant Vehicle No :	SCX73C	Insured Vehicle No :	SLN574U
Date of Loss:	18/06/2021	Nature of Claim:	TP
		Claim No:	7638393793SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCX73C	Engine No:	CHH090766
Make & Model:	AUDI TT, 2.0 TFSI (A)	Chassis No:	TRUZZZFV9F1015951
Reg. Date:	27/04/2016 (Man. Year: 2015)	Odometer:	65887 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,330.36	11,791.04	5,539.32	31.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,022.00	15,347.00	3,675.00	19.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	36,352.36	27,138.04	9,214.32	25.35
+ GST 7.00/7.00% (\$\$)	2,544.67	1,899.66	645.01	25.35
Nett Amount (\$\$)	38,897.03	29,037.70	9,859.33	25.35
+ Loss of Use (17.0 x S\$100.00/day) (\$\$)		1,700.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		30,739.70		

INSPECTION

Date of Assignment:	29/06/2021		
Date Inspected:	29/06/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	15.0 days		

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR SECTIONAL PART-LH	Distorted	6,536.00 FS	*5,228.80 FS
2	1		*REAR SIDE WINDOW LH	Necessary	472.00 FS	*377.60 FS
3	1		*PRIMER	Not Necessary	20.00 FS	*- FS
4	1		*REAR SILL TRIM STRIP -LH OUTER	Necessary	255.00 FS	*203.60 FS
5	1		*REAR WHEEL SPOILER -LH	Not Necessary	35.00 FS	*- FS
6	1		*MEMBER TRIM -LH	Deformed	699.00 FS	*551.20 FS
7	1		*MEMBER TRIM ATTACHMENT PART	Necessary	281.00 FS	*224.80 FS
8	1		*REAR MEMBER TRIM ADHESIVE TAPE	Necessary	44.00 FS	*44.00 FS
9	1		*REAR DOOR -LH	Dented	4,085.00 FS	*3,268.00 FS
10	1		*REAR DOOR SEAL -LH	Necessary	205.00 FS	*164.00 FS
11	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
12	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
13	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
14	1		*REAR DOOR ATTACHMENT	Not Necessary	105.00 FS	*- FS
15	1		*REAR DOOR CATCH -LH	Not Necessary	105.00 FS	*- FS
16	1		*INNER DOOR SEAL	Not Necessary	528.00 FS	*- FS
17	1		*REAR DOOR HANDLE -LH	Repair	374.00 FS	*- FS
18	1		*REAR DOOR HANDLE COVER CAP -LH	Repair	52.00 FS	*- FS
19	1		*REAR DOOR SLID VALVE-LH	Not Necessary	22.00 FS	*- FS
20	1		*REAR DOOR HANDLE SENSOR -LH	Not Necessary	228.00 FS	*- FS
21	1		*REAR DOOR HANDLE MOUNTING BAR LH	Not Necessary	162.00 FS	*- FS
22	1		*REAR DOOR LATCH CABLE -LH	Not Necessary	52.00 FS	*- FS
23	1		*AIRBAG STICKER	Necessary	24.00 FS	*19.04 FS
24	1		*WARNING STICKER	Necessary	29.00 FS	*22.48 FS
25	1		*ALUMINIUM POWER	Necessary	573.00 FS	*458.40 FS
26	1		*HARDENER	Necessary	210.00 FS	*168.00 FS
27	1		*ALUMINIUM PRIMER	Not Necessary	212.00 FS	*- FS
28	1		*REAR EPOXY ADHESIVE	Not Necessary	113.00 FS	*- FS
29	1		*STATIC MIXER	Not Necessary	8.00 FS	*- FS
30	1		*CLEANER BLOCK	Not Necessary	77.00 FS	*- FS
31	1		*REAR WHEEL LINER -LH	Not Necessary	240.00 FS	*- FS
32	1		*A/SELANT	Necessary	180.00 FS	*180.00 FS
33	1		*C WAX	Necessary	140.00 FS	*140.00 FS
34	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
35	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
36	1		*SUNDRIES	Necessary	500.00 FS	*101.76 FS
37	1		*COUNTERSUNK RIVET	Necessary	84.00 FS	*84.00 FS
38	1		*POP RIVET	Necessary	24.00 FS	*24.00 FS
39	1		*2-PACK EPOXY ADHESIVE	Necessary	180.80 FS	*180.80 FS
40	1		*STATIC MIXER	Necessary	23.36 FS	*23.36 FS
41	2		*TAIL LIGHT TRIM -LH/RH	Necessary	47.20 FS	*47.20 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **17,330.36** **11,791.04**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING LID CHECK FUNCTION	New	280.00	0.00
2	TO RENEW LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	300.00	300.00
3	TO INSTALL SOLAR FILM FOR 1/4 GLASS	New	400.00	400.00
4	TO CARRY OUT WATER SEEPAGE TEST ON 1/4 GLASS	New	200.00	150.00
5	TO REMOVE AND REINSTALL REAR WIRE HARNESS FOR LIGHT ,BATTERY MANAGER FUSE AND RELAY TRAYS ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
6	TO REMOVE AND TRANSFER LHS DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES CHECK FUNCTION	New	350.00	280.00
7	TO REMOVE AND REINSTALL REAR SEATS ,BACK REST HATTRAY ,ABCD PILLAR TRIMS ,LUGGAGE COMPARTMENTS TRIMS AND SEAT BELTS DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIR BAG ETC	New	1,400.00	1,400.00
8	TO SET UP AND PALCE VEHICLE IN ALUMINIUM REPAIR RECILITY	New	1,800.00	1,800.00
9	TO DISMANTLE AND REINSTALL REAR BUMPER .TO RENEW LHS DOOR AND LHS SILL PANEL TRIM .TO CUT OUT AN WELD LHS REAR FENDER .RE-ORGANIZE CRASH MANAGEMNET COMPONENTS REINSTALL ALL PARTS REMOVED	New	6,300.00	5,400.00
10	TO RESPRAY LHS REAR FENDER ,LHS DOOR ,LHS SILL PANEL TRIM ,LHS SILL PANEL ,DRAIN CHANNEL ROOF CHANNEL ,DOOR ENTRANCE AND REAR END PANELLING	New	5,500.00	3,125.00
11	TO CARRY OUT ALUMINIUM PRIMER WORKS ON AFFECTED PANELS	New	900.00	900.00
12	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			19,022.00	15,347.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >