

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0522/2021/TF
DATE : 24-Jun-21
WIP : 32223

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 25/6/2021

YOUR INSURED VEH NO : SLN 574 U

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. LOH HAK GUAN MARK
ADDRESS : 162 LENTOR LOOP
#02-02
SINGAPORE 789095
TELEPHONE : HP +65 97955548
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 10662775
VEHICLE NO : **SCX 73 C**
MODEL CODE : TT COUPE 2.0 TFSI
MODEL YEAR : 27/4/2016
ENGINE NO : CHH 090766
CHASSIS NO : TRUZZZFV9F1015951
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Jun-21
PLACE OF ACCIDENT : BAYFRONT AVE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCX 73 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING LID. CHECK FUNCTION.	S/N \$	280.00	X
2	TO RENEW LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N \$	300.00	✓
3	TO INSTALL SOLAR FILM FOR 1/4 GLASS	S/N \$	400.00	✓
4	TO CARRY OUT WATER SEEPAGE TEST ON 1/4 GLASS	S/N \$	200.00 150.	
5	TO REMOVE AND REINSTALL REAR WIRE HARNESS FOR LIGHT , BATTERY MANAGER , FUSE AND RELAY TRAYS , ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$	1,400.00	✓
6	TO REMOVE AND TRANSFER LHS DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. CHECK FUNCTION	S/N \$	350.00 280.	
SUB TOTAL LABOUR CHARGES		:	<u>\$ 2,930.00</u>	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCX 73 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND REINSTALL REAR SEATS , BACK REST , HAT TRAY , ABCD PILLAR TRIMS , LUGGAGE COMPARTMENTS TRIM AND SEAT BELTS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIR BAG ETC.	S/N \$ 1,400.00 ✓	
8	TO SET UP AND PALCE VEHICLE IN ALUMINIUM REPAIR FACILITY.	S/N \$ 1,800.00 ✓	
9	TO DISMANTLE AND REINSTALL REAR BUMPER. TO RENEW LHS DOOR AND LHS SILL PANEL TRIM. TO CUT OUT AN WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 6,300.00 3500	Fender 3.5 20
10	TO RESPRAY LHS REAR FENDER , LHS DOOR , LHS SILL PANEL TRIM , LHS SILL PANEL , DRAIN CHANNEL ,ROOF CHANNEL ,DOOR ENTRANCE AND REAR END PANELLING.	\$ 5,500.00 3125	Fender : 3.5 Door : 1 3500 Side Trim : 1 Handle 100 3125
11	TO CARRY OUT ALUMINIUM PRIMER WORKS ON AFFECTED PANELS.	S/N \$ 900.00 ✓	
12	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 19,022.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCX 73 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR SECTIONAL PART - LH <i>Pistonhd</i>	1	\$ 6,536.00	✓
2	REAR SIDE WINDOW - LH <i>nu</i>	1	\$ 472.00	✓
3	PRIMER <i>nu</i>	1	\$ 20.00	✓
4	REAR SILL TRIM STRIP - LH OUTER <i>nu</i>	1	\$ 255.00	✓
5	REAR WHEEL SPOILER - LH <i>nu</i>	1	\$ 35.00	x
6	MEMBER TRIM - LH <i>Dehd</i>	1	\$ 699.00	✓
7	MEMBER TRIM ATTACHEMENT PART <i>nu</i>	1	\$ 281.00	✓
8	REAR MEMBER TRIM ADHESIVE TAPE <i>nu</i>	1	TBC	✓
9	REAR DOOR - LH <i>Dehted</i>	1	\$ 4,085.00	✓
10	REAR DOOR SEAL - LH <i>nu</i>	1	\$ 205.00	✓
11	BONDING AGENT <i>?</i>	1	\$ 49.00	?
12	CLEANING SOLUTION <i>?</i>	1	\$ 68.00	?
13	APPLICATOR <i>?</i>	1	\$ 8.00	?
14	REAR DOOR ATTACHMENT <i>nu</i>	1	\$ 105.00	x
15	REAR DOOR CATCH - LH <i>?</i>	1	\$ 105.00	?
16	INNER DOOR SEAL <i>nu</i>	1	\$ 528.00	x.
17	REAR DOOR HANDLE - LH <i>Rjr</i>	1	\$ 374.00	+
18	REAR DOOR HANDLE COVER CAP - LH <i>Rjr</i>	1	\$ 52.00	+
19	REAR DOOR SLID VALVE - LH <i>3nu</i>	1	\$ 22.00	+
20	REAR DOOR HANDLE SENSOR - LH <i>3nu</i>	1	\$ 228.00	+
SUB TOTAL SPARE PARTS		:	\$ 14,127.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCX 73 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR DOOR HANDLE MOUNTING BAR - LH <i>new</i>	1	\$ 162.00	✓
22	REAR DOOR LATCH CABLE - LH <i>new</i>	1	\$ 52.00	✓
23	AIRBAG STICKER <i>} new</i>	1	\$ 24.00	✓
24	WARNING STICKER	1	\$ 29.00	✓
25	ALUMINIUM POWER	1	\$ 573.00	✓
26	HARDENER	1	\$ 210.00	✓
27	ALUMINIUM PRIMER	1	\$ 212.00	✓
28	REAR EPOXY ADHESIVE <i>} new</i>	1	\$ 113.00	✓
30	STATIC MIXER	1	\$ 8.00	✓
31	CLEANER BLOCK	1	\$ 77.00	✓
32	REAR WHEEL LINER - LH ?	1	\$ 240.00	?
33	A/SELANT <i>} new</i>	1	\$ 180.00	✓
34	C WAX	1	\$ 140.00	✓
35	STONE CHIP	1	\$ 180.00	✓
36	1/4 GLASS SEALANT <i>new</i>	1	\$ 100.00	✓
37	SUNDRIES ?	S/N	\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 16,927.00	
TOTAL LABOUR CHARGES		:	\$ 19,022.00	
GRAND TOTAL		:	\$ 35,949.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ling.*
SURVEYED DATE : *29/06/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *not Authorised, 13 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT