

PPE 5826

Towing	—	• 45	/
Towing to idar	—	• 45	/
Jay Fork	—	• 180SNB120	Labour
Handle Bar RH Hender Bar R	—	• 290	R/bb /
Handle Bar Hender Beleser	—	• 150	ant /
Brake lever	—	• 145	ant /
Mirror Mirror	—	• 130	ant /
Top Colling Top Colling	—	• 385	Ry
Head Light Headlight Right	—	• 685	ant /
Front Manguang mudguard	—	• 185	Ry
Signal Right R	—	• 145	ant /
Front Side Black cover	—	• 90	ant /
Side cover R	—	• 395	ant /
fender Sinder cover R	—	• 235	ant /
Side fender Sinder cover	—	• 125	ant /
Lower cover	—	• 195	ant /
Ruel Tank tank.	—	• 785	Ry

Footrest Rider			
Footless Rider	→	120	cut ✓
Brake pedal			
Brake Pender	→	125	dd ✓
Pillion Footrest			
Pilling Footless	→	98	dd ✓
Exhaust Pipe Assy			
Exc p/pi Assy	→	585	dd ✓
Exhaust pipe cover			
Exc p/pi cover x 2	→	85 + 95	dd ✓
Engine clutch cover repair			
Engn Cloth cover Repair	→	120	60
Labour	→	280	200
Spray	→	450	
		600	
		5726	
			260
			120
			<u>380</u>

Parts - 3791
 10% - 3411.90

Tanphi 97495749
 WP' 23/6/21e
 plp Resny new parts
 tanphi e (Mant's.com) * Subject to insurance approval
 4 days

3411.90
 380
 \$3791.90 #
 04days