

PPE 5826

Towing	— \$ 45 —
Towing to idar	— \$ 45 —
Jet Fork	— \$ 180 \$120 —
Handle Bar RH Header Bar R	— \$ 290 Right —
Handle Bar Balancer Header Balancer	— \$ 150 int —
Brake Lever	— \$ 145 int —
Mirror	— \$ 130 int —
Top Colling ^{Coupling}	— \$ 385 Rp —
Head ^{Headlight} Right	— \$ 685 int —
Front ^{midguard} Mangung	— \$ 185 Rp —
Signal Right R	— \$ 145 int —
Front Side Black cover	— \$ 98 int —
Side cover R	— \$ 395 int —
Sender cover R	— \$ 235 int —
Side sender cover	— \$ 125 int —
Lower cover	— \$ 195 int —
Fuel Tank	— \$ 785 Rp —

Footrest Rider	
Footless Rider	— 120 cut ✓
Brake pedal. Pender	— 125 dd ✓
Pillion Footrest. Pilling Footless	— 98 dd ✓
Exhaust Pipe Assy Exc ppi Assy	— 585 dd ✓
Exhaust pipe cover Exc ppi cover x 2	— 85 + 95 dd ✓
Engine clutch cover repair Engn Clutch cover Repair	120 60
labour	— 280 200
Spray	600 450
	5726

Tauphin 97495749
 - WP' 23/6/21e
 1/3 Resing after upi-
 tauphin e (Munitions)
 4 days