

REPAIR ESTIMATE*

20/06/21

1600

ef

MAKE :

MODEL **IONIQ G3**

CHIANG/CHINA

NA2 CLK
22/6/2021 1605
PIF
3 DAYS
CHECK ITEM PHOTO
BY PAINT PHOTO

Acknowledged by Repairer
Signature:
Date:

Workshops

205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717

Date/Time: 21.06.2021 16:16

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 4091071

JC NO.: 305474595


CUSTOMER		REGN NO.: SHA1643M	MILEAGE
VMS		MAKE : HYUNDAI	FUEL
CUSTOMER NO. 7010045		MODEL IONIQ(G2)	E.....1/2.....F
ADDRESS 383 SIN MING DRIVE		YR OF MANU. 02.07.2019	DATE/TIME IN 21.06.2021 11:00
Singapore SINGAPORE 575717		CHASSIS CODE KMHC851CVKU164510	TARGET DATE
65508755 (O)		COMPLETION DATE/TIME:	
(P)			
COUNT CARD NO.			

JOB DESCRIPTION

Accident Date: 20.06.2021

NATURE: 3P 20.06.2021

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY: _____		CUSTOMER'S SIGNATURE _____	
SERVICE ADVISOR _____			
Acknowledgement Slip		Exit Pass	
Vehicle No.: SHA1643M		SHA1643M	
Signature/Date _____		Name of Service Advisor _____	
To be returned to Service Reception upon collection		To be kept by Security Guard	