

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0380/2021/TF
DATE : 18-Jun-21
WIP : 31841

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/6/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR ONG ENG HOCK SIMON
ADDRESS : 20 JALAN HAJIJAH
#04-18
SINGAPORE 468726
TELEPHONE : HP +65 98211398
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800097216-02
VEHICLE NO : **SMD 3242 Z**
MODEL CODE : A4 SEDAN 2.0 TFSI S TRONIC
MODEL YEAR : 14/8/2018
ENGINE NO : CVK 064806
CHASSIS NO : WAUZZZF4XJN015523
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Jun-21
PLACE OF ACCIDENT : MARINE PARADE TOWARDS AMBER

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMD 3242 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AIS AND REAR LID KICK SENSOR. CHECK FUNCTION	S/N \$	360.00	✓
2	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILLITATE FENDER RENEWAL	S/N \$	600.00	X
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND LHS 1/4 GLASS	S/N \$	400.00	X
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN AND 1/4 GLASS	S/N \$	200.00	X
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER , FUSE AND RELAY TRAYS , ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	S/N \$	1,400.00	X
SUB TOTAL LABOUR CHARGES		:	\$ 2,960.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMD 3242 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO REMOVE AND REINSTALL REAR SEAT , BACK REST , HAT TRAY , ABCD PILLAR TRIMS , LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN ATRRAG. ETC	S/N \$ 1,400.00	X
7	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	S/N \$ 700.00	560 ✓
8	TO REMOVE AND RENEW LHS REAR WHEEL SUSPENSION ASSEMBLY .	S/N \$ 1,800.00	X.
9	TO DISMANTLE AND RENEW BUMPER , LHS REAR DOOR AND LHS FRONT DOOR. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL PARTS REMOVED	\$ 6,300.00	1750. ✓
10	TO RESPRAY REAR BUMPER , LHS REAR FENDER , LHS REAR DOOR , LHS FRONT DOOR. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. <i>Sill Panel</i>	\$ 6,250.00	2750. ✓
11	TO RENEW LHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	280 ✓
12	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 20,122.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 3242 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Dehd</i>	1	\$ 2,181.00	✓ 1744.8
2	REAR BUMPER GUIDE SECTION - LH <i>new</i>	1	\$ 44.00	✓
3	REAR SECTIONAL PART - LH <i>Rgr</i>	1	\$ 4,052.00	✓
4	REAR WINDSCREEN <i>} new</i>	1	\$ 1,154.00	✓
5	REAR 1/4 GLASS - LH <i>} new</i>	1	\$ 616.00	✓
6	REAR DOOR - LH <i>Dented</i>	1	\$ 3,192.00	✓ 2553.6
7	REAR DOOR OUTER SEAL - LH <i>new</i>	1	\$ 205.00	✓ 164
8	BONDING AGENT <i>?</i> NN	1	\$ 49.00	?
9	CLEANING SOLUTION <i>?</i> NN	1	\$ 68.00	?
10	APPLICATOR <i>?</i>	1	\$ 8.00	?
11	REAR DOOR SEALING STRIP <i>new</i>	1	\$ 17.00	✓
12	REAR DOOR ATTACHMENT PARTS <i>Not n</i>	1	TBC	✓
13	REAR DOOR CATCH - LH <i>?</i> DAMAGED	1	\$ 120.00	✓ 96
14	FRONT DOOR - LH <i>Dented</i>	1	\$ 3,192.00	✓ 2553.6
15	FRONT DOOR OUTER SEAL - LH <i>new</i>	1	\$ 205.00	✓ 164
16	BONDING AGENT <i>?</i> NN	1	\$ 49.00	?
17	CLEANING SOLUTION <i>?</i> NN	1	\$ 68.00	?
18	APPLICATOR <i>?</i> NN	1	\$ 8.00	?
19	BUNGS <i>new</i>	1	\$ 4.00	✓
20	FRONT DOOR ATTACHMENT PARTS - LH <i>Not n</i>	1	TBC	✓
SUB TOTAL SPARE PARTS		:	\$ 15,232.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 3242 Z

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT DOOR CATCH - LH ? NN	1	\$ 105.00	X	
22	REAR WHEEL HOUSING - LH Regis	1	\$ 240.00	+	
23	REAR WHEEL HOUSING ATTACHMENT PARTS xhe u	1	TBC	+	
24	REAR TAIL LIGHT - OUTER LH Lt	1	\$ 1,019.00	✓	815.2
25	REAR TAIL LIGHT TRIM - OUTER LH xhe u	1	\$ 30.00	+	913.60
26	REAR TYRE RIM - LH Lt	1	\$ 1,142.00	✓	
27	REAR WISHBONE - LH LOWER / UPPER / FRONT / REAR xhe u	4	\$ 1,985.00	+	
28	REAR TRACK ROD - LH xhe u	1	\$ 171.00	+	
29	REAR WHEEL BEARING HOUSING - LH 3 xhe u	1	\$ 990.00	+	
30	REAR WHEEL BEARING - LH	1	\$ 440.00	+	
31	REAR STONE CHIP GUARD - LH xhe u	1	\$ 45.00	+	
32	REAR ABSORBER - LH xhe u	1	\$ 301.00	+	
33	REAR BUMPER REFLECTOR xhe u	1	\$ 41.00	+	
34	REAR WINDSCREEN PRIMER ?	1	\$ 20.00	+	
35	1/4 GLASS SEALANT	S/N	\$ 100.00	+	
36	ACRYLIC SEALANT	S/N	\$ 180.00	+	
37	CAVITY WAX	S/N	\$ 140.00	+	
38	STONE CHIP TREATMENT	S/N	\$ 180.00	+	
39	METAL FILLER POWER	S/N	\$ 280.00	+	
40	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	+	
41	SUNDRIES ?	NEC	\$ 450.00	+	9.6
TOTAL SPARE PARTS			:	\$	23,291.00
TOTAL LABOUR CHARGES			:	\$	20,122.00
GRAND TOTAL			:	\$	43,413.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King.*
SURVEYED DATE : *22/06/21.*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *not Authorised , 07 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT