

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0380/2021/TF  
DATE : 18-Jun-21  
WIP : 31841

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/6/2021

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

Hi Adrian,

**7 days - ok - Jy - 8 Sep 21**

OWNER'S NAME : MR ONG ENG HOCK SIMON  
ADDRESS : 20 JALAN HAJIJAH  
#04-18  
SINGAPORE 468726  
TELEPHONE : HP +65 98211398  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 1800097216-02  
VEHICLE NO : **SMD 3242 Z**  
MODEL CODE : A4 SEDAN 2.0 TFSI S TRONIC  
MODEL YEAR : 14/08/2018  
ENGINE NO : CVK 064806  
CHASSIS NO : WAUZZZF4XJN015523  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 16-Jun-21  
PLACE OF ACCIDENT : MARINE PARADE TOWARDS AMBER

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMD 3242 Z**

| S/N                             | NATURE OF JOBS                                                                                                                                                                |        | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|---------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------------------|-------------------------------|
| 1                               | TO REMOVE AND REINSTALL REAR PARKING AIS AND REAR LID KICK SENSOR. CHECK FUNCTION                                                                                             | S/N \$ | 360.00               | \$ 360.00                     |
| 2                               | TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILLITATE FENDER RENEWAL                                                                                                      | S/N \$ | 600.00               |                               |
| 3                               | TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND LHS 1/4 GLASS                                                                                                                   | S/N \$ | 400.00               |                               |
| 4                               | TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN AND 1/4 GLASS                                                                                                             | S/N \$ | 200.00               |                               |
| 5                               | TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER , FUSE AND RELAY TRAYS , ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY. | S/N \$ | 1,400.00             |                               |
| <b>SUB TOTAL LABOUR CHARGES</b> |                                                                                                                                                                               | :      | <b>\$ 2,960.00</b>   | <b>\$ 360.00</b>              |

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

| S/N                         | NATURE OF JOBS                                                                                                                                                                        |            | ESTIMATED CHARGES   | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|---------------------|----------------------------|
|                             |                                                                                                                                                                                       | <i>c/f</i> |                     | \$ 360.00                  |
| 6                           | TO REMOVE AND REINSTALL REAR SEAT , BACK REST , HAT TRAY , ABCD PILLAR TRIMS , LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.                       | S/N        | \$ 1,400.00         |                            |
| 7                           | TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES                                                             | S/N        | \$ 700.00           | \$ 560.00                  |
| 8                           | TO REMOVE AND RENEW LHS REAR WHELL SUSPENSION ASSEMBLY .                                                                                                                              | S/N        | \$ 1,800.00         |                            |
| 9                           | TO DISMANTLE AND RENEW BUMPER , LHS REAR DOOR AND LHS FRONT DOOR. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL PARTS REMOVED.              |            | \$ 6,300.00         | \$ 1,750.00                |
| 10                          | TO RESPRAY REAR BUMPER , LHS REAR FENDER , LHS REAR DOOR , LHS FRONT DOOR. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. |            | \$ 6,250.00         | \$ 2,750.00                |
| 11                          | TO RENEW LHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.                                                                                                                         | S/N        | \$ 520.00           | \$ 280.00                  |
| 12                          | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                                                        | S/N        | \$ 192.00           | \$ 192.00                  |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                       | <b>:</b>   | <b>\$ 20,122.00</b> | <b>\$ 5,892.00</b>         |

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 3242 Z**

|                              |                                  |     | DAMAGED PARTS & PRICES |                    |
|------------------------------|----------------------------------|-----|------------------------|--------------------|
| S/N                          | PARTS DESCRIPTION                | QTY | S/NETT                 | REMARKS            |
| 1                            | REAR BUMPER                      | 1   | \$ 2,181.00            | \$ 1,744.80        |
| 2                            | REAR BUMPER GUIDE SECTION - LH   | 1   | \$ 44.00               |                    |
| 3                            | REAR SECTIONAL PART - LH         | 1   | \$ 4,052.00            |                    |
| 4                            | REAR WINDSCREEN                  | 1   | \$ 1,154.00            |                    |
| 5                            | REAR 1/4 GLASS - LH              | 1   | \$ 616.00              |                    |
| 6                            | REAR DOOR - LH                   | 1   | \$ 3,192.00            | \$ 2,553.60        |
| 7                            | REAR DOOR OUTER SEAL - LH        | 1   | \$ 205.00              | \$ 164.00          |
| 8                            | BONDING AGENT                    | 1   | \$ 49.00               |                    |
| 9                            | CLEANING SOLUTION                | 1   | \$ 68.00               |                    |
| 10                           | APPLICATOR                       | 1   | \$ 8.00                |                    |
| 11                           | REAR DOOR SEALING STRIP          | 1   | \$ 17.00               |                    |
| 12                           | REAR DOOR ATTACHMENT PARTS       | 1   | TBC                    |                    |
| 13                           | REAR DOOR CATCH - LH             | 1   | \$ 120.00              | \$ 96.00           |
| 14                           | FRONT DOOR - LH                  | 1   | \$ 3,192.00            | \$ 2,553.60        |
| 15                           | FRONT DOOR OUTER SEAL - LH       | 1   | \$ 205.00              | \$ 164.00          |
| 16                           | BONDING AGENT                    | 1   | \$ 49.00               |                    |
| 17                           | CLEANING SOLUTION                | 1   | \$ 68.00               |                    |
| 18                           | APPLICATOR                       | 1   | \$ 8.00                |                    |
| 19                           | BUNGS                            | 1   | \$ 4.00                |                    |
| 20                           | FRONT DOOR ATTACHMENT PARTS - LH | 1   | TBC                    |                    |
| <b>SUB TOTAL SPARE PARTS</b> |                                  | :   | <b>\$ 15,232.00</b>    | <b>\$ 7,276.00</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 3242 Z**

|                             |                                                 |            | DAMAGED PARTS & PRICES |         |                  |
|-----------------------------|-------------------------------------------------|------------|------------------------|---------|------------------|
| S/N                         | PARTS DESCRIPTION                               | QTY        | S/NETT                 | REMARKS |                  |
|                             |                                                 | <i>c/f</i> |                        | \$      | 7,276.00         |
| 21                          | FRONT DOOR CATCH - LH                           | 1          | \$ 105.00              |         |                  |
| 22                          | REAR WHEEL HOUSING - LH                         | 1          | \$ 240.00              |         |                  |
| 23                          | REAR WHEEL HOUSING ATTACHMENT PARTS             | 1          | TBC                    |         |                  |
| 24                          | REAR TAIL LIGHT - OUTER LH                      | 1          | \$ 1,019.00            | \$      | 815.20           |
| 25                          | REAR TAIL LIGHT TRIM - OUTER LH                 | 1          | \$ 30.00               |         |                  |
| 26                          | REAR TYRE RIM - LH                              | 1          | \$ 1,142.00            | \$      | 913.60           |
| 27                          | REAR WISHBONE - LH LOWER / UPPER / FRONT / REAR | 4          | \$ 1,985.00            |         |                  |
| 28                          | REAR TRACK ROD - LH                             | 1          | \$ 171.00              |         |                  |
| 29                          | REAR WHEEL BEARING HOUSING - LH                 | 1          | \$ 990.00              |         |                  |
| 30                          | REAR WHEEL BEARING - LH                         | 1          | \$ 440.00              |         |                  |
| 31                          | REAR STONE CHIP GUARD - LH                      | 1          | \$ 45.00               |         |                  |
| 32                          | REAR ABSORBER - LH                              | 1          | \$ 301.00              |         |                  |
| 33                          | REAR BUMPER REFLECTOR                           | 1          | \$ 41.00               |         |                  |
| 34                          | REAR WINDSCREEN PRIMER                          | 1          | \$ 20.00               |         |                  |
| 35                          | 1/4 GLASS SEALANT                               | S/N        | \$ 100.00              |         |                  |
| 36                          | ACRYLIC SEALANT                                 | S/N        | \$ 180.00              |         |                  |
| 37                          | CAVITY WAX                                      | S/N        | \$ 140.00              |         |                  |
| 38                          | STONE CHIP TREATMENT                            | S/N        | \$ 180.00              |         |                  |
| 39                          | METAL FILLER POWER                              | S/N        | \$ 280.00              |         |                  |
| 40                          | REAR WINDSCREEN SEALANT                         | S/N        | \$ 200.00              |         |                  |
| 41                          | SUNDRIES                                        |            | \$ 450.00              | \$      | 9.60             |
| <b>TOTAL SPARE PARTS</b>    |                                                 | :          | <b>\$ 23,291.00</b>    | \$      | <b>9,014.40</b>  |
| <b>TOTAL LABOUR CHARGES</b> |                                                 | :          | <b>\$ 20,122.00</b>    | \$      | <b>5,892.00</b>  |
| <b>GRAND TOTAL</b>          |                                                 | :          | <b>\$ 43,413.00</b>    | \$      | <b>14,906.40</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bi-06/08/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :  
SURVEYED DATE :  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF  
THE AFFECTED VEHICLE. SHOULD WE REQUIRE  
FURTHER LABOUR CHARGES AND SPARE PARTS IN THE  
PROGRESS OF REPAIR, WE SHALL INFORM YOU  
ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO  
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR  
APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT