

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21006941/BTF3E2

Date: 17/08/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900077480
Claimant Vehicle No : FBH2224S Insured Vehicle No : SFW6409Z
Date of Loss: 21/06/2021 Nature of Claim: TP Claim No: 6548602543SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBH2224S**
Make & Model: YAMAHA FZ16, 153cc (M) Engine No: 21CD024000
Reg. Date: 15/04/2013 (Man. Year: 2013) Chassis No: ME121C0D2D2023987
Colour: Red Odometer: 36708 km
Engine Capacity: 153 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70/17 Rear Tyre Size: 140/70/17
Front Left Side: Metzeler 6 mm Rear Left Side: Metzeler 6 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,702.38	2,575.00	3,127.38	54.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,220.00	520.00	700.00	57.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,922.38	3,095.00	3,827.38	55.29
Approved Total (Overridden) (S\$)		2,190.00		
(S\$)	6,922.38	2,190.00	4,732.38	68.36
+ GST 7.00/7.00% (S\$)	484.57	153.30	331.27	68.36
Nett Amount (S\$)	7,406.95	2,343.30	5,063.65	68.36

INSPECTION

Date of Assignment: 23/06/2021
Date Inspected: 23/06/2021 Inspected At: Ms Car Auto Pte Ltd (HQ)
8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT
Singapore 415875
Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP	Cut	358.00 FL	*125.00 FL
2	1		*FRONT HEADLAMP STAY	Necessary	85.30 FL	*50.00 FL
3	1		*HEADLAMP COWLING	Broken	325.00 FL	*190.00 FL
4	2		*FRONT SIGNAL LIGHT R/L	Broken	170.00 FL	*76.00 FL
5	1		*FRONT LEFT WING MIRROR	N/S Missing	150.00 FL	*45.00 FL
6	1		*HANDLE BAR	Bent	325.40 FL	*135.00 FL
7	1		*SET FRONT HANDLE GRIP	Cut	105.00 FL	*70.00 FL
8	1		*FRONT FENDER	Cut	175.00 FL	*70.00 FL
9	1		*FORK ASSY	Bent	875.00 FL	*550.00 FL
10	1		*FORK BEARING ASSY	Necessary	79.60 FL	*45.00 FL
11	1		*FORK STEM	Bent	65.00 FL	*65.00 FL
12	1		*FRONT WHEEL SHAFT	Necessary	123.70 FL	*38.00 FL
13	1		*FRONT WHEEL BEARING	Jammed	125.00 FL	*40.00 FL
14	2		*FRONT SIDE OUTER COWLING L+R	Cracked	304.00 FL	*210.00 FL
15	2		*FRONT SIDE INNER COWLING RL	Broken	290.00 FL	*180.00 FL
16	1		*CENTER CONTROL GARNISH RL	O/S Cut	133.60 FL	*85.00 FL
17	1		*GEAR SELECTOR PEDAL	Bent	147.20 FL	*48.00 FL
18	1		*MAIN STAND	Cut	145.00 FL	*43.00 FL
19	2		*REAR SIDE SIGNAL RL	Cut	76.50 FL	*45.00 FL
20	2		*OIL TANK COVER	Not Damaged	256.60 FL	*- FL
21	1		*BELLY PAN	Not Damaged	255.00 FL	*- FL
22	1		*CLUTCH LEVER	Cut	76.70 FL	*35.00 FL
23	1		*BRAKE LEVER	Broken	82.60 FL	*35.00 FL
24	2		*EMBLEM YAMAHA LOGO L+R	Not Necessary	40.00 FL	*- FL
25	2		*REAR SIDE FAIRING RL	Cut	165.00 FL	*70.00 FL
26	1		*IU UNIT ASSY + BRACKET	Not Damaged	180.80 FS	*- FS
27	1		*IU COVER	Not Damaged	40.00 FS	*- FS
28	1		*TAIL BOX	Cut	320.00 FS	*250.00 FS
29	1		*TAIL BOX BRACKET	Not Damaged	115.80 FS	*- FS
30	1		*FORK OIL	Necessary	45.00 FS	*20.00 FS
31	2		*HELMET	Cut	560.00 FS	*280.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,195.80	2,800.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	493.42	225.00
Total Parts (\$\$)	5,702.38	2,575.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WORKMANSHIP	New	600.00	300.00
2	SPRAYPAINTING (BLACK)	New	500.00	200.00
3	ELECTRICAL	New	80.00	0.00
4	BALANCE FRONT WHEEL	New	40.00	20.00
Gross Labour Cost (\$\$)			1,220.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >